



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Page No. 1

Vehicle No. **SKU9893P VOLVO V40**

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
	<b><u>PARTS (LIST ITEMS)</u></b>			
1	Front bumper		960.00	Rp
1	Front bumper retainer RH		40.00	x
1	Front bumper undercover		360.00	x
1	Front innershield RH		190.00	x
1	Front fender RH		730.00	bt ✓
1	Headlamp RH		860.00	x
			3140.00	
		Less 10%	314.00	10%
			2826.00	
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	Rear bumper clips		40.00	x
			2866.00	



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Page No. 2

Vehicle No. SGZ9311Z HONDA STREAM 1.8A

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	<b><u>LABOUR</u></b>		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	800.00 400	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	600.00 400	
3	To remove, refix wiring system at accident damaged areas and check for proper function	120.00 30	
4	To perform anti-rust treatment on affected areas	150.00 20	
	Labour Total :	1670.00	
	TOTAL (PARTS & LABOUR):	4536.00	

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 9749544  
-up  
Resurvey after repair  
03 days  
sure (Wah Hong Motor)