



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Page No. 1

Vehicle No. SKU9893P VOLVO V40

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>			
1	Front bumper		960.00	Rx
1	Front bumper retainer RH		40.00	x } n
1	Front bumper undercover		360.00	x } n
1	Front innershield RH		190.00	x } n
1	Front fender RH		730.00	bt
1	Headlamp RH		860.00	x n
			3140.00	
		Less 10%	314.00	10%
			2826.00	
	<u>SPECIAL NETT ITEMS</u>			
1	Rear bumper clips		40.00	x n
			2866.00	

730

657



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Page No. 2

Vehicle No. SGZ9311Z HONDA STREAM 1.8A

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	800.00 400	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	600.00 400	
3	To remove, refix wiring system at accident damaged areas and check for proper function	120.00 30	
4	To perform anti-rust treatment on affected areas	150.00 20	
	Labour Total :	1670.00 850	
	TOTAL (PARTS & LABOUR):	4536.00	

LIK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanlim 97495744
- up -

Resurvey after repair

03 days

sur@likauto.com

1507

4536.00 #

3 days