

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Mar 2020 Edit Reg		04 Oct 2019 00:00 Edit Adj Rpt	S\$5,900.00 Edit Estimates	S\$5,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R									
Main Claimant: TAN BOON WEI GARY , ID: S8717122A									
Vehicle Reg. No.:	SJY8163K	Date of Loss:	02/10/2019 00:00 - :59 [108 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19100035	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHC8332D	Policy No. (Claimant):	5108631040						
		Excess:							
Repairer:	Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64841626								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 16/10/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (30/06/2020): Alert - Adj Mandate Approved (S\$8353.45) - SJY8163K - Claim Handler: Sherini Pillai - III_SG (30/06/2020): Alert - Adj Mandate Maintained - SJY8163K - Claim Handler: Sherini Pillai - III_SG (20/11/2019): Alert - Adj Mandate Approved (S\$0.00) - SJY8163K - Claim Handler: Sherini Pillai									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJY8163K (MCT19100035)**
[SHC8332D]
TP
TAN BOON WEI GARY
Oct 2 2019 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
Chew Goon Motor

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/03/20 13:33	General View	Load JPG	☒
2	27/03/20 13:33	General View	Load JPG	☒
3	27/03/20 13:33	General View	Load JPG	☒
4	27/03/20 13:33	General View	Load JPG	☒
5	27/03/20 13:33	General View	Load JPG	☒
6	27/03/20 13:33	General View	Load JPG	☒
7	27/03/20 13:33	General View	Load JPG	☒
8	27/03/20 13:33	General View	Load JPG	☒
9	27/03/20 13:33	General View	Load JPG	☒
10	27/03/20 13:33	General View	Load JPG	☒
11	27/03/20 13:33	General View	Load JPG	☒
12	27/03/20 13:33	General View	Load JPG	☒
13	27/03/20 13:33	General View	Load JPG	☒
14	27/03/20 13:33	General View	Load JPG	☒
15	27/03/20 13:33	General View	Load JPG	☒
16	27/03/20 13:33	General View	Load JPG	☒
17	27/03/20 13:33	General View	Load JPG	☒
18	27/03/20 13:33	General View	Load JPG	☒
19	27/03/20 13:33	General View	Load JPG	☒
20	27/03/20 13:33	General View	Load JPG	☒
21	27/03/20 13:33	General View	Load JPG	☒
22	27/03/20 13:33	General View	Load JPG	☒
23	27/03/20 13:33	General View	Load JPG	☒
24	27/03/20 13:33	General View	Load JPG	☒
25	27/03/20 13:33	General View	Load JPG	☒
26	27/03/20 13:33	General View	Load JPG	☒
27	27/03/20 13:33	General View	Load JPG	☒
28	27/03/20 13:33	Odometer Reading	Load JPG	☒
29	27/03/20 13:33	Chassis Number	Load JPG	☒
30	27/03/20 13:34	Reinspection Photo	Load JPG	☒
31	27/03/20 13:34	Reinspection Photo	Load JPG	☒
32	27/03/20 13:34	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/10/19 15:10	EMAIL FROM III DD 07102019	Load PDF	
2	08/10/19 17:13	TP ESTIMATE- MARKED	Load PDF	
3	08/10/19 17:13	TP GIA REPORT	Load PDF	
4	01/04/20 16:49	AMENDED LOD AND TAX INVOICE	Load PDF	
5	12/05/20 13:22	LTA SEARCH	Load PDF	
6	12/05/20 13:22	RENTAL RECEIPT	Load PDF	
7	29/06/20 10:29	TP FINAL EST LIST	Load PDF	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
8	02/09/20 14:06	Authorisation to Act		Load PDF	
9	02/09/20 14:06	DISCHARGE VOUCHER		Load PDF	
10	02/09/20 14:06	LOD		Load PDF	
11	02/09/20 14:06	LTA SEARCH		Load PDF	
12	02/09/20 14:06	RENTAL RECEIPT		Load PDF	
13	02/09/20 14:06	WORKSHOP INVOICE		Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	08/10/19 08:39	Singapore Accident Statement		Load PDF	
2	26/03/20 14:05	Letter of Demand from Third Party TPD LOD FROM CHEW GOON MOTOR (SJY8163K)		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III19017601/KGS3S2**Date:** 02/09/2020REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SJY8163K	Insured Vehicle No :	SHC8332D
Date of Loss:	02/10/2019	Nature of Claim:	TP
		Claim No:	MCT19100035

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY8163K	Engine No:	L15A71002920
Make & Model:	HONDA JAZZ, 1.3 (A)	Chassis No:	JHMGE88509S202398
Reg. Date:	01/10/2010 (Man. Year: 2008)	Odometer:	207986 km
Colour:	Metallic Dark Blue		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	175/65 R14	Rear Tyre Size:	175/65 R14
Front Left Side:	Linglong 7 mm	Rear Left Side:	Linglong 7 mm
Front Right Side:	Linglong 7 mm	Rear Right Side:	Linglong 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,349.50	4,517.37	832.13	15.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,990.00	2,900.00	1,090.00	27.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,339.50	7,417.37	1,922.13	20.58
Approved Total (Overridden) (S\$)		5,900.00		
(S\$)	9,339.50	5,900.00	3,439.50	36.83
+ GST 7.00/7.00% (S\$)	653.77	413.00	240.77	36.83
Nett Amount (S\$)	9,993.27	6,313.00	3,680.27	36.83
+ Car Rental (17.0 x S\$107.00/day) (S\$)		1,819.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,139.45		
Global Sum Settlement (S\$)		8,100.00		

INSPECTION

Date of Assignment:	04/10/2019	Chew Goon Motor (AMK)
Date Inspected:	07/10/2019 Inspected At:	Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint
Estimated Period of Repair:	11.0 days	Singapore 568047

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Sep 2020)
Parts:	144	HONDA JAZZ 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJY8163K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	845.00 FL	*845.00 FL
2	1		*TAILGATE GLASS MOULDING TOP	Necessary	50.00 FL	*50.00 FL
3	1		*TAILGATE GLASS MOULDING LOWER	Necessary	50.00 FL	*50.00 FL
4	1		*TAILGATE BADGE JAZZ	Necessary	28.00 FL	*28.00 FL
5	1		*TAILGATE LOCK	Dented	198.00 FL	*198.00 FL
6	1		*TAILGATE LOCK CATCH	Repair	28.50 FL	*- FL
7	1		*TAILGATE TRIM BOARD	Mtg Cracked	112.00 FL	*112.00 FL
8	10		*TAILGATE TRIM BOARD CLIPS	Necessary	50.00 FL	*50.00 FL
9	1		*TAILGATE STOPPER LH	Missing	13.00 FL	*13.00 FL
10	1		*REAR BUMPER	Bent	485.00 FL	*485.00 FL
11	10		*REAR BUMPER CLIPS	Necessary	38.00 FL	*38.00 FL
12	2		*REAR BUMPER BRACKETS	Not Necessary	36.00 FL	*- FL
13	2		*REAR BUMPER TOP RETAINERS	Not Necessary	36.00 FL	*- FL
14	1		*REAR BUMPER LOWER DIFFUSER COVER	Distorted	300.00 FL	*300.00 FL
15	1		*REAR BUMPER TOW COVER	Missing	18.50 FL	*18.50 FL
16	2		*REAR BUMPER CORNER RETAINERS	Distorted	220.00 FL	*220.00 FL
17	2		*TAILLAMPS	Cracked	766.00 FL	*766.00 FL
18	2		*TAILLAMPS GASKET	Damaged	52.00 FL	*52.00 FL
19	2		*TAILLAMPS LOCK CLIPS	Necessary	30.00 FL	*30.00 FL
20	1		*TAILLAMPS PANEL LH	Repair	146.00 FL	*- FL
21	1		*END PANEL	Bent	303.00 FL	*303.00 FL
22	1		*END PANEL GARNISH	Dented	65.00 FL	*65.00 FL
23	1		*SPARE TYRE PANEL	Bent / Buckled	830.00 FL	*830.00 FL
24	1		*SPARE TYRE TOP BOARD	Deformed	209.00 FL	*209.00 FL
25	1		*REAR STYROFOAM STORAGE BOX	Cracked	290.00 FL	*290.00 FL
26	1		*REAR FENDER INNER TRIM BOARDS	Cracked	510.00 FL	*510.00 FL
27	1		*REAR EXHAUST SILENCER	Repair	533.00 FL	*- FL
28	1		*REAR EXHAUST SILENCER GASKET	Serviceable	28.00 FL	*- FL
29	1		*TAILGATE WEATHERSTRIP (@ \$101.00 DISC 50%)	Distorted / Dented	75.75 FS	*50.50 FS
30	1		*SPARE TYRE PANEL INSULATION	Deformed	146.25 FS	*100.00 FS
31	1		*REAR NUMBER PLATE	Serviceable	45.00 FS	*- FS
32	1		*TAILGATE GLASS SEALANT	Necessary	50.00 FS	*40.00 FS
33	1		*TAILGATE GLASS FASTENER	Necessary	50.00 FS	*30.00 FS
34	1		*REAR BUMPER REVERSE SENSOR	Dented	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,917.00	5,883.00
- List Item Discount on L Items 25.00/25.00% (\$)	1,567.50	1,365.63
Total Parts (\$)	5,349.50	4,517.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CONDUCT FRONT ELECTRICAL CHECK, REVERSE SENSORS, MODULE, ETC.	New	120.00	50.00
2	TO DISMANTLE / TRANSFER TAILGATE FITTING / ANCILLARY ACCESSORIES.	New	150.00	60.00
3	TO DISMANTLE / REFIT TAILGATE GLASS / ANCILLARY ACCESSORIES.	New	160.00	120.00
4	TO DISMANTLE / REFIT TRUNK COMPARTMENT BOARDS & TRIMS.	New	80.00	60.00
5	TO SUPPLY REAR BODY PANEL SEALANT.	New	80.00	60.00
6	TO REPAIR / REPLACE EXHAUST SILENCER.	New	150.00	60.00
7	TO APPLY RUST PROOFING / RESEAL TUFF COATING TREATMENT TO RESPRAY / REPLACED / REPAIR PANEL.	New	150.00	90.00
8	LABOUR CHARGE - PANEL BEATING, REPAIRING OF REAR CHASSIS MEMBER, INNER PANEL, FLOOR PANEL, REAR FENDER ETC. CUT, WELD END PANEL, SPARE TYRE PANEL AND PARTS REPLACEMENT.	New	1,600.00	1,200.00
9	TO RESPRAY AFFECTED AREAS.	New	1,500.00	1,200.00
Gross Labour Cost (\$\$)			3,990.00	2,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >