

ASS. REC. BY:

REF: CS/FCI19017629/Egd3¹²

Special Instruction:

Assigner: Steve

ASSIGNMENT (Office)

From (Person): Joanne Yong of FCI

Date/Time: 2:59pm 7/10/2019

Estimated Cost: Bill to:

OD: TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGD 4S92C

Insured: SHC 3137J

at Workshop m/s Automotive Repair

Tel: 64688834

of 38 Woodlands Ind. Park E1 #05-18

Policy No:

Claim No: D19006380MFAH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 3/10/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS (DS)

H.O.D. Endorsement:

Date/Time: 3:20pm 7/10/2019

Person Contacted: shujuan

Vehicle: I / OUT

Date/Time	Action/Instruction	Estimate (✓)
	SGD 4S92C - CCG/ATG/3016306/Ag2/2y	DOA: 2/9/2013
	SHC 3137J - CS3/FCI19006393/Ecd3e2	DOA: 5/1/2019
08/10/19 @ 2:44pm	revised to Joanne Yong by email.	

Burrage

Steve

REF:

ASSIGNMENT

From: Date: Veh No: **SGD 4592 C**

Estimated Cost: Type: **M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.


Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

22/02/06

Type: **M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**

Truck / Trailer or

Make:

Toyota Vios

c.c

1497

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

235512

T/Radio: Insured / Std / NI / NA

Eng/No:

CtNo:

N1R053 HIY 4204174997

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Locked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/45ZR16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kum ho

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

3/10/19

D.O.I.

7/10/19

Survey held at

Automatic Repair Centre

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

24/10/19

MV - 42K

Finalize (info)

\$1390, 3 days (Paymond) (Red & 2700, 68%)

mv: \$ 42K

LIA: \$ 34,296

Nett value: \$ 7704

RECEIVED 25 OCT 2019

Date/Time, File Pass to?



: Procl. Report

1) 24/10/19



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format:

7P

Lump Sum / I.B.I. (\$

1300

TOTAL

130
50
50
37

267



Auto
Consultants
Pte Ltd

51 UBI AVE I, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19006380MFSH

Date: 08 October 2019

Our Ref: CS/FCI19017629/Eqd3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SGD 4592C .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 07/10/2019 at the premises of M/s AUTOMOTIVE REPAIR CENTRE. and have the following to report:-

Workshop Estimate Amount	: S\$ 4,000.00 .
Revised Estimate Amount	: S\$ 1,990.00 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

Steve
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	04-10-2019	Our Ref No. D19006380MFSH
Accident Date	03-10-2019	Claim Type. Third Party
Insured Vehicle	SHC3137J	Third Party Vehicle. SGD4592C
Survey Location	38 WOODLANDS INDUSTRIAL PARK E1 #05-18	
Contact Person.	LIN SHU JUAN	
Contact No.	64688834/ 0	Fax No. 64622278
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	AUTOMOTIVE REPAIR CENTRE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 8 October 2019 2:24 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Joanne Yong'; SUR
Subject: RE: SURVEY ASSESSMENT - D19006380MFSH/1
Attachments: CSFCI19017629Eqd3.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SGD 4592C.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Monday, 7 October 2019 3:31 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19006380MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 7 October 2019 2:59 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong <Joanneyong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19006380MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.


> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle


Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	221C
Vehicle Details	
Vehicle No.:	SGD4592C
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5E A
Primary Colour:	Black
Manufacturing Year:	2006
Engine No.:	1NZX374218
Chassis No.:	MR053HY4204174097
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$13,040.00
Original Registration Date:	22 Feb 2006
First Registration Date:	22 Feb 2006
Transfer Count:	0
Actual ARF Paid:	\$9,125.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Feb 2026
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$53,799.00
COE Rebate Amount:	\$34,296.00
Total Rebate Amount:	\$34,296.00

The information contained herein is correct as at 07 Oct 2019


OK



W(BUMPER SPOILER)



W(MUD GUARD)



ARC

Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1910-114
DATE : 4-Oct-2019
POLICY NO. : AUTOGEN P10038351R01
VEHICLE REG. NO. : SGD4592C
VEHICLE MAKE : TOYOTA VIOS 1.5 E (AUTO)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey must be on "advice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Estimate

TO Motor Claim Department
First Capital Insurance Limited
36 Robinson Road #16-01 City House
Singapore 068877
Tel: 6507 3848, Fax: 65073849

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper / DD	1	\$ 580.00	\$ 580.00
2	Rear Bumper Clips / MC	10 / set	\$ 5.00	\$ 50.00
3	Rear Bumper Side Retainer RH / RR	1	\$ 40.00	\$ 40.00
4	Rear Bumper Side Retainer LH / RR	1	\$ 40.00	\$ 40.00
5	Rear Bumper Lower Side Retainer RH x NM	1	\$ 40.00	\$ 40.00
6	Rear Bumper Lower Side Retainer LH x NM	1	\$ 40.00	\$ 40.00
7	Rear Bumper Seal Bracket RH x NM	1	\$ 40.00	\$ 40.00
8	Rear Bumper Seal Bracket LH x NM	1	\$ 40.00	\$ 40.00
9	Rear Bumper Side Extension LH x NM	1	\$ 60.00	\$ 60.00
10	Rear Reinforcement Bracket RH x NM	1	\$ 70.00	\$ 70.00
11	Rear Reinforcement Bracket LH x NM	1	\$ 70.00	\$ 70.00
12	Rear Bootlid Lock x NM	1	\$ 100.00	\$ 100.00
13	Rear Bootlid Rubber Seal / TN	1	\$ 200.00	\$ 200.00
14	Rear / End Panel Garnish / CLN	1	\$ 220.00	\$ 220.00
15	End Panel x R	1	\$ 400.00	\$ 400.00
Total Spare Parts				\$ 1,990.00
SPECIAL NETT				
16	Rear Skirting x NM	1	\$ 300.00	\$ 300.00
17	Reverse Sensor / SHY	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 500.00
LABOUR				
18	Spray painting Rear Bumper Include Skirting and Inner Panel	1	\$ 600.00	\$ 600.00
19	Repair and Replace Affected Accident Parts	1	\$ 600.00	\$ 600.00
20	Remove and Replace Rear Exhaust Pipe and Silencer, Re-align	1	\$ 100.00	\$ 100.00
21	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
22	Remove and Replace Rear Reverse Sensor	1	\$ 80.00	\$ 80.00
23	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 1,510.00
Amount Before Excess				\$ 4,000.00
Add GST @ 7%				280.00
Total Amount Payable				\$ 4,280.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.

758.25
P- 775.25
N- 200
L- 680
1638.25
L/S- 1298.60
= 1390



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19017629/Eqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 29-10-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3137J	Veh. Inspected	SGD 4592C	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19006380MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	07/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	MR053HY4204174097	Colour	BLACK	
Odometer	235512	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/45 ZR16	KUMHO	5 mm	
L/H Front Tyre	205/45 ZR16	KUMHO	5 mm	
R/H Rear Tyre	205/45 ZR16	KUMHO	5 mm	
L/H Rear Tyre	205/45 ZR16	KUMHO	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/10/2019	Inspection Date	07/10/2019	
Survey held at	AUTOMOTIVE REPAIR CENTRE PTE LTD 38 WOODLANDS INDUSTRIAL PARK E1 # 05-18 SINGAPORE 757700			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGD 4592C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED	580.00	481.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	30.00
1	REAR BUMPER SIDE RETAINER RH	BROKEN	40.00	40.00
1	REAR BUMPER SIDE RETAINER LH	BROKEN	40.00	40.00
1	REAR BUMPER LOWER SIDE RETAINER RH	NOT NECESSARY	40.00	-
1	REAR BUMPER LOWER SIDE RETAINER LH	NOT NECESSARY	40.00	-
1	REAR BUMPER SEAL BRACKET RH	NOT NECESSARY	40.00	-
1	REAR BUMPER SEAL BRACKET LH	NOT NECESSARY	40.00	-
1	REAR BUMPER SIDE EXTENSION LH	NOT NECESSARY	60.00	-
1	REAR REINFORCEMENT BRACKET RH	NOT NECESSARY	70.00	-
1	REAR REINFORCEMENT BRACKET LH	NOT NECESSARY	70.00	-
1	REAR BOOTLID LOCK	NOT NECESSARY	100.00	-
1	REAR BOOTLID RUBBER SEAL	TORN	200.00	200.00
1	REAR/END PANEL GARNISH	CRUSHED	220.00	220.00
1	END PANEL	TO REPAIR SEE LABOUR	400.00	-
	LESS 25% DISCOUNT		-	-252.75
			1,990.00	758.25
SPECIAL NETT ITEMS				
1	REAR SKIRTING (SN)	NOT NECESSARY	300.00	-
1	REVERSE SENSOR (SN)	SHORTED	200.00	200.00
			500.00	200.00
LABOUR				
	SPRAY PAINTING REAR BUMPER INCLUDE SKIRTING AND INNER PANEL.		600.00	300.00
	REPAIR AND REPLACE AFFECTED ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF END PANEL.		600.00	300.00
	REMOVE AND REPLACE REAR EXHAUST PIPE AND SILENCER,RE-ALIGN.	NOT NECESSARY	100.00	-
	APPLY RUST PROOFING ON REPLACED/REPAIRED PANEL.		100.00	30.00
	REMOVE AND REPLACE REAR REVERSE SENSOR.		80.00	20.00

Report Ref No. CS/FC19017629/Eqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CHECK AND RECTIFY ELECTRICAL WIRING.		30.00	30.00
			1,510.00	680.00
	GRAND TOTAL		4,000.00	1,638.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,300.00

Report Ref No. CS/FCI19017629/Eqd3n2

MARKET VALUE: \$42,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$34,296.00=NETT VALUE: \$7,704.00

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.