

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19017641/T1KA3Q2

Date: 18/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : SKD4476H

Insured Vehicle No : SFG59Z

Date of Loss: 06/10/2019

Nature of Claim: TP

Claim No: 1847494129SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKD4476H**

Make & Model: AUDI A5, 2.0 SPORTBACK (A)

Engine No: CDN228830

Reg. Date: 30/11/2011 (Man. Year: 2011)

Chassis No: WAUZZZ8T4BA108146

Colour: Grey

Odometer: 101073 km

Engine Capacity: 1984 cc

Market Value/New Car

Price: N/A

Sum Insured (\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18

Rear Tyre Size: 245/40 R18

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,468.00	5,412.56	17,055.44	75.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,032.00	5,152.00	6,880.00	57.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	34,500.00	10,564.56	23,935.44	69.38
Approved Total (Overridden) (\$)		10,000.00		
(S\$)	34,500.00	10,000.00	24,500.00	71.01
+ GST 7.00/7.00% (\$)	2,415.00	700.00	1,715.00	71.01
Nett Amount (\$)	36,915.00	10,700.00	26,215.00	71.01
+ Loss of Use (10.0 x S\$100.00/day) (\$)		1,000.00		
+ Doc/Search Fee (\$)		2.00		
Nett Liability (\$)		11,702.00		

INSPECTION

Date of Assignment: 09/10/2019

Date Inspected: 09/10/2019 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 10.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,633.00 FS	*1,306.40 FS
2	1		*FRONT BJMPER FIXING PARTS	Not Necessary	234.00 FS	*- FS
3	1		*FRONT BUMPER SIDE REINFORCEMENT BEAM	Not Necessary	802.00 FS	*- FS
4	1		*FRONT BUMPER BRACKET - RH	Not Necessary	207.00 FS	*- FS
5	1		*FRONT BUMPER SUPPORT - LH/RH	N/s Not Necessary / O/s Bent	52.00 FS	*20.32 FS
6	1		*FRONT BUMPER GUIDE PIECE - LH/RH	N/s Not Necessary/O/s Deformed	80.00 FS	*31.52 FS
7	1		*FRONT BUMPER COVER	Deformed	116.00 FS	*92.40 FS
8	1		*FRONT BUMPER CLOSING ELEMENT - LOWER	Not Necessary	191.00 FS	*- FS
9	1		*FRONT BUMPER FOAM FILLER PIECE	Cut	116.00 FS	*92.40 FS
10	2		*FOAM FILLER PIECE SUPPORT	Not Necessary	18.00 FS	*- FS
11	1		*FRONT BUMPER AIR GUIDE GRILLE - LH/RH	N/s Not Necessary/O/s Missing	246.00 FS	*98.00 FS
12	1		*FRONT BUMPER COVER	Deformed	89.00 FS	*70.88 FS
13	4		*FRONT BUMPER PULL STRAP - LOWER	Not Necessary	187.00 FS	*- FS
14	1		*SIGNAL HORN - RH LOW TONE	Cracked	184.00 FS	*146.80 FS
15	1		*SIGNAL HORN - LH HIGH TONE	Not Necessary	184.00 FS	*- FS
16	1		*SPRING SHACKLE - RH LOW TONE	Bent	23.00 FS	*23.00 FS
17	1		*SPRING SHACKLE - LH HIGH TONE	Not Necessary	23.00 FS	*- FS
18	1		*RADIATOR GRILLE WITH NUMBER PLATE HOLDER	Cracked	713.00 FS	*570.00 FS
19	1		*QUATTRO INSCRIPTION	Necessary	113.00 FS	*113.00 FS
20	1		*CAUTION SIGN STICKER	Necessary	13.00 FS	*9.76 FS
21	1		*AIRCON STICKER	Necessary	18.00 FS	*18.00 FS
22	1		*FRONT FENDER - RH	Repair	980.00 FS	*- FS
23	1		*FRONT FENDER ATTACHMMENT PARTS	Not Necessary	52.00 FS	*- FS
24	2		*FRONT FENDER BRACKET - RH FRONT / REAR	Not Necessary	106.00 FS	*- FS
25	1		*FRONT FENDER BRACE	Bent	110.00 FS	*88.00 FS
26	1		*FRONT WHEEL HOUSING LINER	Not Necessary	169.00 FS	*- FS
27	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	41.00 FS	*- FS
28	1		*BONNET	Not Necessary	1,825.00 FS	*- FS
29	1		*BONNET ATTACMENT PARTS	Not Necessary	152.00 FS	*- FS
30	2		*BONNET LIF HINGE - LH / RH	Not Necessary	152.00 FS	*- FS
31	1		*BONNET ANTI - THEFT GUARD	Not Necessary	16.00 FS	*- FS
32	1		*BONNET CATCH HOOK	Not Necessary	127.00 FS	*- FS
33	1		*BONNET GAS FILLED STRUT - LH	Not Necessary	109.00 FS	*- FS
34	2		*BONNET EDGE ROTECTION - FRONT	Not Necessary	50.00 FS	*- FS
35	1		*BONNET LID LOCK	Not Necessary	196.00 FS	*- FS
36	1		*Nicro SWITCH	Not Necessary	67.00 FS	*- FS
37	1		*BONNET LID LOCK CABLE	Not Necessary	44.00 FS	*- FS
38	1		*BONNET LID LOCK CABLE - REAR	Not Necessary	67.00 FS	*- FS
39	1		*BONNET LOCK COVER	Not Necessary	21.00 FS	*- FS
40	1		*HEADLIGHT MOUNTING - LH/RH	N/s Not Necessary/O/s Cracked	228.00 FS	*90.80 FS
41	1		*HEADLIGHT BRACKET - LH/RH	N/s Not Necessary/O/s Cracked	146.00 FS	*57.92 FS
42	1		*HEADLIGHT - LH/RH	N/s Not Necessary/O/s Cracked	4,340.00 FS	*1,736.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*GAS DISCHARGE LAMP	Not Necessary	398.00 FS	*- FS
44	1		*GAS DISCHARGE LAMP CONTROL UNIT	Not Necessary	1,051.00 FS	*- FS
45	1		*LIFT CYLINDER -LH/RH	N/s Not Necessary/O/s Cracked	502.00 FS	*200.40 FS
46	1		*LIFT CYLINDER SECURING BRACKET - RH	Not Necessary	26.00 FS	*- FS
47	5		*HEADLIGHT HOSE	Missing / Distorted	179.00 FS	*143.20 FS
48	1		*HEADLIGHT T-PIECE	Not Necessary	14.00 FS	*- FS
49	1		*HALOGEN FOG LAMP - LH/RH	N/s Not Necessary/O/s Cracked	470.00 FS	*188.00 FS
50	1		*LOCK CARRIER	Not Necessary	928.00 FS	*- FS
51	1		*LOCK CARRIER BRACE - RH	Not Necessary	41.00 FS	*- FS
52	2		*COOLANT REGULATOR SUPPROT	Not Necessary	69.00 FS	*- FS
53	1		*A/C CONDENSER	Not Necessary	677.00 FS	*- FS
54	1		*CHARGE AIR COOLER	Not Necessary	513.00 FS	*- FS
55	1		*CHARGE AIR COOLER PRESSURE HOSE - RH	Not Necessary	261.00 FS	*- FS
56	1		*COOLANT RADIATOR	Not Necessary	1,246.00 FS	*- FS
57	4		*READY MIX COOLANT	Not Necessary	84.00 FS	*- FS
58	1		*RADIATOR AIR GUIDE - LH/RH	N/s Not Necessary/O/s Deformed	56.00 FS	*21.76 FS
59	1		*RADIATOR SEALING STRIP - UPPER	Not Necessary	21.00 FS	*- FS
60	1		*STRAINER	Not Necessary	21.00 FS	*- FS
61	1		*INTAKE MANIFOLD	Not Necessary	88.00 FS	*- FS
62	1		*BELLOWS	Not Necessary	98.00 FS	*- FS
63	1		*AIR FILTER	Cracked	279.00 FS	*223.20 FS
64	1		*AIR MASS METER	Not Necessary	533.00 FS	*- FS
65	1		*INTAKE MANIFOLD	Not Necessary	133.00 FS	*- FS
66	1		*FRONT NO PLATE	Necessary	40.00 FS	*40.00 FS
67	1		*SUNDRIES	Necessary	500.00 FS	*30.80 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 22,468.00 5,412.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO TOW BACK FROM ACCIDENT SCENE.	New	280.00	0.00
2	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	New	360.00	360.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, RADIATOR AND CHARGED AIR COOLER. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	New	1,200.00	1,200.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	6,400.00	1,750.00
5	TO RESPRAY FRONT BUMPER, BONNET, RHS FRONT FENDER AND HINGES.	New	3,600.00	1,650.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (\$\$)			12,032.00	5,152.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >