Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19017701/KKA3Q2

Date: 14/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800038989-01 Claimant SHD5965S Insured Vehicle No: SJE2080K

Vehicle No:

Date of Loss: TP 02/10/2019 Nature of Claim: Claim No: 1875324297SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SHD5965S Reg No:

Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A) Engine No: 2ZR2B63347

Chassis No: Reg. Date: 01/11/2018 (Man. Year: 2018) JTDKB3FU703075517

Colour: Metallic White/Red Odometer: 88598 km

Engine Capacity: 1798 cc Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15 Front Left Side: Giti 9 mm Rear Left Side: Goodyear 2 mm Front Right Side: Rear Right Side: Giti 9 mm Goodyear 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's 3,247.42	Difference 5,617.38	Diff % 63.37	
Parts	8,864.80				
Miscellaneous Items	0.00	0.00	0.00		
Labour	11,000.00	860.00	10,140.00	92.18	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Gross Total (S\$)	19,864.80	4,107.42	15,757.38	79.32	
+ GST 7.00/7.00% (S\$)	1,390.54	287.52	1,103.02	79.32	
Nett Amount (S\$)	21,255.34	4,394.94	16,860.40	79.32	

Global Sum Settlement (S\$) 0.00

INSPECTION

Date of Assignment: 07/10/2019

Date Inspected: 07/10/2019 Inspected At: Trans-cab Auto Services Pte Ltd (Ang

Mo Kio)

2, Ang Mo Kio Street 63 Singapore 569111

Estimated Period of Repair: 2.0 days

Manager: Khanchna Pothuraj Adjuster: KENNETH KONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 4

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	516.00 FL	*516.00 FL
2	1		*FRONT BUMPER SIDE RETAINER LH	Distorted	82.30 FL	*82.30 FL
3	1		*ABSORBER,FRONT BUMPER,LOWER	Serviceable	132.70 FL	*- FL
4	1		*ABSORBER,FRONT BUMPER ENERGY	Serviceable	79.60 FL	*- FL
5	1		*FRONT LED LAMP (LOWER) LH	Cut	951.40 FL	*951.40 FL
6	1		*FRONT HEADLAMP LH	Cut	2,637.60 FL	*2,637.60 FL
7	1		*COMPUTER SUB-ASSY,HEADLAMP,LH NO 1	Serviceable	960.50 FL	*- FL
8	1		*MOTOR,HEADLAMP LEVELING,LH	Serviceable	487.50 FL	*-FL
9	1		*FRONT FENDER LH	Repair	977.80 FL	*- FL
10	1		*LINER,FRONT FENDER LH	Serviceable	202.50 FL	*-FL
11	1		*FRONT FENDER EMBLEM LH	Necessary	54.60 FL	*54.60 FL
12	1		*GRILLE SUB-ASSY,RADIATOR	Serviceable	346.00 FL	*- FL
13	1		*GRILLE RADIATOR,LOWER NO 1	Serviceable	170.10 FL	*- FL
14	1		*FRONT BONNET	Repair	983.10 FL	*- FL
15	1		*HINGE ASSY,HOOD,LH	Repair	58.90 FL	*- FL
16	1		*FRONT WHEEL RIM	Serviceable	1,570.55 FS	*-FS
17	1		*FRONT WHEEL RIM COVER	Serviceable	175.80 FS	*- FS
18	1		*FRONT TYRE 195/65/15	Serviceable	350.00 FS	*- FS
19	1		*CLIP,FRONT FENDER LINER	Not Necessary	22.00 FS	*-FS
20	1		*FRONT NUMBER PLATE WITH MOULDING	Serviceable	200.00 FS	*- FS
21	1		*BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
F=Fra	nchise	part. S=Spc	Nett. L=ListItemDisc.			
				Sub Total (S\$)	11,024.95	4,307.90
			- List Item Discount on L Items 2	25.00/25.00% (S\$)	2,160.15	1,060.48
				Total Parts (S\$)	8,864.80	3,247.42
			Report was unsubmitted during this	print-out.		
				•		

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Repairer's	Lab.Type	Particulars	O
		our Items	_abo
4,500.00	New	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1
4,500.00	New	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	2
380.00	New	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	3
170.00	New	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	1
170.00	New	TO TRANSFER OF FRONT BUMPER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	5
170.00	New	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	3
380.00	New	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	7
220.00	New	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	3
170.00	New	TO RUST-PROOFING OF THE AFFECTED AREAS	9
170.00	New	TO CHECK ELECTRICAL LIGHTING CONCERNED	10
170.00	New	TO TRANSFER OF FRONT BONNET FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	11
11,000.00	Cost (S\$)	Gross Labour Cost (S\$)	
	4,500.00 4,500.00 380.00 170.00 170.00 380.00 220.00 170.00 170.00 170.00	New 4,500.00 New 4,500.00 New 380.00 New 170.00 New 170.00 New 380.00 New 220.00 New 170.00 New 170.00 New 170.00 New 170.00 New 170.00	PUTTY AND SPRAY PAINTING OF THE AFFECTED New 4,500.00 PORTION PANEL BEATING,KNOCKING AND STRAIGHTENING THE New 4,500.00 NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME TO REMOVE AND REFIT INTERIOR New 380.00 FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS New 170.00 AND PERFORM WATER SEEPAGE TEST TO TRANSFER OF FRONT BUMPER New 170.00 FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING New 170.00 LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE New 380.00 ON JIG BENCH,TO FACILITATE REPAIR TO CHECK STEERING GEOMETRY AND COMPUTER New 220.00 WHEEL ALIGNMENT TO RUST-PROOFING OF THE AFFECTED AREAS New 170.00 TO CHECK ELECTRICAL LIGHTING CONCERNED New 170.00 FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST

Report was unsubmitted during this print-out.

< END OF ESTIMATES >