

S.D CAR CARE CENTRE

Blk 2, Kaki Bukit Avenue 2, #01-29, (Kaki Bukit AutoHub), Singapore 417921

H/P: 9616 1359 (Ah Boon) / 9650 7403 (Ah Boy)

Tel: 6749 6155 / 6745 5102 / Fax: 6742 9003

TP111
Cecilia.

Vehicle number: GK811K

Vehicle Made & Model: TOYOTA DYNA

<u>Qty</u>	<u>List Items</u>	<u>Amount \$</u>
1	Front bumper <i>Distorted</i>	521.60 ✓
1	Front corner panel - RH <i>Distorted</i>	321.60 ✓
1	Front corner moulding - RH <i>3 new</i>	199.62 ✗
1	Front corner garnish - RH	287.43 ✗
1	Front cab panel <i>3 new</i>	1,265.60 ✗
1	Front cab panel logo	89.95 ✗
1	Front cab panel emblem "DYNA" <i>new</i>	86.90 ✗
1	Front door - RH <i>Distorted</i>	1,658.60 ✓
1	Front door side mirror <i>lt</i>	281.90 ✓
1	Front door outer handle <i>new</i>	161.20 ✗
1	Front door glass outer moulding <i>new</i>	141.60 ✗
1	Front door glass run channel <i>3 new</i>	155.90 ✗
1	Front door glass guide <i>new</i>	110.65 ✗
1	Front door glass regulator <i>Damaged</i>	281.60 ✓
1	Front door glass regulator motor <i>Not new</i>	481.90 ✗
1	Front door inner lock <i>Jammed</i>	581.65 ✓
1	Front door inner trim board <i>cracked</i>	761.90 ✓
1	Front door insulation <i>new</i>	130.20 ✗
1	Front door w/strip <i>lt</i>	141.60 ✓
1	Front door seal <i>new</i>	112.30 ✓
1	Front door checker <i>Damaged</i>	89.95 ✓
2	Front door hinges @ 115 <i>Best</i>	230.00 ✓
1	Front door pillar - RH - Outer <i>Distorted</i>	711.52 ✓
1	Front door pillar - RH - Inner <i>Repis</i>	695.50 ✗
1	Front door rear pillar <i>Repis</i>	581.90 ✗
1	Front headlamp assy <i>cracked</i>	704.35 ✓
1	Front grille <i>cracked</i>	487.31 ✓
1	Front wheel guard - RH <i>new</i>	286.90 ✗
1	Front wheel arch panel - RH <i>Buckled</i>	441.59 ✓
1	Front wheel arch panel moulding <i>lt</i>	121.30 ✓
1	Front wheel arch panel garnish <i>Deformed</i>	186.90 ✓

Vehicle number: GK811K

Vehicle Made & Model: TOYOTA DYNA

1	Front windscreen rubber <i>Not New</i>	287.92 X
1	Front step garnish - RH <i>Distorted</i>	312.60 ✓
1	Front shock absorber - RH <i>Bent</i>	221.30 ✓
1	Front steering rack link assy <i>Not New</i>	1,126.50 X
1	Front steering box universal joint <i>Bent</i>	481.30 ✓
1	Front axle beam <i>Not New</i>	2,885.90 X
1	Front knuckle arm <i>Bent</i>	861.90 ✓
1	Front wheel hub bearing <i>Damaged</i>	551.60 ✓
1	Brake air chamber - RH <i>Not New</i>	281.30 X
		<i>10073.37</i>
		<i>7555.02</i>
Sub-total		19,321.24
Less 25%		4,830.31
Total List		14,490.93

Special Nett Items

1	Front wheel rim <i>Not New</i>	280.00 250
1	Front tyre <i>Not New</i>	260.00 X
1	R.O.V sticker <i>New</i>	45.00 30
Total Special Nett		585.00

Labour charges

To check front electrical wiring	120.00 30
Towing charges	150.00 60
To respray undercoating	150.00 80
To remove, refix front interior trims to assist repair	120.00 80
To remove, refix front undercarriage	450.00 280
To remove, refix front windscreen	150.00 X
To remove, refix front dashboard	350.00 220
To check wheel alignment	120.00 80
To respray painting and etc	1,500.00 1000
Panel beating, cut, weld remove & replacing above parts	2,000.00 1400
Total Labour	5,110.00

- UKK Auto Consultants hence notify the Repairer of the following:*
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

20,185.93

Acknowledged by Repairer
Signature:
Date:

Total: 11065.02
L/S: 8.81c 12 Days