



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

QBE INSURANCE (SINGAPORE) PTE LTD

1 RAFFLES QUAY #29-10 SOUTH TOWER
SINGAPORE 048583

INV No. AC2108966

INV Date 30/12/2021

Reference CC4/QBE19017725/Kra3q2

Code QBE

PROFESSIONAL SERVICE FEE

Vehicle No. SJS 9789E

Insured Veh. SLA 509C

Claim No. VC012997

Policy No.

Accident Date 12/09/2019

Inspection Date 07/10/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD 1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583			Ref: CC4/QBE19017725/Kra3q2	
			Date: 30/12/2021	
			Code: QBE	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLA 509C	Veh. Inspected	SJS 9789E	
Policy No.		Coverage (\$)	0.00	
Claim No.	VC012997	Excess (\$)	0.00	
Assign From	JENNY	Assign Date	07/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FIT (A)	c.c	1339	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	GE61083356	Colour	METALLIC SILVER	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/50 R15	MICHELIN	8 mm	
L/H Front Tyre	195/50 R15	MICHELIN	8 mm	
R/H Rear Tyre	195/50 R15	MICHELIN	8 mm	
L/H Rear Tyre	195/50 R15	MICHELIN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/09/2019	Inspection Date	07/10/2019	
Survey held at	POON POONG MOTORS PTE LTD BLK 176 SIN MING DRIVE #05-14/15 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 9789E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BENT	680.00	493.70
1	EXHAUST (BEFORE CAT)	TO REPAIR SEE LABOUR	950.00	-
1	REAR BUMPER	REPEATED	550.00	-
1	RL BUMPER RETAINER	DISTORTED	150.00	150.00
1	RL BUMPER REFLECTOR	SERVICEABLE	110.00	-
1	REAR BOOT	BENT	1,180.00	845.20
1	END PANEL	BENT	365.00	296.00
1	RL FENDER INNER HOUSING	TO REPAIR SEE LABOUR	580.00	-
2	REVERSE SENSOR	DENTED	95.00	95.00
10	CLIP @\$2.00	NECESSARY	20.00	20.00
1	HONDA LOGO	NOT NECESSARY	35.00	-
1	FIT LOGO	NECESSARY	25.00	25.00
1	RR BUMPER RETAINER	DISTORTED	150.00	150.00
1	END PANEL TOP GARNISH	MTG DISTORTED	190.00	166.50
1	RL WHEEL HOUSING GARNISH	SERVICEABLE	350.00	-
1	BOOT DOOR INNER GARNISH	SERVICEABLE	210.00	-
1	BOOT LOCK	DENTED	150.00	150.00
1	SPARE TYRE TRUNK	TO REPAIR SEE LABOUR	450.00	-
1	TAIL LIGHT LEFT	CRACKED	350.00	286.20
1	TAIL LIGHT RIGHT	CRACKED	350.00	286.20
1	REAR FENDER LEFT	TO REPAIR SEE LABOUR	400.00	-
1	REAR FENDER RIGHT	TO REPAIR SEE LABOUR	400.00	-
	LESS 20% DISCOUNT		-	-592.76
			7,740.00	2,371.04

Report Ref No. CC4/QBE19017725/Kra3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>LABOUR</u>			
	TO REMOVE, REFIT DAMAGE PARTS AND WELDING. INCLUSIVE OF THE REPAIR OF EXHAUST (BEFORE CAT), RL FENDER INNER HOUSING, SPARE TYRE TRUNK, REAR FENDER LEFT AND REAR FENDER RIGHT.		1,800.00	800.00
	TO REMOVE AND REFIT BOOT WINDSCREEN.		180.00	120.00
	PAINTWORK.		1,000.00	800.00
			2,980.00	1,720.00
	GRAND TOTAL		10,720.00	4,091.04
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,250.00

Report Ref No. CC4/QBE19017725/Kra3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJS 9789E

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJS 9789E

RE-INSPECTION

