

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No. 08102600I

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

*Not Withheld
11 Sep 87
Purvey After Paint*

3 days

REPAIR ESTIMATE FOR SKW5336Y

No.	Qty	List Items	Price	Notes
1	1	Front bumper	cm \$/Bu 447.25	✓
2	1	Front bumper "TOYOTA" logo	\$ na 47.67	✓
3	2	Front bumper fog lamp cover	\$ su 130.00	X
4	1	Front bumper air grille	\$ Di 138.50	✓
5	1	Front bumper inner top garnish	\$ na 169.70	✓
6	2	Front bumper side retainer	ol sd \$ 107.80	✓
7	1	Front bumper inner reinforcement	\$ m 361.00	✓
8	1 set	Front bumper clips	\$ na 30.00	✓
9	1	Front grille	\$ cm 220.70	✓
10	1	Front bonnet	\$ r 488.20	X
11	2	Headlamp	mg \$ cm 767.00	✓
12	1	Front support panel	\$ r 883.40	X
			\$ 3,791.22	
Less 25%			\$ 947.81	
Total :			\$ 2,843.42	

Special Nett Items

13	1	Front number plate	\$ m 50.00	45m
----	---	--------------------	------------	-----

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.		\$ 900.00	4001
2	To putty and spray Spray Paintings charges.		\$ 1,000.00	3601
3	To remove, refix A/c condenser, radaitor and etc, including refill of A/c gas.		\$ na 140.00	X
4	To check wirings and lightings.		\$ 40.00	201
5	To supply and apply anti rust treatment		\$ na 80.00	X
Total :			\$ 2,160.00	

Total Parts and Labour : \$ 5,053.42

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by: _____
Signature: _____
Date: _____