

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19017767/DGA3Q2

Date: 10/09/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SHD3462P	Insured Vehicle No :	SHD6762D
Date of Loss: 06/10/2019	Nature of Claim: TP	Claim No: MCT19100111

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD3462P		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDGU668603
Reg. Date:	18/08/2016 (Man. Year: 2016)	Chassis No:	KMHLB41UMGU093323
Colour:	Blue	Odometer:	448000 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,471.20	13,697.52	12,773.68	48.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,640.00	2,870.00	4,770.00	62.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	34,111.20	16,567.52	17,543.68	51.43
Approved Total (Overridden) (S\$)		12,572.50		
Nett Amount (S\$)	34,111.20	12,572.50	21,538.70	63.14
+ Loss of Use (11.0 x S\$40.00/day) (S\$)		440.00		
+ Car Rental (11.0 x S\$112.67/day) (S\$)		1,239.37		
Nett Liability (S\$)		14,251.87		
Global Sum Settlement (S\$)		14,000.00		

INSPECTION

Date of Assignment:	08/10/2019	
Date Inspected:	08/10/2019 Inspected At:	Chunni Motor Work Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint Singapore 568047
Estimated Period of Repair:	10.0 days	

Adjuster: BRYAN TANI**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jan 2020)
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD3462P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER (LH)	Dented	566.30 FL	*566.30 FL
2	1		*FRONT FENDER SHIELD (LH)	Not Necessary	174.90 FL	*- FL
3	1		*FRONT DOOR (LH)	Buckled	2,256.40 FL	*2,256.40 FL
4	1		*FRONT DOOR RUBBER	Deformed	290.50 FL	*290.50 FL
5	1		*FRONT DOOR GEAR / REGULATOR (LH)	Mounting Cracked	250.60 FL	*250.60 FL
6	1		*FRONT DOOR HINGE UPPER (LH)	Not Necessary	36.10 FL	*- FL
7	1		*FRONT DOOR HINGE LOWER (LH)	Not Necessary	36.10 FL	*- FL
8	1		*FRONT DOOR CHECK (LH)	Not Necessary	39.20 FL	*- FL
9	1		*FRONT DOOR INNER LOCK (LH)	Not Necessary	290.80 FL	*- FL
10	1		*FRONT DOOR OUTER MOULDING (LH)	Not Necessary	47.10 FL	*- FL
11	1		*FRONT DOOR POWER MOTOR, LH	Not Necessary	172.70 FL	*- FL
12	1		*FRONT DOOR TRIM BOARD (LH)	Mounting Cracked	973.50 FL	*973.50 FL
13	1		*ROCKER PANEL OUTER GARNISH	Cut	341.40 FL	*341.40 FL
14	1		*FRONT WINDSCREEN MOULDING	Not Necessary	113.30 FL	*- FL
15	1		*FRONT WINDSCREEN PILLAR OUTER (LH)	Not Necessary	1,745.50 FL	*- FL
16	1		*FRONT WHEEL RIM (LH)	Not Necessary	325.30 FL	*- FL
17	1		*FRONT WHEEL HUB CAP (LH)	Cut	107.10 FL	*107.10 FL
18	1		*FRONT WHEEL BEARING	Damaged	540.50 FL	*540.50 FL
19	1		*FRONT SHOCK ABSORBER (ASSY) (LH)	Distorted	342.20 FL	*342.20 FL
20	1		*FRONT SHOCK ABSORBER MOUNTING (LH)	Not Necessary	108.80 FL	*- FL
21	1		*FRONT DRIVE SHAFT (LH)	Not Necessary	1,030.80 FL	*- FL
22	1		*RACK & PINION ASSY	Not Necessary	969.60 FL	*- FL
23	1		*STG TIE END	Distorted	62.60 FL	*62.60 FL
24	1		*FRONT SUSPENSION LOWER ARM (LH)	Distorted	529.30 FL	*529.30 FL
25	1		*KNUCKLE ARM (LH)	Distorted	552.00 FL	*552.00 FL
26	1		*ENGINE CROSSMEMBER	Not Necessary	2,094.40 FL	*- FL
27	1		*ABS SENSOR, LH	Not Necessary	234.00 FL	*- FL
28	1		*ELECTRIC POWER STEERING	Not Necessary	3,641.00 FL	*- FL
29	1		*REAR BUMPER	Cut	553.00 FL	*553.00 FL
30	1		*REAR BUMPER CLIP 10 PCS	Necessary	22.00 FL	*22.00 FL
31	1		*REAR BUMPER BRACKET, LH	Not Necessary	35.60 FL	*- FL
32	1		*REAR FENDER (LH)	Dented	4,736.80 FL	*2,020.00 FL
33	1		*REAR FENDER INNER LINING (LH)	Not Necessary	169.30 FL	*- FL
34	1		*REAR WINDSCREEN MOULDING	Necessary	28.30 FL	*28.30 FL
35	1		*REAR DOOR (LH)	Dented	2,201.10 FL	*2,201.10 FL
36	1		*DOOR CENTRE PILLAR OUTER (LH)	Dented	2,527.80 FL	*2,527.80 FL
37	1		*REAR TYRE RIM (LH)	Distorted	325.30 FL	*325.30 FL
38	1		*REAR WHEEL HUP-CAP (LH)	Cut	107.10 FL	*107.10 FL
39	1		*REAR WHEELBEARING ING & HUB	Damaged	362.00 FL	*362.00 FL
40	1		*REAR TRAILING ARM (LH)	Distorted	192.00 FL	*192.00 FL
41	1		*REAR ASSIST (LH)	Distorted	145.70 FL	*145.70 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*REAR SHOCK ABSORBER (LH)	Distorted	276.30 FL	*276.30 FL
43	1		*REAR SHOCK ABSORBER MOUNTING (LH)	Not Necessary	81.30 FL	*- FL
44	1		*REAR CROSSMEMBER	Not Necessary	1,021.50 FL	*- FL
45	1		*STABILIZER BAR	Not Necessary	199.60 FL	*- FL
46	1		*STABILIZER LINK	Not Necessary	85.90 FL	*- FL
47	1		*REAR UPPER ARM (LH)	Distorted	335.75 FL	*335.75 FL
48	1		*REAR LOWER ARM (LH)	Distorted	353.80 FL	*353.80 FL
49	1		*REAR KNUCKLE ARM (LH)	Distorted	545.60 FL	*545.60 FL
50	1		*FRONT DOOR COMFORT LOGO (LH)	Necessary	75.00 FS	*75.00 FS
51	1		*FRONT WINDSCREEN SEALANT	Not Necessary	46.00 FS	*- FS
52	1		*FRONT TYRE (LH)	Not Necessary	216.00 FS	*- FS
53	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
54	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
55	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (LH)	Necessary	80.00 FS	*80.00 FS
56	1		*REAR TYRE (LH)	Not Necessary	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 32,906.75 17,059.15
- List Item Discount on L Items 20.00/20.00% (\$\$) 6,435.55 3,361.63

Total Parts (\$\$) 26,471.20 13,697.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING.	New	2,400.00	1,000.00
2	SPRAY PAINTING CHARGE.	New	1,800.00	1,000.00
3	WIRING CHARGE.	New	100.00	0.00
4	TUFF KOTE.	New	150.00	40.00
5	TOWING CHARGE.	New	50.00	0.00
6	REMOVE / REFIX CUSHION & UPHOLSTERY REAR.	New	150.00	80.00
7	REMOVE / REFIX REAR WINDSCREEN GLASS.	New	120.00	80.00
8	REMOVE / REFIX REVERSE SENSOR.	New	120.00	40.00
9	REMOVE / REFIX UNDERCARRIAGE (FRT).	New	200.00	150.00
10	REMOVE / REFIX FUEL TANK.	New	150.00	0.00
11	TRANSFER OF DOOR.	New	240.00	120.00
12	REMOVE / REFIX UNDERCARRIAGE (RR).	New	200.00	150.00
13	FOUR WHEEL ALIGNMENT.	New	120.00	60.00
14	REMOVE / REFIX DASHBOARD.	New	350.00	0.00
15	REMOVE / REFIX FRONT WINDSCREEN GLASS.	New	120.00	0.00
16	REMOVE / REFIX CUSHION & UPHOLSTERY FRONT.	New	90.00	0.00
17	RE-SET FRT & REAR ABS SYSTEM.}	New	400.00	150.00
18	RE-SET FRT & REAR POWER WINDOW SYSTEM.}	New	400.00	0.00
19	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.}	New	480.00	0.00
Gross Labour Cost (\$\$)			7,640.00	2,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >