

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19017770/T1GA3N2

Date: 20/05/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SHA8112H	Insured Vehicle No :	SHC8495S
Date of Loss: 07/10/2019	Nature of Claim: TP	Claim No: MCT19100341

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA8112H		
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Engine No:	G4LEKU298749
Reg. Date:	06/08/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVKU165026
Colour:	Yellow	Odometer:	31697 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	895.80	240.70	655.10	73.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,180.00	800.00	380.00	32.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,075.80	1,040.70	1,035.10	49.87
+ GST 7.00/7.00% (\$\$)	145.31	72.85	72.46	49.87
Nett Amount (\$\$)	2,221.11	1,113.55	1,107.56	49.87
+ Loss of Use (2.0 x S\$40.00/day) (\$\$)		80.00		
+ Car Rental (2.0 x S\$117.00/day) (\$\$)		234.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		1,435.00		
Global Sum Settlement (\$\$)		1,400.00		

INSPECTION

Date of Assignment:	08/10/2019		
Date Inspected:	09/10/2019	Inspected At:	Ding Automotive Pte Ltd (HQ)
			31 CORPORATION ROAD
			Singapore 649825
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Apr 2020)	
Parts:	N/A	HYUNDAI AE IONIQ HEV DCT 1.6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA8112H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	659.40 FL	* - FL
2	1		*REAR BUMPER RETAINER RH	Not Necessary	78.22 FL	* - FL
3	1		*REAR WHEEL CAP RH	Cut	275.88 FL	*275.88 FL
4	1		*SET REAR BUMPER CLIP	Not Necessary	35.00 FS	* - FS
5	1		*REPAIR REAR FENDER RH (NPA)	Repair	0.00 FS	* - FS
6	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,098.50	295.88
- List Item Discount on L Items 20.00/20.00% (\$\$)	202.70	55.18
Total Parts (\$\$)	895.80	240.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	New	600.00	400.00
2	RUST PROOFING	New	80.00	0.00
3	RESPRAY REAR BUMPER	New	250.00	200.00
4	RESPRAY REAR FENDER RH	New	250.00	200.00
Gross Labour Cost (\$\$)			1,180.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >