



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19017800/Apa3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN:KITTY

Date : 29-04-2020



Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |           |                |            |
|--------------|-----------|----------------|------------|
| Insured Veh. | SJG 4821R | Veh. Inspected | XB 6424B   |
| Policy No.   | GA370405  | Coverage (\$)  | 0.00       |
| Claim No.    | S9M022DF  | Excess (\$)    | 0.00       |
| Assign From  |           | Assign Date    | 09/10/2019 |

### 2. Vehicle Particulars & Condition

|              |                   |              |          |
|--------------|-------------------|--------------|----------|
| Make & Model | VOLVO FL10 6X4    | c.c          | 9603     |
| Engine No.   | HIDDEN            | Year of Reg. | 1999     |
| Chassis No.  | YV2F4B9D5XA289788 | Colour       | WHITE    |
| Odometer     | 384286            | Steering     | IN ORDER |
| Brakes       | IN ORDER          | Modification | NIL      |
| General      | GOOD              |              |          |

### 3. Conditions of Tyres

|                | Size         | Make   | Balance |
|----------------|--------------|--------|---------|
| R/H Front Tyre | 315/80 R22.5 | TR 918 | 6 mm    |
| L/H Front Tyre | 315/80 R22.5 | TR 918 | 6 mm    |
| R/H Rear Tyre  | 315/80 R22.5 | TR 918 | 6 mm    |
| L/H Rear Tyre  | 315/80 R22.5 | TR 918 | 6 mm    |

### 4. Description of Damages

|                                                                                 |
|---------------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.<br>DAMAGES SEE DETAILS. |
|---------------------------------------------------------------------------------|

### 5. General Information

|                |                                                                                                      |                 |            |
|----------------|------------------------------------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 01/10/2019                                                                                           | Inspection Date | 18/10/2019 |
| Survey held at | NEW HOCK TECK MOTOR PTE LTD<br>1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT<br>SINGAPORE 417883 |                 |            |

### 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

### 5b. Estimate Days of Repair

|                                     |                       |
|-------------------------------------|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | <b>2 Working Days</b> |
|-------------------------------------|-----------------------|