

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG19017804/ATF3E2

Date: 24/08/2020

REFERENCE

| | | | | |
|-------------------|--------------|------------------|------------|------------------------|
| Insured/Claimant: | TAN KEAN HUI | Policy No: | 1900161230 | |
| Date of Loss: | 08/10/2019 | Nature of Claim: | OD | Claim No: 4081852131SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SGX580H | Engine No: | CZC774164 |
| Make & Model: | AUDI A3, 1.4 TFSI (A) | Chassis No: | WAUZZZ8V7J1054082 |
| Reg. Date: | 10/05/2018 (Man. Year: 2018) | Odometer: | 8836 km |
| Colour: | Grey | | |
| Engine Capacity: | 1395 cc | | |
| Market Value/New Car Price: | S\$137,000.00 | | |
| Sum Insured (\$\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 205/55 R16 | Rear Tyre Size: | 205/55 R16 |
| Front Left Side: | Michelin 6 mm | Rear Left Side: | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------------------|------------------|------------------|-----------------|--------------|
| Parts | 7,601.00 | 4,558.80 | 3,042.20 | 40.02 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 14,452.00 | 10,452.00 | 4,000.00 | 27.68 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (\$\$) | 22,053.00 | 15,010.80 | 7,042.20 | 31.93 |
| - Excess (\$\$) | 600.00 | 600.00 | 0.00 | 0.00 |
| (\$\$) | 21,453.00 | 14,410.80 | 7,042.20 | 32.83 |
| + GST 7.00/7.00% (\$\$) | 1,501.71 | 1,008.76 | 492.95 | 32.83 |
| Nett Amount (\$\$) | 22,954.71 | 15,419.56 | 7,535.15 | 32.83 |

INSPECTION

| | | |
|-----------------------------|------------|-----------------------------------|
| Date of Assignment: | 10/10/2019 | |
| Date Inspected: | 09/10/2019 | Inspected At: |
| | | Premium Automobiles Pte Ltd (UBI) |
| | | 55 Ubi Road 1 |
| | | Singapore 408699 |
| Estimated Period of Repair: | 16.0 days | |

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|---------------|-------------|--------------|
| 1 | 1 | | *REAR FENDER - RH | Distorted | 2,110.00 FS | *1,688.00 FS |
| 2 | 1 | | *NOISE INSULATION PLATE - RH | Not Necessary | 64.00 FS | *- FS |
| 3 | 1 | | *REAR BUMPER | Torn | 1,793.00 FS | *1,434.40 FS |
| 4 | 4 | | *REAR BUMPER STICKY PAD | Not Necessary | 21.00 FS | *- FS |
| 5 | 1 | | *REAR BUMPER FIXING PARTS | Not Necessary | 175.00 FS | *- FS |
| 6 | 1 | | *REAR BUMPER WHEEL HOUSING LINER ADAPTER - RH | Not Necessary | 34.00 FS | *- FS |
| 7 | 1 | | *REAR BUMPER GUIDE SECTION - RH | Damaged | 15.00 FS | *11.44 FS |
| 8 | 1 | | *REAR BUMPER LOCKING MECHANISM | Necessary | 27.00 FS | *21.20 FS |
| 9 | 1 | | *REAR BUMPER SPOILER - LH | Not Necessary | 216.00 FS | *- FS |
| 10 | 1 | | *REAR LIGHT REFLECTOR - RH | Not Necessary | 38.00 FS | *- FS |
| 11 | 1 | | *LED TAIL LIGHT - RH | Not Necessary | 800.00 FS | *- FS |
| 12 | 1 | | *TAIL LIGHT TRIM - RH | Not Necessary | 27.00 FS | *- FS |
| 13 | 1 | | *REAR WHEEL HOUSING LINER - RH | Not Necessary | 223.00 FS | *- FS |
| 14 | 1 | | *WHEEL HOUSING LINER ATTACHMENT PARTS | Necessary | 52.00 FS | *41.60 FS |
| 15 | 1 | | *REAR BUMPER GUIDE SECTION - RH | Damaged | 60.00 FS | *47.84 FS |
| 16 | 1 | | *REAR ALUMINIUM RIM - RH | Cut | 666.00 FS | *532.40 FS |
| 17 | 1 | | *ACRYLIC SEALANT | Necessary | 180.00 FS | *180.00 FS |
| 18 | 1 | | *CAVITY WAX | Necessary | 140.00 FS | *140.00 FS |
| 19 | 1 | | *STONE CHIP | Necessary | 180.00 FS | *180.00 FS |
| 20 | 1 | | *METAL FILLER POWDER | Necessary | 280.00 FS | *280.00 FS |
| 21 | 1 | | *SUNDRIES | Necessary | 500.00 FS | *1.92 FS |

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **7,601.00** **4,558.80**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|---|----------|------------------|------------------|
| <u>Labour Items</u> | | | | |
| 1 | TO REMOVE AND REINSTALL REAR WIRE HARNESS, RELAY, FUSE BOXES, AUDIO EQUIPMENT, RHS REAR WINDOW AND LIFTING MECHANISM. RHS TRIMS, LUGGAGE COMPARTMENT TRIMS | New | 1,600.00 | 1,600.00 |
| 2 | TO REMOVE AND REINSTALL REAR PARKING AID | New | 280.00 | 280.00 |
| 3 | TO REMOVE AND REINSTALL CONVERTIBLE TOP, COMPLETE WITH FRAME, HYDRAULIC SYSTEM ASSY, STORAGE BOX ETC | New | 1,800.00 | 1,800.00 |
| 4 | TO DISMANTLE REAR BUMPER, REAR LID ASSY AND FIXTURES. CUT OUT AND REWELD RHS 1/4 PANEL, SILL PANEL, INNER B PILLAR. TO RENEW REAR BUMPER. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED | New | 6,300.00 | 3,500.00 |
| 5 | TO RESPRAY RHS REAR FENDER, RHS SILL PANEL, DOOR ENTRANCE AND REAR BUMPER. TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT | New | 4,000.00 | 2,800.00 |
| 6 | TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT | New | 280.00 | 280.00 |
| 7 | TO CARRY OUT DIAGNOSTIC CHECKS | New | 192.00 | 192.00 |
| Gross Labour Cost (S\$) | | | 14,452.00 | 10,452.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >