

ASS. REC. BY:

REF:

III

ASSIGNMENT

From:

Date:

17.10.2019

Veh No:

SFB 100M

Yr Regn:

CUE 2027 Meng
2017, JuneType: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspection Vehicle No: SFB 100M

at Workshop m/s: MOVA Automotiva

of BLK 100 Bukit Merah Lane 3 #01-04

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

After 11.00 a.m

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

A\$80K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Truck / Trailer or

Make:

Mercedes Benz S350 c.c

3748

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

113880

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD2211562A139252

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/60R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

17/10/1935g

Survey held at

Mong BM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or +

n/s Rear, u/c

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Week-end (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Rep. Form:

Lump Sum / L.B.I. (\$