

Atty - LKK - 14/10/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SME 5401 M

Not Authorized
Resurvey By paint

Parts	(a) Cost / List Price Items	\$	5,985.81	\$ 765.19
	Plus/Less 25%	\$	1,496.45	\$ 191.30
	Total of Cost / List	\$	4,489.36	\$ 573.89
	(b) Nett Price Items			
	Less			
	Total of Nett Item			
	(c) Special Nett Items	\$	350.00	-
Total Parts Cost		\$	4,839.36	\$ 573.89
Labour		\$	3,420.00	\$ 1,780.00
Total		\$	8,259.36	P/P \$2,353.89

The above total will be subjected to 7% G.S.T.

Name of Surveyor

:

Kenneth

Company

:

CICe

Survey conducted on

:

14/10/19

at

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor

:

Le

Date:

14/10/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SME 5401 M**
Make & Model : **TOYOTA PRIUS ALPHA**
Chassis No : **ZVW400030005**

Submit By : **JENNY**
Year Manufacture : **2018**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front bumper	1	\$496.50		✓
2	Front bumper clip	10	\$38.90		✓
3	Front bumper side retainer LH	1	\$78.60		X
4	Front bumper side retainer RH	1	\$78.60		7X
5	Front bumper bracket LH	1	\$208.71		X
6	Front bumper bracket RH	1	\$208.71		X
7	LH front fender	1	\$767.90		X
8	LH front fender undershield	1	\$165.90		X
9	LH front fender undershield clip	10	\$21.10		X
10	LHF fender wording "HYBRID"	1	\$44.17		✓
11	LH front rim	1	\$1,451.50		7X
12	LH front tyre	1	\$350.00	S.N	X
13	LHF hup cap	1	\$185.62		✓
14	LH front door	1	\$1,126.90		X
15	Lh rear door	1	\$1,112.70		X
16			765.19		
17		201.	573.89		
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SME 5401 M** Submit By : **Carmen Lim**
Make & Model : **TOYOTA PRIUS ALPHA** Year of Manufacture : **2018**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER,LHF FENDER,LHS MIRROR, LHF DOOR,LHR DOOR,LHS SKIRT,REAR BUMPER)	\$1,400.00	500
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER,LHF FENDER,LHS MIRROR, LHF DOOR,LHR DOOR,LHS SKIRT,REAR BUMPER)	\$1,400.00	1200
3	To check wiring	\$50.00	20
4	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.	\$300.00	X
5	To tuff coat.	\$150.00	X
6	To do wheel alignment.	\$120.00	60
			1,780.00
			T/P \$2,353.89

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.