

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19017815/KHA3Q2

Date: 08/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SLT3421B **Insured Vehicle No :** SJR2008C

Date of Loss: 05/10/2019 Nature of Claim: TP Claim No: 8110568860SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT3421B	Engine No:	2ZRS106248
Make & Model:	TOYOTA PRIUS, 1.5 HYBRID (A)	Chassis No:	JTDKB3FU603574826
Reg. Date:	26/10/2017 (Man. Year: 2017)	Odometer:	202190 km
Colour:	Metallic Silver		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 3 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,840.64	1,119.50	2,721.14	70.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	980.51	494.28	486.23	49.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,821.15	1,613.78	3,207.37	66.53
+ GST 7.00/7.00% (S\$)	337.48	112.96	224.52	66.53
Nett Amount (S\$)	5,158.63	1,726.74	3,431.89	66.53
+ Car Rental (6.0 x S\$61.99/day) (S\$)		371.94		
+ Doc/Search Fee (S\$)		7.48		
Nett Liability (S\$)		2,106.16		

INSPECTION

Date of Assignment: 09/10/2019

Date Inspected: 09/10/2019 Inspected At: 385 SIN MING DRIVE
Repairer: Esteem Performance Pte Ltd (HQ)

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled / Cracked	450.80 FL	*450.80 FL
2	1		*RIGHT HEADLAMP ASSY	Not Necessary	2,531.60 FL	*- FL
3	1		*R/CLIP	Not Necessary	20.00 FL	*- FL
4	1		*R/F WING	Bent	868.70 FL	*868.70 FL
5	1		*R/F WING BADGE	Necessary	44.17 FL	*44.17 FL
6	1		*R/F WHEELHOUSE COVER	Not Necessary	185.64 FL	*- FL
7	1		*FOG LAMP RH	Not Necessary	910.70 FL	*- FL
8	1		*FRONT BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
9	1		*SIDE RETAINER LH	Serviceable	107.20 FL	*- FL
10	1		*SIDE RETAINER RH	Not Necessary	107.20 FL	*- FL
11	1		*RHF UNDERSHIELD CLIP	Not Necessary	25.00 FL	*- FL
12	1		*RHF HUP CAP	Dented	195.62 FL	*195.62 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,486.63	1,599.29
- List Item Discount on L Items 30.00/30.00% (\$\$)	1,645.99	479.79
Total Parts (\$\$)	3,840.64	1,119.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DO ALIGNMENT ALIGNMENT	New	120.00	60.00
2	TUFF COAT TUFF COAT	New	150.00	30.00
3	60.0 WU X 50.00 SGD/H	New	300.00	140.00
4	LABOUR COST 59.0 WU X 50.00 SGD/H	New	295.00	170.00
5	MATERIAL COST	New	115.51	94.28
			Gross Labour Cost (\$)	494.28

Report was unsubmitted during this print-out.

< END OF ESTIMATES >