

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III19017886/K1PA3Q2

Date: 17/04/2020

### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MFL0003414
<b>Claimant Vehicle No :</b>	SHD1214C	<b>Insured Vehicle No :</b>	SMK6817J
Date of Loss:	08/10/2019	Nature of Claim:	TP
		Claim No:	MFL2019D0001223

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHD1214C</b>		
Make & Model:	HYUNDAI I30 GDH, 1.6 D TCI 5DR DCT (M)	Engine No:	D4FBGZ115774
Reg. Date:	22/03/2017 (Man. Year: 2016)	Chassis No:	TMAD281UVHJ125074
Colour:	Silver	Odometer:	200469 km
Engine Capacity:	1582 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Maxxis 7 mm	Rear Left Side:	Maxxis 7 mm
Front Right Side:	Maxxis 7 mm	Rear Right Side:	Maxxis 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,294.37	0.00	1,294.37	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,760.00	360.00	1,400.00	79.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>3,054.37</b>	<b>360.00</b>	<b>2,694.37</b>	<b>88.21</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>213.81</b>	<b>25.20</b>	<b>188.61</b>	<b>88.21</b>
<b>Nett Amount (\$\$)</b>	<b>3,268.18</b>	<b>385.20</b>	<b>2,882.98</b>	<b>88.21</b>
<b>+ Loss of Use (2.0 x S\$40.00/day) (\$\$)</b>		80.00		
<b>+ Car Rental (2.0 x S\$90.76/day) (\$\$)</b>		181.52		
<b>+ Doc/Search Fee (\$\$)</b>		7.45		
<b>Nett Liability (\$\$)</b>		<b>654.17</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>650.00</b>		

### INSPECTION

Date of Assignment: 08/10/2019

Date Inspected: 08/10/2019 Inspected At:

Premier Automotive Services Pte Ltd  
(HQ)  
23 Changi South Ave 2, #01-02  
Singapore 486443

Estimated Period of Repair: 2.0 days

---

**Adjuster:** KALVIN ANG WEI KUN**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 06 Dec 2019)	
<b>Parts:</b>	N/A	HYUNDAI I30 GDH 1.6 D TCI 5DR DCT (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD1214C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR BUMPER N/S & O/S SIDE BRACKET	Serviceable	104.40 FL	*- FL
2	1		*REAR BUMPER O/S REFLECTOR	Serviceable	107.50 FL	*- FL
3	1		*REAR BUMPER	Repair	811.11 FL	*- FL
4	1		*REAR O/S MUD FLAP GUARD	Serviceable	47.45 FL	*- FL
5	1		*SET REAR BUMPER CLIPS	Not Necessary	48.00 FS	*- FS
6	1		*SET REVERSE SENSOR	Serviceable	280.00 FS	*- FS
7	1		*REAR O/S FENDER STICKER	Not Necessary	60.00 FS	*- FS
8	1		*SUNDRY	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>1,508.46</b>	<b>0.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	214.09	0.00
<b>Total Parts (\$\$)</b>	<b>1,294.37</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO DISMANTLE AND REPLACE REVERSE SENSOR AND TEST SYSTEM	New	80.00	0.00
2	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	0.00
3	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING TO KNOCK -OUT ,STRAIGHTEN ,REPAIR,RESHAPE OF THE REAR O/S FENDER ,REAR BUMPER ETC	New	750.00	180.00
4	TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER ,REAR O/S RIM ,RIM O/S FENDER	New	600.00	180.00
5	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	150.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,760.00</b>	<b>360.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >