

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/SMO19017896/HVD3E2
Date: 21/04/2023**REFERENCE**

Handling Insurer:	SOMPO INSURANCE SINGAPORE PTE. LTD.	Policy No:	D19MTPV01010029
Claimant Vehicle No :	SLB5759J	Insured Vehicle No :	SMN4999P
Date of Loss:	27/09/2019	Nature of Claim:	TP
		Claim No:	CMTD1904699

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB5759J		
Make & Model:	TOYOTA VELLFIRE, 2.5 2.5V CVT ABS AIRBAG 2WD 5DR (A)	Engine No:	2ARH581593
Reg. Date:	14/04/2016 (Man. Year: 2015)	Chassis No:	AGH300024524
Colour:	Black	Odometer:	83792 km
Engine Capacity:	2493 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	Continental 5 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,051.80	2,305.87	4,745.93	67.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	740.00	1,760.00	70.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,551.80	3,045.87	6,505.93	68.11
Approved Total (Overridden) (\$\$)		2,400.00		
Nett Amount (\$\$)	9,551.80	2,400.00	7,151.80	74.87

INSPECTION

Date of Assignment:	10/10/2019	
Date Inspected:	10/10/2019	Inspected At: MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934
Estimated Period of Repair:	4.0 days	

Adjuster: LEE HOCK ANN**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Apr 2023)
Parts:	M1-MPV	TOYOTA VELLFIRE 2.5 2.5V CVT ABS AIRBAG 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	LKK Auto Consultants Pte Ltd/SLB5759J/21/04/2023 10:57	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (\$751.00) (50%)	Dented	1,985.00 FL	*375.50 FL
2	1		*FRONT BUMPER LOWER GARNISH	Serviceable	512.00 FL	*- FL
3	1		*FRONT BUMPER SPONGE	Not Necessary	298.00 FL	*- FL
4	1		*FRONT BUMPER BRACKET RH	Not Necessary	144.00 FL	*- FL
5	1		*FRONT BUMPER SIDE RETAINER RH	Not Necessary	112.00 FL	*- FL
6	1		*FRONT BUMPER SIDE COVER RH	Not Necessary	160.00 FL	*- FL
7	1		*HEADLAMP LED RH	Cut	3,824.20 FL	*1,850.00 FL
8	1		*HEADLAMP GARNISH RH	Cut	112.00 FL	*60.00 FL
9	1		*FRONT HEADLAMP LOWER BRACKET	Not Necessary	112.00 FL	*- FL
10	1		*WIPER WASHER TANK C/W MOTOR	Not Necessary	459.00 FL	*- FL
11	1		*FRONT FENDER RH	Buckled	987.00 FL	*789.00 FL
12	1		*FRONT FENDER COWLING RH	Not Necessary	321.20 FL	*- FL
13	1		*FRONT FENDER EMBLEM HYBRID RH	Not fitted	96.00 FL	*- FL
14	1		*FRONT BUMPER CLIPS	Not Necessary	80.00 FS	*- FS
15	1		*SET FRONT FENDER COWLING CLIPS	Not Necessary	50.00 FS	*- FS
16	1		*FRONT FENDER SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,332.40	3,074.50
- List Item Discount on L Items 25.00/25.00% (S\$)	2,280.60	768.63
Total Parts (S\$)	7,051.80	2,305.87

LKK Auto Consultants Pte Ltd/SLB5759J/21/04/2023 10:57. Not valid without Reference section.
--

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL WIRING }	New	200.00	30.00
2	REALIGN HEADLAMP }	New	300.00	-
3	CHECK AND RESET FAULT CODE LIGHT ON	New	500.00	70.00
4	APPLY ANTI RUST ON AFFECTED AREAS	New	300.00	40.00
5	SPRAY PAINTING ON AFFECTED AREAS	New	600.00	300.00
6	PANEL BEATING ON AFFECTED AREAS	New	600.00	300.00
Gross Labour Cost (S\$)			2,500.00	740.00

LKK Auto Consultants Pte Ltd/SLB5759J/21/04/2023 10:57. Not valid without Reference section.

< END OF ESTIMATES >