

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19017905/AGTD3E2

Date: 29/06/2020

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VPCB/19-000001-00
Claimant Vehicle No :	SJH5750A	Insured Vehicle No :	SKR5405H
Date of Loss:	22/09/2019	Nature of Claim:	TP
		Claim No:	MSC/V/19-001203

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJH5750A	Engine No:	1NZD183185
Make & Model:	TOYOTA ALLION, 1.5 (A)	Chassis No:	NZT2603032428
Reg. Date:	13/08/2008 (Man. Year: 2008)	Odometer:	144253 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Comfortmax 6 mm	Rear Left Side:	Comfortmax 6 mm
Front Right Side:	Comfortmax 6 mm	Rear Right Side:	Comfortmax 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,716.80	909.15	1,807.65	66.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,050.00	430.00	620.00	59.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,766.80	1,339.15	2,427.65	64.45
Approved Total (Overridden) (S\$)		1,050.00		
Nett Amount (S\$)	3,766.80	1,050.00	2,716.80	72.12

INSPECTION

Date of Assignment:	09/10/2019	
Date Inspected:	14/10/2019 Inspected At:	Our Bro's Workshop (s) Pte Ltd (HQ) 10 Kaki Bukit Road 2, #03-37/38 First East Centre Singapore 417868
Estimated Period of Repair:	2.0 days	

Adjuster: XING GUO QIANG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jun 2020)
Parts:	143	TOYOTA ALLION 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJH5750A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	791.40 F	*- FL
2	1		*FRONT BUMPER CLIPS	Not Necessary	30.00 F	*- FL
3	1		*FRONT BUMPER SIDE HOLDER LH	Not Necessary	38.00 F	*- FL
4	1		*FRONT LH FENDER	Not Necessary	645.20 F	*- FL
5	1		*FRONT GRILLE	Cracked	349.10 F	*349.10 FL
6	1		*FRONT GRILLE CLIPS	Necessary	20.00 F	*20.00 FL
7	1		*FRONT GRILLE LOGO	Necessary	78.00 F	*78.00 FL
8	1		*HEADLAMP LH	Cracked	765.10 F	*765.10 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,716.80	1,212.20
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	303.05
Total Parts (S\$)	2,716.80	909.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	500.00	200.00
2	SPRAY PAINTING	New	500.00	200.00
3	WIRING	New	50.00	30.00
Gross Labour Cost (S\$)			1,050.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >