

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: [sur@lkkauto.com](mailto:sur@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG19017911/T1VF3E2

**Date:** 19/10/2020

### REFERENCE

Insured/Claimant:	RENGARAJ RANGANATHAN	Policy No:	1700018472-02
Date of Loss:	05/10/2019	Nature of Claim:	OD
		Claim No:	4960439546SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP8208P			
Make & Model:	AUDI Q2, 999cc 1.0 TFSI S TRONIC (A)	Engine No:	CHZ401661	
Reg. Date:	19/06/2017 (Man. Year: 2017)	Chassis No:	WAUZZZGA3HA052306	
Colour:	White	Odometer:	41293 km	
Engine Capacity:	999 cc			
Market Value/New Car Price:	S\$87,000.00			
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>			

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	61,543.88	40,498.96	21,044.92	34.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	41,844.00	27,064.00	14,780.00	35.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>103,387.88</b>	<b>67,562.96</b>	<b>35,824.92</b>	<b>34.65</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>55,000.00</b>		
<b>(\$\$)</b>	103,387.88	55,000.00	48,387.88	46.80
<b>+ GST 7.00/7.00% (\$\$)</b>	7,237.15	3,850.00	3,387.15	46.80
<b>Nett Amount (\$\$)</b>	<b>110,625.03</b>	<b>58,850.00</b>	<b>51,775.03</b>	<b>46.80</b>

### INSPECTION

Date of Assignment:	10/10/2019	
Date Inspected:	09/10/2019	Inspected At: 24 Benoi Sector
		Repairer : Premium Automobiles Pte Ltd
Estimated Period of Repair:	33.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,704.00 FS	*1,364.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	314.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTRE	Deformed	179.00 FS	*143.20 FS
4	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Missing	308.00 FS	*245.60 FS
5	2		*FRONT BUMPER END CAP - LH / RH	Missing	62.00 FS	*48.80 FS
6	1		*FRONT BUMPER SPOILER	Deformed	273.00 FS	*218.00 FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Cracked	142.00 FS	*113.20 FS
8	2		*FRONT WHEEL SPOILER - LH / RH	O/S Cracked / N/S Deformed	62.00 FS	*49.12 FS
9	2		*FRONT BUMPER ADAPTER - LH / RH	Necessary	70.00 FS	*55.92 FS
10	1		*RADIATOR GRILLE	Cracked	1,301.00 FS	*1,040.80 FS
11	1		*RADIATOR GRILLE STRIKER PLATE	Distorted	114.00 FS	*91.20 FS
12	1		*FRONT BUMPER CARRIER	Bent	625.00 FS	*499.60 FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	71.00 FS	*56.08 FS
14	1		*FRONT BUMPER COVER	Deformed	91.00 FS	*72.56 FS
15	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Deformed	64.00 FS	*51.20 FS
16	1		*FRONT BUMPER DISTANCE PIECE	Not Necessary	12.00 FS	*- FS
17	1		*HORN - LH LOW TONE	Cracked	262.00 FS	*209.20 FS
18	1		*SIGNAL HORN - RH HIGH TONE	Deformed	180.00 FS	*143.60 FS
19	2		*HORN SPRING SHACKLE - LH / RH	Bent	58.00 FS	*45.44 FS
20	1		*EXTERNAL TEMPERATURE SENSOR	Distorted	54.00 FS	*42.96 FS
21	1		*BONNET	Bent	2,549.00 FS	*2,039.20 FS
22	1		*BONNET ATTACHMENT PARTS	Not Necessary	149.00 FS	*- FS
23	2		*BONNET LID HINGE - LH / RH	Not Necessary	108.00 FS	*- FS
24	1		*BONNET GAS FILLED STRUT	Not Necessary	93.00 FS	*- FS
25	2		*BONNET STRIKER - LH / RH	Bent	200.00 FS	*159.04 FS
26	1		*BONNET SOUND ABSORBER	Not Necessary	201.00 FS	*- FS
27	1		*BONNET IMPACT PROTECTION - LH / RH / CENTRE (3PCS)	Necessary	82.00 FS	*64.40 FS
28	2		*BONNET LOWER COVER - LH / RH	Not Necessary	74.00 FS	*- FS
29	2		*BONNET UPPER COVER - LH / RH	Not Necessary	28.00 FS	*- FS
30	1		*PLENUM CHAMBER COVER FRONT	Not Necessary	144.00 FS	*- FS
31	1		*WATER BOX	Not Necessary	124.00 FS	*- FS
32	1		*BONNET BOWDEN CABLE - CENTRE	Bent	53.00 FS	*41.68 FS
33	1		*BONNET LID LOCK CABLE	Not Necessary	67.00 FS	*- FS
34	1		*BONNET RELEASE ELEMENT	Distorted	53.00 FS	*41.68 FS
35	2		*BONNET BOWDEN CABLE - LH / RH	Distorted	106.00 FS	*83.36 FS
36	1		*BONNET RELEASE LEVER	Distorted	12.00 FS	*9.60 FS
37	1		*CAUTION SIGN STICKER	Necessary	13.00 FS	*9.76 FS
38	1		*AIRCON STICKER	Necessary	7.00 FS	*5.12 FS
39	2		*HEADLIGHT MOUNTING - LH / RH	Cracked	214.00 FS	*171.20 FS
40	2		*LED HEADLIGHT - LH / RH	O/S Cut / N/S Cracked	8,982.00 FS	*7,185.60 FS
41	2		*MAIN LIGHT ELECTRONICS POWER MODULE - LH / RH	Not Necessary	1,385.00 FS	*- FS
42	2		*LIGHT CONTROL SYSTEM CONTROL UNIT - LH / RH	Not Necessary	1,015.00 FS	*- FS
43	2		*LED WITH HEAT SINK - LH / RH	Not Necessary	1,332.00 FS	*- FS
44	2		*HEADLIGHT HOSE - LH / RH	Not Necessary	52.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	2		*LIFT CYLINDER - LH / RH	Distorted	256.00 FS	*136.00 FS
46	1		*HEADLIGHT HOSE	Cracked	170.00 FS	*21.76 FS
47	1		*HEADLIGHT DISTRIBUTOR	Distorted	65.28 FS	*65.28 FS
48	3		*HEADLIGHT ELBOW FITTING	Not Necessary	81.00 FS	*- FS
49	1		*HEADLIGHT PUMP	Not Necessary	147.00 FS	*- FS
50	1		*WINDSCREEN WASHER SYSTEM PUMP	Not Necessary	118.00 FS	*- FS
51	1		*WASH WATER RESERVOIR	Deformed	156.00 FS	*124.80 FS
52	1		*HEADLIGHT WASHER STRAINER	Not Necessary	19.00 FS	*- FS
53	1		*HEADLIGHT WASHER END CAP	Not Necessary	19.00 FS	*- FS
54	1		*LOCK CARRIER	Cracked	907.00 FS	*725.60 FS
55	1		*A/C CONDENSER	Bent	503.00 FS	*402.00 FS
56	1		*REFRIGERANT LINE A/C CONDENSER - CUT - OFF POINT	Bent	601.00 FS	*480.40 FS
57	1		*REFRIGERANT LINE A/C COMPRESSOR - CONDENSER	Bent	461.00 FS	*368.80 FS
58	1		*RADIATOR	Bent	878.00 FS	*718.80 FS
59	1		*ADDITIONAL RADIATOR	Bent	837.00 FS	*686.00 FS
60	2		*RADIATOR BRACKET - UPPER	Distorted	77.00 FS	*61.28 FS
61	2		*RADIATOR BUSH - LOWER	Deformed	18.00 FS	*14.24 FS
62	2		*RADIATOR SEALING STRIP - LH / RH	Necessary	32.00 FS	*24.96 FS
63	4		*READY MIX COOLANT	Necessary	84.00 FS	*67.20 FS
64	1		*RADIATOR FAN	Not Necessary	1,483.00 FS	*- FS
65	2		*RADIATOR AIR GUIDE - LH / RH	Deformed	54.00 FS	*42.72 FS
66	1		*RADIATOR AIR GUIDE - UPPER CENTRE	Deformed	19.00 FS	*15.20 FS
67	1		*AIR INLET	Deformed	53.00 FS	*41.84 FS
68	1		*AIR FILTER	Not Necessary	62.00 FS	*- FS
69	1		*INTER COOLER GASKET	Not Necessary	13.00 FS	*- FS
70	1		*WATER DRAINAGE HOSE	Not Necessary	31.00 FS	*- FS
71	1		*AIR FILTER	Not Necessary	252.00 FS	*- FS
72	1		*INTAKE MANIFOLD	Not Necessary	129.00 FS	*- FS
73	1		*ACTIVATED CHARCOAL CONTAINER	Not Necessary	294.00 FS	*- FS
74	1		*NOISE INSULATION - FRONT	Cracked	239.00 FS	*191.20 FS
75	2		*FRONT WHEEL COVER - LH / RH	O/S Missing / N/S Deformed	588.00 FS	*469.60 FS
76	1		*REAR BUMPER	Deformed	1,074.00 FS	*859.20 FS
77	1		*REAR BUMPER FIXING PARTS	Not Necessary	70.00 FS	*- FS
78	1		*REAR BUMPER SPOILER	Cracked	259.00 FS	*207.20 FS
79	1		*REAR BUMPER TOWING EYE COVER	Deformed	39.00 FS	*30.88 FS
80	2		*REAR LIGHT REFLECTOR - LH / RH	Missing	54.00 FS	*43.04 FS
81	1		*REAR BUMPER CARRIER	Bent	501.00 FS	*400.40 FS
82	2		*REAR BUMPER HOLDING STRAP - LH / RH	Cracked	24.00 FS	*17.92 FS
83	2		*REAR BUMPER GUIDE SECTION - LH / RH	Deformed	98.00 FS	*77.44 FS
84	1		*SET REAR BUMPER WIRING	Not Necessary	472.00 FS	*- FS
85	1		*REAR LID	Bent	2,195.00 FS	*1,756.00 FS
86	2		*REAR LID HINGE	Not Necessary	275.00 FS	*- FS
87	1		*REAR LID ATTACHMENT PARTS	Not Necessary	109.00 FS	*- FS
88	1		*REAR LID LOCK STRIKER	Not Necessary	265.00 FS	*- FS
89	1		*REAR LID FLAP GASKET	Necessary	106.00 FS	*84.40 FS
90	1		*REAR LID LOCK STRIKER	Bent	196.00 FS	*156.40 FS
91	1		*BONNET LOCK COVER	Distorted	11.00 FS	*8.64 FS
92	1		*REAR LID LOCK ACTUATOR PUSH BUTTON	Not Necessary	167.00 FS	*- FS
93	2		*REAR LID GAS FILLED STRUT BRACKET - LH / RH	Not Necessary	66.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
94	2		*REAR LID BRACKET - LH / RH	Not Necessary	178.00 FS	*- FS
95	1		*LICENCE PLATE TRIM	Cut	213.00 FS	*170.00 FS
96	1		*REAR LID BALANCE WEIGHT	Not Necessary	485.00 FS	*- FS
97	1		*AUDI EMBLEM	Necessary	113.00 FS	*90.00 FS
98	1		*Q2 INSCRIPTION	Necessary	87.00 FS	*69.28 FS
99	1		*TFSI INSCRIPTION	Necessary	87.00 FS	*69.28 FS
100	1		*REAR LID FOAM STRIPS	Necessary	121.00 FS	*96.40 FS
101	1		*REAR LID SPOILER FIXING PARTS	Necessary	121.00 FS	*96.40 FS
102	1		*REAR WINDSCREEN	Necessary	711.00 FS	*568.80 FS
103	1		*PRIMER	Necessary	19.00 FS	*15.20 FS
104	2		*LED LICENCE PLATE LIGHT	Not Necessary	92.00 FS	*- FS
105	2		*TAIL LIGHT - LH / RH	N/S Cut / O/S Cracked	2,414.00 FS	*1,931.20 FS
106	2		*TAIL LIGHT TRIM - LH / RH	Deformed	54.00 FS	*43.04 FS
107	1		*CROSS PANEL REINFORCEMENT	Bent	669.00 FS	*535.20 FS
108	1		*REAR CROSS PANEL	Bent	224.00 FS	*178.80 FS
109	1		*REAR CROSS PANEL CONNECTING PIECE - LH	Bent	37.00 FS	*29.44 FS
110	1		*REAR CROSS PANEL BOOT FLOOR PLATE	Buckled	1,687.00 FS	*1,349.60 FS
111	1		*REAR CROSS PANEL TRIM	Deformed	141.00 FS	*112.40 FS
112	1		*REAR CROSS PANEL TRIM PLASTIC TRAY	Not Necessary	210.00 FS	*- FS
113	1		*LUGGAGE COMPARTMENT FLOOR COVERING	Not Necessary	646.00 FS	*- FS
114	1		*REAR LID TRIM PANEL - LOWER	Deformed	447.00 FS	*357.20 FS
115	2		*REAR WHEEL COVER - LH / RH	Deformed	312.00 FS	*248.80 FS
116	1		*REAR SILENCER	Bent	653.00 FS	*522.00 FS
117	1		*REAR SILENCER DUAL CLIP	Bent	55.00 FS	*43.52 FS
118	2		*EXHAUST SYSTEM RETAINER	Not Necessary	75.00 FS	*- FS
119	1		*THREE-POINT AUTOMATIC SEAT BELT	Cut	952.00 FS	*761.60 FS
120	1		*FELT STRIPS - LH	Not Necessary	22.00 FS	*- FS
121	1		*THREE-POINT AUTOMATIC SEAT BELT	Activated	952.00 FS	*761.60 FS
122	1		*FELT STRIPS - LH	Not Necessary	22.00 FS	*- FS
123	2		*SEAT BELT HEIGHT ADJUSTER	Activated	322.00 FS	*257.60 FS
124	1		*AIRBAG CONTROL UNIT	Necessary	1,578.00 FS	*1,262.40 FS
125	1		*FRONT NO PLATE	Bent	40.00 FS	*40.00 FS
126	1		*REAR NO PLATE	Bent	40.00 FS	*40.00 FS
127	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
128	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
129	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
130	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
131	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
132	1		*SUNDRIES	Necessary	1,000.00 FS	*243.60 FS
133	1		*HEAT SHIELD FOR REAR SILENCER	Buckled	122.40 FS	*122.40 FS
134	1		*BONNET BUNGS	Necessary	87.36 FS	*87.36 FS
135	1		*COOLANT HOSE WITH QUICK RELEASE COUPLING LOWER	Cracked	100.40 FS	*100.40 FS
136	1		*COOLANT HOSE WITH QUICK RELEASE COUPLING FRONT	Cracked	186.80 FS	*186.80 FS
137	1		*MECHATRONIC WITH SOFTWARE	Bent	2,952.00 FS	*2,952.00 FS
138	1		*TRANSMISSION FLUID	Necessary	96.00 FS	*96.00 FS
139	1		*WHEEL HOUSING LINER LHS FRONT	Cut	146.00 FS	*146.00 FS
140	1		*WHEEL HOUSING LINER RHS FRONT	Cut	146.00 FS	*146.00 FS
141	1		*BONNET LID LOCK WITH MIRCRO SWITCH	Not Working	293.60 FS	*293.60 FS
142	1		*CORRUGATED PIPE FOR WATER RESERVOIR	Cut	59.92 FS	*59.92 FS
143	1		*WATER RESERVOIR TERMINAL	Missing	7.04 FS	*7.04 FS
144	1		*RADIATOR FAN WITH FAN RING	Cracked	836.80 FS	*836.80 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
145	1		*AIR INTAKE TOP COVER	Cracked	21.36 FS	*21.36 FS
146	1		*AIR INTAKE AIR GUIDE	Cracked	14.48 FS	*14.48 FS
147	1		*END PANEL CONNECTING PLATE RHS	Cracked	29.44 FS	*29.44 FS
148	1		*REAR WHEEL HOUSING LINER RHS	Cracked	150.80 FS	*150.80 FS
149	1		*BOLT FOR SPARE WHEEL MOUNTING	Cracked	19.20 FS	*19.20 FS
150	1		*SUPPORT FLOOR LUGGAGE BOOT LINING LHS LOWER	Deformed	58.00 FS	*58.00 FS
151	4		*REAR PARKING AID SENSOR - LH / RH	Not Necessary	924.00 FS	*- FS
152	4		*REAR PARKING AID SEAL RING	Necessary	12.00 FS	*9.68 FS
153	2		*REAR LID GAS FILLED STRUT	Not Necessary	217.00 FS	*- FS
154	1		*SEAT FRAME WITH HEIGHT ADJUSTMENT	Bent	1,688.00 FS	*1,688.00 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$) 61,543.88 40,498.96**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT	New	280.00	0.00
2	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER	New	800.00	800.00
3	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
4	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
5	TO REMOVE AND REINSTALL REAR LIDS CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR WIPER ASSY	New	480.00	480.00
6	TO RENEW REAR WINDSCREEN	New	480.00	480.00
7	TO INSTALL REAR WINDSCREEN SOLAR FILM	New	400.00	400.00
8	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,400.00	1,400.00
9	TO DISMANTLE AND REINSTALL CENTRE CONSOLE. RENEW AIRBAG CONTROL UNIT AND BOTH FRONT SEATBELT	New	1,800.00	1,800.00
10	TO REMOVE AND REINSTALL ENGINE ASSY WITH GEARBOX ASSY TO FACILITATE CAR O-LINER REPAIRS	New	2,800.00	0.00
11	TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY WITH SUBFRAME TO FACILITATE CAR O-LINER REPAIRS. INSPECT FOR DAMAGES AND RENEW IF NECESSARY	New	2,400.00	0.00
12	TO REMOVE AND REINSTALL EXHAUST SYSTEM AND REAR SUSPENSION ASSEMBLY. RENEW ACCORDINGLY	New	2,400.00	2,400.00
13	TO REMOVE AND REINSTALL FUEL TANK ASSY	New	600.00	600.00
14	TO PLACE VEHICLE ON CAR O-LINER	New	2,400.00	1,200.00
15	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH HEADLIGHTS, REAR BUMPER AND REAR LID. CUT OUT AND REWELD END PANELLING AND SPARE WHEEL HOUSING. TO REPAIR BOTH FRONT FENDERS AND BOTH REAR FENDERS. RENEW FRONT LOCK CARRIER AND ALIGN POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	12,000.00	8,000.00
16	TO CARRY OUT STONE CHIP PRIMER WORK ON REAR END PANELLING AND SPARE WHEEL HOUSING	New	780.00	780.00
17	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, ENGINE COMPARTMENT, REAR BUMPER, REAR LID, BOTH REAR FENDERS, HINGES, END PANELLING AND SPARE WHEEL HOUSING. TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT	New	10,100.00	6,000.00
18	TO CARRY OUT WHEEL ALIGNMENT	New	240.00	240.00
19	TO CARRY OUT DIAGNOSTIC CHECKS	New	384.00	384.00
20	TO RENEW MECHATRONIC WITH SOFTWARE. TO CARRY OUT CALIBRATION	New	980.00	980.00
21	TO REMOVE AND REINSTALL DRIVER SEAT	New	180.00	180.00
22		New	300.00	300.00

Report was unsubmitted during this print-out.

Report was unsubmitted during this print-out.

<https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen...> 19/10/2020