

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 INV No. AC2003179 INV Date 15/04/2020

INV Date 15/04/2020 Reference CC4/LPC19017922/Kha3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SKR 1992E

Insured Veh. GBD 201S

Claim No. 18/19/VC00/022453

Policy No. Z/18/VC00/102569

Accident Date 01/10/2019

Inspection Date 18/10/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internationale Des Experts En Automobile							
LONPAC INSURANCE BHD Ref: CC4/LPC1			Ref : CC4/LPC1901792	2/Kha3q2				
	BEACH ROAD 04/07 THE CONC	OURSESINGAPORE 199555	Date: 15-04-2020 Code: LPC2					
1.	1. Policy Particulars :- THIRD PARTY CLAIM							
	Insured Veh.	GBD 201S	Veh. Inspected	SKR 1992E				
	Policy No.	Z/18/VC00/102569	Coverage (\$)	0.00				
	Claim No.	18/19/19/VC00/022453	Excess (\$)	0.00				
	Assign From	KENNY	Assign Date	09/10/2019				
2.		Vehicle Partic	culars & Condition					
	Make & Model	MERCEDES C180 (A)	c.c	1595				
	Engine No.	HIDDEN	Year of Reg.	2015				
	Chassis No.	WDD2050402R028384	Colour	METALLIC SILVER				
	Odometer	52786	Steering	IN ORDER				
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM				
	General	GOOD						
3.	_	Conditi	ons of Tyres					
		Size	Make	Balance				
	R/H Front Tyre	225/50 R17	MICHELIN	6 mm				
	L/H Front Tyre	225/50 R17	MICHELIN	6 mm				
	R/H Rear Tyre	225/50 R17	MICHELIN	6 mm				
	L/H Rear Tyre	225/50 R17	MICHELIN	6 mm				
4.	,	•	on of Damages					
	THE VEHICLE SU	STAINED DAMAGES AT THE O/S	REAR BODY.					
	DAMAGES SEE D	ETAILS.						
5.		Genera	Information					
	Accident Date	01/10/2019	Inspection Date	18/10/2019				
	Survey held at	S & H MOTOR PTE LTD						
		160 SIN MING DRIVE #07-02 SIN MING AUTOCITY SINGAPORE 575722						
5a.		Re	emarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.							
5b.	<u> </u>							
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days							



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 1992E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	LH REAR DOOR (WCP)	BENT	1,100.00	1,100.00
1	LH REAR DOOR OUTER HANDLE (WCP)	SERVICEABLE	390.00	-
1	LH REAR DOOR INNER LOCK (WCP)	TO REPAIR SEE LABOUR	240.00	-
1	LH REAR FENDER (WCP)	BENT	1,250.00	1,250.00
1	REAR BUMPER (WCP)	TO REPAIR SEE LABOUR	980.00	-
1	LH REAR WHEEL RIM (WCP)	DENTED	580.00	580.00
1	LH REAR KNUCKLE ARM (WCP)	SERVICEABLE	850.00	-
1	LH REAR KNUCKLE ARM BEARING (WCP)	SERVICEABLE	190.00	-
1	REAR LEFT DOOR RUBBER (ADDITIONAL)(WCP)	NECESSARY	190.00	190.00
	COST PLUS 15%		865.50	468.00
			6,635.50	3,588.00
	SPECIAL NETT ITEMS			
1	REAR SILICON GUM (SN)	NECESSARY	80.00	40.00
1	REAR RUBBER SEAL (SN)	NECESSARY	28.00	28.00
			108.00	68.00
	<u>LABOUR</u>			
	TO REMOVE AND REINSTALL REAR WINDSCREEN AND CONDUCT WATER LEAK TEST.		120.00	120.00
	TO SPRAY PAINT REAR RH FENDER,REAR BUMPER,RH REAR DOOR AND ACCIDENT REPAIR AREAS.		800.00	700.00
	TO REMOVE DAMAGED PARTS, TO JACK OUT LH REAR DOOR, LH REAR FENDER, REAR BUMPER, TO REINSTALL RH REAR DOOR QUARTER GLASS, ECU DIAGNOSTIC AND ADJUST BODY ALIGNMENT. INCLUSIVE OF THE REPAIR OF LH REAR DOOR INNER LOCK AND REAR BUMPER.		850.00	720.00
	TO PERFORM COMPUTERISED WHEEL ALIGNMENT.		80.00	60.00
			1,850.00	1,600.00
	GRAND TOTAL		8,593.50	5,256.00

Report Ref No. CC4/LPC19017922/Kha3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,200.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/LPC19017922/Kha3q2

KONG SENG CHEONG

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933


Reg. No: 199607198R GST Reg. No. 19-9607198-R


PHOTOGRAPHS FOR VEHICLE NO. SKR 1992E


















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi hdustrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKR 1992E





