

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG19017929/UBA3Q2

**Date:** 30/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800077316

**Claimant**  
**Vehicle No :** SKD5702Z **Insured Vehicle No :** SGH5020J

Date of Loss: 09/10/2019 Nature of Claim: TP Claim No: 2799121063SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKD5702Z</b>		
Make & Model:	BMW 523i, 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A)	Engine No:	09747818N52B25AF
Reg. Date:	16/12/2011 (Man. Year: 2011)	Chassis No:	WBAFP32040C867224
Colour:	Blue	Odometer:	123337 km
Engine Capacity:	2497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	245/40ZR19	Rear Tyre Size:	275/35ZR19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,849.90	2,473.38	1,376.52	35.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	1,050.00	950.00	47.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,849.90</b>	<b>3,523.38</b>	<b>2,326.52</b>	<b>39.77</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,450.00</b>		
<b>(S\$)</b>	5,849.90	2,450.00	3,399.90	58.12
<b>+ GST 7.00/7.00% (S\$)</b>	409.49	171.50	237.99	58.12
<b>Nett Amount (S\$)</b>	<b>6,259.39</b>	<b>2,621.50</b>	<b>3,637.89</b>	<b>58.12</b>
<b>+ Car Rental (3.0 x S\$100.00/day) (S\$)</b>		300.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,923.50</b>		
<b>Global Sum Settlement (S\$)</b>		<b>2,920.00</b>		

### INSPECTION

Date of Assignment: 21/10/2019

Date Inspected: 21/10/2019 Inspected At:

Hock Wah Motor Workshop Pte Ltd  
(Bedok)  
Blk 3011, Bedok Industrial Park E.,

#01-2008/2010/2012  
Singapore 489977

Estimated Period of Repair: 3.0 days

---

**Adjuster:** MARCUS CHUA

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented/Deformed	1,396.60 F	*1,396.60 FL
2	1		*REAR BUMPER RETAINER RH	Not Necessary	137.75 F	*- FL
3	1		*REAR BUMPER RETAINER LH	Not Necessary	137.75 F	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Bent/Cracked	772.05 F	*772.05 FL
5	1		*REAR BUMPER BRACKET RH	No such part	137.75 F	*- FL
6	1		*REAR BUMPER BRACKET LH	No such part	137.75 F	*- FL
7	1		*REAR BUMPER TOWING COVER	Torn	47.60 F	*47.60 FL
8	1		*REVERSE SENSOR (4 Pcs)	Shorted (2 Pcs only)	947.40 F	*473.70 FL
9	1		*REAR BUMPER LOWER CENTER GARNISH	Cracked	58.25 F	*58.25 FL
10	1		*REAR BUMPER REFLECTOR RH	Not Necessary	38.50 F	*- FL
11	1		*REAR BUMPER REFLECTOR LH	Not Necessary	38.50 F	*- FL
12	1		*END PANEL (NPA)	Repair	0.00 F	*- FL
13	1		*BOOTLID (NPA)	Repair	0.00 F	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,849.90</b>	<b>2,748.20</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	0.00	274.82

<b>Total Parts (\$\$)</b>	<b>3,849.90</b>	<b>2,473.38</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	800.00	400.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	800.00	600.00
3	ANTI-RUST COATING	New	250.00	0.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,000.00</b>	<b>1,050.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >