

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG19017933/R1SD3E2

Date: 26/06/2020

REFERENCE

Insured/Claimant:	GOH BEE KHENG	Policy No:	2100237329-08	
Date of Loss:	08/10/2019	Nature of Claim:	OD	Claim No: 2032268109SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJZ3783Z		
Make & Model:	AUDI A3, 1.8 FSI AT ABS D/AB TC HID (A)	Engine No:	CDA157279
Reg. Date:	19/11/2010 (Man. Year: 2010)	Chassis No:	TRUZZZ8P5B1003420
Colour:	White	Odometer:	77275 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$40,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40Z R18	Rear Tyre Size:	225/40Z R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,745.08	8,827.76	6,917.32	43.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,482.00	3,952.00	6,530.00	62.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	26,227.08	12,779.76	13,447.32	51.27
Approved Total (Overridden) (\$\$)		11,000.00		
- Excess (\$\$)	1,200.00	1,200.00	0.00	0.00
(\$\$)	25,027.08	9,800.00	15,227.08	60.84
+ GST 7.00/7.00% (\$\$)	1,751.90	686.00	1,065.90	60.84
Nett Amount (\$\$)	26,778.98	10,486.00	16,292.98	60.84

INSPECTION

Date of Assignment:	11/10/2019	
Date Inspected:	10/10/2019	Inspected At: 281 ALEXANDRA ROAD
		Repairer : Premium Automobiles Pte Ltd
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,236.00 FS	*988.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Serviceable	164.00 FS	*- FS
3	1		*FRONT BUMPER CARRIER	Serviceable	611.00 FS	*- FS
4	1		*FRONT SHOCK ABSORBER - RH	Serviceable	200.00 FS	*- FS
5	1		*FRONT BUMPER GUIDE SECTION - RH	Cracked	35.00 FS	*27.52 FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Missing	233.00 FS	*186.40 FS
7	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Serviceable	177.00 FS	*- FS
8	1		*FRONT BUMPER FOAM FILLER PIECE	Cut	118.00 FS	*94.00 FS
9	1		*SPRING SHACKLE	Serviceable	47.00 FS	*- FS
10	2		*SIGNAL HORN - LOW TONE / HIGH TONE	Scratched	412.00 FS	*329.60 FS
11	1		*FRONT FENDER - RH	Bent	692.00 FS	*553.60 FS
12	1		*FRONT FENDER ATTACHMENT PARTS	Serviceable	44.00 FS	*- FS
13	3		*FRONT FENDER - FRONT / REAR / CENTRE	Bent	135.00 FS	*106.80 FS
14	1		*FRONT FENDER BRACE - RH	Bent	49.00 FS	*39.12 FS
15	1		*WHEEL HOUSING LINER - RH	Cracked	158.00 FS	*126.00 FS
16	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Serviceable	66.00 FS	*- FS
17	1		*FRONT WHEEL HOUSING LINER - RH	Deformed	121.00 FS	*96.80 FS
18	1		*WHEEL HOUSING LINER SPOILER - RH	Serviceable	51.00 FS	*- FS
19	1		*BONNET	Bent	2,189.00 FS	*1,751.20 FS
20	1		*BONNET ATTACHMENT PARTS	Serviceable	88.00 FS	*- FS
21	2		*BONNET LID HINGE - LH / RH	Serviceable	106.00 FS	*- FS
22	1		*BONNET GAS FILLED STRUT	Serviceable	109.00 FS	*- FS
23	1		*BONNET CATCH HOOK	Serviceable	85.00 FS	*- FS
24	1		*GAS FILLED STRUT BRACKET - RH	Serviceable	38.00 FS	*- FS
25	1		*BONNET LID LOCK	Serviceable	196.00 FS	*- FS
26	1		*MICRO SWITCH	Serviceable	99.00 FS	*- FS
27	1		*BONNET LOCK COVER - UPPER FRONT	Serviceable	46.00 FS	*- FS
28	1		*HEADLIGHT MOUNTING - RH	Cracked	107.00 FS	*85.60 FS
29	1		*HALOGEN TWIN HEADLIGHTS - RH	Cracked	1,859.00 FS	*1,487.20 FS
30	1		*GAS DISCHARGE LAMP CONTROL UNIT	Not Working	1,051.00 FS	*840.80 FS
31	1		*GAS DISCHARGE LAMP	Cracked	398.00 FS	*318.40 FS
32	2		*COMPENSATING PIECE	Serviceable	80.00 FS	*- FS
33	1		*HEADLAMP HOUSING REPAIRING KIT - RH	Serviceable	65.00 FS	*- FS
34	1		*LIFT CYLINDER - RH	Cracked	192.00 FS	*153.20 FS
35	5		*HEADLIGHT HOSE	Serviceable	179.00 FS	*- FS
36	3		*HEADLIGHT ELBOW FITTING	Serviceable	81.00 FS	*- FS
37	1		*HEADLIGHT SPRING CLIP	Serviceable	12.00 FS	*- FS
38	2		*HALOGEN FOG LAMP - RH	Cracked	237.00 FS	*189.60 FS
39	1		*LOCK CARRIER	Serviceable	898.00 FS	*- FS
40	4		*READY MIX COOLANT	Serviceable	84.00 FS	*- FS
41	1		*RADIATOR AIR GUIDE - RH	Serviceable	35.00 FS	*- FS
42	1		*FRONT ALUMINIUM RIM - RH	Serviceable	1,128.00 FS	*- FS
43	4		*ALUMINIUM RIM RUBBER VALVE	Serviceable	13.00 FS	*- FS
44	1		*SUNDRIES	Necessary	400.00 FS	*51.04 FS
45	1		*WATER RESERVOIR	Deformed	124.00 FS	*124.00 FS
46	1				19.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*WATER RESERVOIR END CAP (MISSING)	Not Consistent With The Impact		
47	1		*WINDSCREEN WASHER SYSTEM PUMP	Not Working	94.00 FS	*94.00 FS
48	1		*WATER LEVEL SWITCH	Cracked	34.16 FS	*34.16 FS
49	1		*RADIATOR GRILLE	Scratched	1,087.20 FS	*1,087.20 FS
50	1		*FLAT CONTACT HOUSING WITH CONTACT LOCKING MECHANISM	Cracked	22.72 FS	*22.72 FS
51	1		*NO PLATE	Necessary	40.00 FS	*40.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					15,745.08	8,827.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND RENEW AIRCOND CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,200.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	5,250.00	1,750.00
4	TO RESPRAY FRONT BUMPER, BONNET, RHS FRONT FENDER AND HINGES	New	3,200.00	1,650.00
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			10,482.00	3,952.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >