

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI19017939/KQF3S2**Date:** 13/01/2020**REFERENCE**

|                              |   |                             |                           |
|------------------------------|---|-----------------------------|---------------------------|
| Handling Insurer:            | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:                  | DMPCSN3028391900          |
| <b>Claimant Vehicle No :</b> | SLL4846U                                      | <b>Insured Vehicle No :</b> | SJN6977A                  |
| Date of Loss:                | 07/10/2019                                    | Nature of Claim:            | TP                        |
|                              |   | Claim No:                   | SNM19D204742-SJN6977A-TKL |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SLL4846U</b>                   | Engine No:  | CVK023619         |
| Make & Model:               | AUDI A5, 2.0 TFSI MU (A)          | Chassis No: | WAUZZZF5XHA006914 |
| Reg. Date:                  | 27/02/2017 (Man. Year: 2016)      | Odometer:   | 38478 km          |
| Colour:                     | Metallic Grey                     |             |                   |
| Engine Capacity:            | 1984 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |      |                         |     |                          |     |
|--------------------------|------|-------------------------|-----|--------------------------|-----|
| General Condition:       | Good | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes  | Engine Modification:    | No  | Pre-accident Condition:  |     |

**CONDITION OF TYRES**

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 255/35 ZR19      | Rear Tyre Size:  | 255/35 ZR19      |
| Front Left Side:  | Continental 6 mm | Rear Left Side:  | Continental 7 mm |
| Front Right Side: | Continental 6 mm | Rear Right Side: | Continental 7 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                    | 4,416.30          | 3,304.80          | 1,111.50          | 25.17         |
| Miscellaneous Items      | 0.00              | 0.00              | 0.00              |               |
| Labour                   | 2,400.00          | 720.00            | 1,680.00          | 70.00         |
| Paintwork Labour         | 0.00              | 0.00              | 0.00              |               |
| Towing                   | 0.00              | 0.00              | 0.00              |               |
| <b>Nett Amount (S\$)</b> | <b>6,816.30</b>   | <b>4,024.80</b>   | <b>2,791.50</b>   | <b>40.95</b>  |

**INSPECTION**

|                             |            |               |  |
|-----------------------------|------------|---------------|--|
| Date of Assignment:         | 15/10/2019 |               |  |
| Date Inspected:             | 25/10/2019 | Inspected At: | Chuan Ho Auto Service<br>160 Sin Ming Drive #07-09 Autobay<br>Singapore 575721 |
| Estimated Period of Repair: | 3.0 days   |               |  |

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |  |   |
|----------------------|--|---|
| <b>Part Source:</b>  | MRM-SG   | Version: 1.0 (Last Synchronised: 13 Jan 2020)             |
| <b>Parts:</b>        | M1-COUPE   | AUDI A5 2.0 TFSI MU (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's   | (Price-denominated Standard List)                         |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SLL4846U)  |   |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |   |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.   |   |

### Recommended Parts

| No. | Qty | Part No. | Particulars                  | Condition        | Repairer's   | Amount                   |
|-----|-----|----------|------------------------------|------------------|--|--------------------------|
| 1   | 1   |          | *REAR BUMPER                 | Buckled / Dented | 2,128.00 FL  | *2,128.00 FL             |
| 2   | 1   |          | *REAR BUMPER SILVER MOULDING | Cracked          | 434.00 FL  | *434.00 FL               |
| 3   | 1   |          | *REAR BUMPER REFLECTOR LH    | Cracked          | 55.00 FL   | *55.00 FL                |
| 4   | 1   |          | *SET REAR EXHAUST TIP        | Dented           | 550.00 FL  | *455.00 FL               |
| 5   | 1   |          | *REAR BUMPER BRACKET LH      | Serviceable      | 65.00 FL   | -                        |
| 6   | 1   |          | *REAR REINFORCEMENT BAR      | Repair           | 850.00 FL  | *- FL                    |
| 7   | 1   |          | *REAR BUMPER DIFFUSER        | Cracked          | 600.00 FL  | *600.00 FL               |
| 8   | 1   |          | *REAR BUMPER SENSOR SEAL LH  | Not Necessary    | 15.00 FL   | *- FL                    |
| 9   | 1   |          | *REAR BUMPER SENSOR LH       | Serviceable      | 210.00 FL  | *- FL                    |
|     |     |          |                              |                  | <b>Sub Total (\$\$)</b>                                    | <b>4,907.00 3,672.00</b> |
|     |     |          |                              |                  | <b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b> | <b>490.70 367.20</b>     |
|     |     |          |                              |                  | <b>Total Parts (\$\$)</b>                                  | <b>4,416.30 3,304.80</b> |

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                              | Particulars   | Lab.Type | Repairer's      | Amount        |
|---------------------------------|---|----------|-----------------|---------------|
| <b>Labour Items</b>             |   |          |                 |               |
| 1                               | ANTI RUST PROOFING, GALVANISING SPOT WELD.                              | New      | 300.00          | 0.00          |
| 2                               | TO CHECK LIGHTING, WIRING & FUSES.                                      | New      | 300.00          | 20.00         |
| 3                               | LABOUR TO DISMANTLE, REPAIR, REPLACE PARTS AND ALIGN.                   | New      | 800.00          | 300.00        |
| 4                               | TO PUTTY, PRIMER, SPRAY PAINT REAR BUMPER, REAR DIFFUSER AND END PANEL. | New      | 1,000.00        | 400.00        |
| <b>Gross Labour Cost (\$\$)</b> |   |          | <b>2,400.00</b> | <b>720.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >