

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG19017949/ABA3Q2

**Date:** 11/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

#### Claimant

**Vehicle No :** SFS2829S

**Insured Vehicle No :** GBC6077A

**Date of Loss:** 01/10/2019

**Nature of Claim:** TP

**Claim No:** 1530515027SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

**Reg No:** SFS2829S

**Make & Model:** BMW 530I, 2.0 LED NAV (A)

**Engine No:** 11799973B48B20B

**Reg. Date:** 28/06/2017 (Man. Year: 2017)

**Chassis No:** WBAJA52010WA34697

**Colour:** Silver

**Odometer:** 29591 km

**Engine Capacity:** 1998 cc

**Market Value/New Car**

**Price:** N/A

**Sum Insured (\$):** **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

**General Condition:** Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes

**Handbrake (Serviceable):** Yes **Engine Modification:** No **Pre-accident Condition:**

### CONDITION OF TYRES

**Front Tyre Size:** 245/40 R19

**Rear Tyre Size:** 245/40 R19

**Front Left Side:** Michelin 6 mm

**Rear Left Side:** Michelin 6 mm

**Front Right Side:** Michelin 6 mm

**Rear Right Side:** Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	16,506.44	10,912.32	5,594.12	33.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,150.00	1,390.00	760.00	35.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$)</b>	<b>18,656.44</b>	<b>12,302.32</b>	<b>6,354.12</b>	<b>34.06</b>
<b>Approved Total (Overridden) (\$)</b>		<b>9,800.00</b>		
<b>Nett Amount (\$)</b>	<b>18,656.44</b>	<b>9,800.00</b>	<b>8,856.44</b>	<b>47.47</b>
<b>+ Loss of Use (7.0 x S\$180.00/day) (\$)</b>		1,260.00		
<b>+ Doc/Search Fee (\$)</b>		7.45		
<b>Nett Liability (\$)</b>		<b>11,067.45</b>		
<b>Global Sum Settlement (\$)</b>		<b>10,600.00</b>		

### INSPECTION

**Date of Assignment:** 10/10/2019

**Date Inspected:** 10/10/2019 Inspected At:

Chin Meng Motors (HQ)  
1 Kaki Bukit Ave 6 #01-40/63, Autobay  
@ Kaki Bukit  
Singapore 417883

**Estimated Period of Repair:** 6.0 days

**Adjuster:** ADRIAN LING**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT	Dented	2,450.60 FL	*2,450.60 FL
2	1		*BOOT EMBLEM -LOGO	Necessary	71.25 FL	*71.25 FL
3	1		*BOOT EMBLEM -530I	Necessary	66.80 FL	*66.80 FL
4	2		*BOOT HINGES	Not Necessary	237.60 FL	*- FL
5	2		*BOOT DAMPER	Not Necessary	970.00 FL	*- FL
6	1		*BOOT INNER LOCK	Not Necessary	385.00 FL	*- FL
7	1		*BOOT INSULATOR	Not Necessary	229.50 FL	*- FL
8	8		*BOOT INSULATOR CLIPS	Not Necessary	40.00 FL	*- FL
9	3		*BOOT STOPPERS	Not Necessary	80.10 FL	*- FL
10	2		*BOOT LAMPS	Not Necessary	979.00 FL	*- FL
11	2		*BOOT SIDE GARNISH	Not Necessary	131.60 FL	*- FL
12	1		*BOOT WEATHERSTRIP	Not Necessary	216.50 FL	*- FL
13	2		*BOOT NO .PLATE LAMPS	Not Necessary	50.80 FL	*- FL
14	2		*TAILLAMPS	Cracked	1,575.00 FL	*1,575.00 FL
15	2		*TAILLAMP CLIP	Necessary	25.00 FL	*25.00 FL
16	2		*TAILLAMP SIDE GARNISH	Not Necessary	131.80 FL	*- FL
17	1		*REAR BUMPER	Deformed	1,852.20 FL	*1,852.20 FL
18	1		*REAR BUMPER REINFORCEMENT	Bent	857.75 FL	*857.75 FL
19	1		*REAR BUMPER CHROME	Cracked	356.80 FL	*356.80 FL
20	2		*REAR BUMPER SIDE BRACKETS	Not Necessary	267.00 FL	*- FL
21	2		*REAR BUMPER SIDE RETAINERS	Necessary	291.00 FL	*291.00 FL
22	1		*REAR BUMPER REFLECTORS	O/S Cracked	91.40 FL	*45.70 FL
23	1		*REAR BUMPER TOW COVER	Missing	81.55 FL	*81.55 FL
24	4		*REAR BUMPER PDC SENSOR	Damaged (2 PCS ONLY)	994.80 FL	*452.40 FL
25	6		*REAR BUMPER PDC SENSOR HOLDER	Damaged	142.80 FL	*142.80 FL
26	1		*REAR BUMPER PDC WIREHARNES	Not Necessary	232.85 FL	*- FL
27	1		*REAR BUMPER INNER CENTRE GARNISH	Damaged	168.50 FL	*168.50 FL
28	1		*REAR BUMPER INNER GARNISH (5)	Cracked	188.50 FL	*188.50 FL
29	1		*REAR END PANEL	Repair	1,417.15 FL	*- FL
30	1		*REAR END PANEL GARNISH	Not Necessary	169.80 FL	*- FL
31	1		*REAR EXHAUST OUTER COVER (2 PCS)	Crumpled	185.45 FL	*185.45 FL
32	1		*REAR EXHAUST MUFFLER	Bent	1,658.50 FL	*1,658.50 FL
33	1		*REAR NO .PLATE WITH COVER	Not Necessary	80.00 FS	*- FS
34	1		*BOOT KICK OPEN SENSOR	Damaged	280.00 FL	*280.00 FL
35	1		*BOOT KICK OPEN WIRE HARNESS	Damaged	120.00 FL	*120.00 FL
36	1		*BOOT KICK OPEN CONTROL UNIT	Cracked	650.00 FL	*650.00 FL
37	1		*REAR BUMPER LOWER GARNISH (TOP)	Damaged	180.00 FL	*180.00 FL
38	1		*REAR BUMPER LOWER GARNISH (LOWER)	Damaged	140.00 FL	*140.00 FL
39	1		*EXHAUST SHIELD (CENTRE)	Crumpled	190.00 FL	*190.00 FL
40	1		*EXHAUST SHIELD (R/H)	Crumpled	95.00 FL	*95.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>18,331.60</b>	<b>12,124.80</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	1,825.16	1,212.48
<b>Total Parts (S\$)</b>	<b>16,506.44</b>	<b>10,912.32</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO PANEL BEATING ,WELDING ,REMOVING DAMAGED PARTS AND REPLACEMENT OF THE PARTS AS MENTIONED ABOVE ETC	New	900.00	600.00
2	TO RESPRAY AFFECTED PART	New	1,000.00	600.00
3	TO APPLY UNDERSEAL	New	60.00	0.00
4	TO REMOVE & REFIT REAR REVERSE SENSOR	New	60.00	60.00
5	TO RESET FAULT CODE AFTER REPAIR	New	100.00	100.00
6	TO REMOVE & REFIT OF WIRINGS	New	30.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,150.00</b>	<b>1,390.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >