



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SJU1081E

CLAIM TYPE : THIRD PARTY

TP INS. CO. : AXA INSURANCE SINGAPORE PTE LTD

ACCIDENT DATE : 07/10/2019

TP VEH REG NO : SJU1081E

ESTIMATE

NO : QUOT201910-000026(00)

DATE : 10/10/2019

POLICY NO : 999995580

VEH REG NO : SMC8351P

MAKE/MODEL : MERCEDES BENZ GLA180
URBAN (R18 LED)

CHASSIS NO : WDC1569422J527711

ENGINE NO : 27091031680667

REG. DATE : 2018

Not Authorised
Recovery B4 point

5-7 days

Estimate Repair Cost to Vehicle No : SMC8351P

Description	Quantity	Unit Price	Amount
		S\$	S\$
NET PRICE			
1 Rear end panel	1	920.00	920.00
2 Rear bumper	1	1,260.00	1,260.00
3 Rear bumper top moulding	1	260.00	260.00
4 Rear bumper reinforcement	1	595.00	595.00
5 Rear bumper side retainer - RH / LH	2	45.00	90.00
6 Rear bumper centre inner frame	1	170.00	170.00
7 Rear bumper stiffener	1	67.00	67.00
8 Rear bumper towing cover	1	38.00	38.00
9 Rear bumper sensors	42	188.00	7920.00
10 Rear bumper sensor seals	6	12.00	72.00
11 Rear bumper clips	15	9.00	135.00
12 Rear bumper lower spoiler	1	570.00	570.00
13 Rear bumper lower spoiler clips	10	9.00	90.00
14 Rear bumper lower chrome	1	415.00	415.00
15 Rear safety belt - RH / LH	2	385.00	770.00
16 Rear safety belt top bracket - RH / LH	2	48.00	96.00
17 Rear safety belt lock - RH / LH	2	355.00	710.00
18 Air bag control unit	1	760.00	760.00
			7,770.00
		Less 10%	777.00
			6,993.00
LABOUR			
19 To remove and refix rear bumper sensor	1	100.00	100.00
20 To check and rectify wiring system	1	80.00	80.00
21 To remove and refit both side rear safety belt, rear safety belt lock	1	680.00	680.00
22 To dismantled and refix console box to enable to replace airbag control unit	1	280.00	280.00
23 To panel beat and straighten rear chassis frame, rear floorboard panel, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00
24 To putty and spray paint on affected areas	1	1,200.00	1,200.00
25 To apply rust proofing on repaired and replaced panels	1	160.00	160.00
26 To reprogram air bag control unit and reset all fault code	1	580.00	580.00
			4,080.00



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118 FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SJU1081E

CLAIM TYPE : THIRD PARTY

TP INS. CO. : AXA INSURANCE SINGAPORE PTE LTD

ACCIDENT DATE : 07/10/2019

TP VEH REG NO : SJU1081E

ESTIMATE

NO : QUOT201910-000026(00)

DATE : 10/10/2019

POLICY NO : 999995580

VEH REG NO : **SMC8351P**

MAKE/MODEL : MERCEDES BENZ GLA180
URBAN (R18 LED)

CHASSIS NO : WDC1569422J527711

ENGINE NO : 27091031680667

REG. DATE : 2018

Estimate Repair Cost to Vehicle No : SMC8351P

Description	Quantity	Unit Price	Amount
		S\$	S\$
		TOTAL	S\$ 11,073.00
		ADD GST @ 7%	775.11
		GRAND TOTAL	S\$ 11,848.11

SINGAPORE DOLLAR ELEVEN THOUSAND EIGHT HUNDRED FORTY-EIGHT AND CENTS ELEVEN ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE