



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19017960/Aga3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN:VALE

Date : 27-05-2020



Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SJA 2538D	<b>Veh. Inspected</b>	SLK 551B
<b>Policy No.</b>	GA039007	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S9M0223Z	<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	15/10/2019

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HONDA EDIX	<b>c.c</b>	1998
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2009
<b>Chassis No.</b>	BE31203284	<b>Colour</b>	BLACK
<b>Odometer</b>	142072	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	205/55 R16	PIRELLI	6 mm
<b>L/H Front Tyre</b>	205/55 R16	PIRELLI	6 mm
<b>R/H Rear Tyre</b>	205/55 R16	PIRELLI	6 mm
<b>L/H Rear Tyre</b>	205/55 R16	PIRELLI	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	28/09/2019	<b>Inspection Date</b>	15/10/2019
<b>Survey held at</b>	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**