

ASS. REC. BY:

REF: CS/FCI 17017977 / Ktd3n2

Special Instructions:

Assigner: Kenneth

ASSIGNMENT (Office)

CWS

From (Person): Karen Tan

of

FCI

Date/Time: 12/31 PM 11/10/2011

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SLJ 1211G

Insured:

SHA 7956X

at Workshop m/s

Complete XMS

Tel:

61550012

of

176 Sin Ming Drive # 03-14

Policy No:

Claim No:

D19006509MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 9/10/11

(Client's Record)

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endowment:

Date/Time: 24/2 PM 11/10/11

Person Contacted:

Lily

Vehicle: IN/OUT

Date/Time

Action/Instruction

12/10/11

SHA 7956X : CC3/AT3/12/16/13/12/13/3F3XX DCA 16/05/2012

SLJ 1211G : X

2/10@3:43pm - Revised via email prevli advise

Partby Part \$2534.82 (Red: 2595.23 ; 50%)

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 8 Pdk

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLJ 12116 Yr Regn: 11, 16Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy / Harrier cc 1986Colour: M. Black AC: Insured / Std / NI / NASp. Reading: 58385 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ES460 / 0087200Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Yoko 225/65R17R: mic

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 9/10/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear

R/Bal. 3 mmL/Bal. 3 mmD.O.I. 11/10/19

Survey held at

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 / File pass to

RECEIVED 8 NOV 2019

Date/Time, File Pass to?

11/11 Typist

Date/Time, File Return to?

☐ Prel. Report☒ Final ReportDays Of Repair: 4

Resurvey No. of Trip: _____

Survey Fee:

Transportation

S - RS - SI

Fees

Others

TOTAL

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech Invs (\$☐ Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

Tp
2534.82

140
50
50130
21
311



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: D19006509MFSH

Date: 21/10/2019

Our Ref: CS/FCI19017979/Ktd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLJ 1211G

Please be informed that we had conducted the inspection of the abovementioned vehicle
21/10/2019 at the premises of M/s Complete Vms have the following to report: -

Workshop Estimate Amount	: S\$ <u>5,130.05</u>
Revised Estimate Amount	: S\$ <u>2,444.42</u>
"Check" Items Amount	: S\$ <u>2,105.40</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the
rear parts.



Comments/ Present Status:

Damages Consistent.

Yours faithfully,

Kenneth

Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	10-10-2019	Our Ref No. D19006509MFSH
Accident Date	09-10-2019	Claim Type. Third Party
Insured Vehicle	SHA7956X	Third Party Vehicle. SLJ1211G
Survey Location	176 SIN MING DRIVE #03-14SIN MING AUTOCARE COMPLEX	
Contact Person.	LILY/LI HUI (TEL: 64539622)	
Contact No.	64550012/ 0	Fax No. 65540012
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	COMPLETE VMS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Monday, 21 October 2019 3:43 PM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D19006509MFSH/1
Attachments: PRELI ADVISED OF SLJ 1211G.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLJ 1211G**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Friday, 11 October 2019 2:59 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19006509MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 11 October 2019 12:34 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19006509MFSH/1

Dear Sir/Mdm,



Kt

COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

FARIDAH BINTE KUDIN
10 WESTWOOD DRIVE
SINGAPORE 648828

Attention : THE OWNER
Contact : 91130921

Not Notion
H.P. B2000
Rear Area Paint
82534.82

Estimate : ES006813

Date : 10/10/2019
Vehicle Num. : SLJ1211G
Make/Model : TOYOTA HARRIER 2.0A-2016
Chassis/Eng# : ZSU600087200/3ZRB864070
Accident Date : 09/10/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

		LIST ITEMS :	1343
1.	1	REAR BUMPER	
2.	6	REAR BUMPER CLIP	
3.	1	REAR BUMPER REINFORCEMENT	
4.	1	REAR BUMPER SPONGE	
5.	1	REAR BUMPER SIDE RETAINER L/H	
6.	1	REAR BUMPER LOWER LIP	389.60
7.	1SET	REVERSE SENSOR	
8.	1	REAR END PANEL	
9.	2	REAR BUMPER REFLECTOR	

List Total S\$:
25.00% Discount S\$:

Bu	1,495.30	✓
6.50	39.00	✓
R	325.10	X
CRA	167.80	✓
DIT	93.70	✓
ND	655.20	✓
ND	280.00	✓
R	751.30	X
163.00	326.00	X
		4,133.40
		1,033.35
		3,100.05

LABOUR :
RUST PROOFING TREATMENT
SPRAY PAINT DAMAGED AREA AFFECTED
TO KNOCK TAIL GATE, CUT OFF REAR END PANEL AND CHANGE
ALL NECESSARY PARTS

Labour Total S\$:

ND	100.00	X
	980.00	400
	950.00	400
		2,030.00

SingDollars : Five Thousand One Hundred Thirty & Cents Five Only

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Total S\$: 5,130.05



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

FARIDAH BINTE KUDIN
10 WESTWOOD DRIVE
SINGAPORE 648828

Attention : THE OWNER
Contact : 91130921

*Not Authorized
Lily Bt
Recovery After Paint*

Estimate : ES006813

Date : 10/10/2019
Vehicle Num. : SLJ1211G
Make/Model : TOYOTA HARRIER 2.0A-2016
Chassis/Eng# : ZSU600087200/3ZRB864070
Accident Date : 09/10/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BUMPER		1,495.30
2.	6	REAR BUMPER CLIP	6.50	39.00
3.	1	REAR BUMPER REINFORCEMENT		325.10
4.	1	REAR BUMPER SPONGE		167.80
5.	1	REAR BUMPER SIDE RETAINER L/H		93.70
6.	1	REAR BUMPER LOWER LIP		655.20
7.	1SET	REVERSE SENSOR		280.00
8.	1	REAR END PANEL		751.30
9.	2	REAR BUMPER REFLECTOR	163.00	326.00
List TotalS\$:				4,133.40
25.00% Discount S\$:				1,033.35
				3,100.05
LABOUR :				
RUST PROOFING TREATMENT				100.00
SPRAY PAINT DAMAGED AREA AFFECTED				980.00
TO KNOCK TAIL GATE,CUT OFF REAR END PANEL AND CHANGE				
ALL NECESSARY PARTS				950.00
Labour Total S\$:				2,030.00

SingDollars : Five Thousand One Hundred Thirty & Cents Five Only

Total S\$: 5,130.05

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun

LKK Auto Consultants hereby notify the Repairs of the following:
• To remove blemishes, spray painting
• To replace, damaged part(s) during recovery
• Parts prices are subject to confirmation
• No work will be carried out without "Without Prejudice" case
• Goods received by the customer to be signed and
to be signed by the insurance company

Authorized Person
Signature
Date



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19017979/Kid3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 12-11-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7956X	Veh. Inspected	SLJ 1211G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19006509MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	11/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HARRIER (A)	c.c	1986	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	ZSU600087200	Colour	METALLIC BLACK	
Odometer	58385	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/65 R17	YOKOHAMA	7 mm	
L/H Front Tyre	225/65 R17	YOKOHAMA	7 mm	
R/H Rear Tyre	225/65 R17	MICHELIN	3 mm	
L/H Rear Tyre	225/65 R17	MICHELIN	3 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/10/2019	Inspection Date	11/10/2019	
Survey held at	COMPLETE VMS PTE LTD BLK 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX SINGAPORE 575721			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 1211G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	BUCKLED	1,495.30	1,343.00
6	REAR BUMPER CLIP @\$6.50	NECESSARY	39.00	39.00
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	325.10	-
1	REAR BUMPER SPONGE	CRACKED	167.80	167.80
1	REAR BUMPER SIDE RETAINER L/H	DISTORTED	93.70	93.70
1	REAR BUMPER LOWER LIP	DENTED	655.20	389.60
1	SET REVERSE SENSOR	DENTED	280.00	280.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	751.30	-
2	REAR BUMPER REFLECTOR @\$163.00	SERVICEABLE	326.00	-
	LESS 25% DISCOUNT		-1,033.35	-578.28
			3,100.05	1,734.82
	LABOUR			
	RUST PROOFING TREATMENT.	NOT NECESSARY	100.00	-
	SPRAY PAINT DAMAGED AREA AFFECTED.		980.00	400.00
	TO KNOCK TAIL GATE,CUT OFF REAR END PANEL AND CHANGE ALL NECESSARY PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT.		950.00	400.00
			2,030.00	800.00
	GRAND TOTAL		5,130.05	2,534.82
	RECOMMENDED COST OF REPAIRS			2,534.82

Report Ref No. CS/FCI19017979/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.