

ASS. REC. BY:

REF: CS/FCI 19018036/Ktf3/n2

Special Instruction:

Survivor: Kenneth

ASSIGNMENT (Office)

From (Person): Joanny of fcl Date/Time: 14.10.19 12.50 p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGT 9921 V Insured: SHD 3417 x

at Workshop m/s Accord Auto Tel: 97400999

of 10 Annk Industrial Park 2A Annk Auto Point #03-11

Policy No: Claim No: D19006529MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 10.10.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 14.10.19 10.09 p.m Person Contacted: Wat Ping H.O.D. Endorsement:

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SGT 9921 V - x
	SHD 3417 x - CS/FCI 19005450/Hbn) R.O.A - 16/03/2017
18/10	L1 Lyp @ 1700p email & confirm (Red: 3746.64; 68%)

ASS. REQ. BY:

REF: FCL

ASSIGNMENT

From: _____ Date: 15.10.2019

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SGT 9921U

at Workshop m/s: Accord Auto

of 10 Amk Indusam/ Park 2A #03-11 Autopoint

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: After 11.00 a.m

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 841k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 3/27 Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGT 9921U

Yr Regn: 04, 07

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Dai

A/Copen

c.c

659

Colour: Red

A/C: Insured / Std / NI / NA

Sp. Reading: 88/22

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: L 880k

0030287

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 165/50R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Palken

Front

Rear

R/Bal. 9 mm

R/Bal. 9 mm

L/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 10/10/19

D.O.L. 15/10/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or +

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV: 841,000/-

CTA: 37570/-

NV: 3430/-

RECEIVED 23 OCT 2019

Date/Time, File Pass to?

☐

Preli. Report

1) 23/10 Typist

☐

Final Report

Date/Time, File Return to?

2)

Report Form:

Lump Sum / I.E.I. /

Tp

1700/-

Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

140

50

50

16

256

MOTOR SURVEY ASSIGNMENT

Date	11-10-2019	Our Ref No. D19006529MFSH
Accident Date	10-10-2019	Claim Type. Third Party
Insured Vehicle	SHD3417X	Third Party Vehicle. SGT9921U
Survey Location	10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTO POINT #03-11	
Contact Person.	WAI PING	
Contact No.	64819517/ 97400999	Fax No. 64819516
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ACCORD AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	474G
Vehicle Details	
Vehicle No.:	SGT9921U
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Oct 2019
Vehicle Make:	DAIHATSU
Vehicle Model:	COPEN 660 A
Primary Colour:	Red
Manufacturing Year:	2007
Engine No.:	JB0368647
Chassis No.:	L880K0038207
Maximum Power Output:	47.0 kW (63 bhp)
Open Market Value:	\$15,264.00
Original Registration Date:	27 Apr 2007
First Registration Date:	27 Apr 2007
Transfer Count:	2
Actual ARF Paid:	\$16,791.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2027
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$49,429.00
COE Rebate Amount:	\$37,570.00
Total Rebate Amount:	\$37,570.00

The information contained herein is correct as at 23 Oct 2019

OK

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

MS First Capital Insurance Ltd

36 Robinson Road,

#16-01 City House

Singapore 068877

Attn: Claim Dept

Not Notarised
21 Sep @ 1700h
Runny After Rain
3 days

Date : 10.10.2019
Vehicle No : SGT 9921 U
Veh Make/Model : Daihatsu Copen
YOM : 2007
Chassis No : L880K0038207
Date of Accident : 10.10.2019

No	Qty	Description	Amount S
		<u>List Items:-</u>	
1	1	Front headlamp (RH)	\$ 590.00 ✓
2	1	Front headlamp bracket (RH)	\$ 620.95 X
3	1	Front fender (RH)	\$ 422.75 X
4	1	Front fender shield (RH)	\$ 530.00 X
5	set	Front fender shield clips (RH)	\$ 50.00 X
6	1	Front bumper	\$ 739.16 ✓
7	1	Front bumper side retainer (RH)	\$ 363.15 X
8	set	Front bumper clips	\$ 50.00 ✓
9	1	Front grille top, centre & lower (together)	\$ 486.76 X
10	1	Front foglamp (RH)	\$ 475.10 X
11	1	Front foglamp bracket	\$ 98.06 X
12	1	Front number plate garnish	\$ 76.00 X
13			\$ -
14			\$ -
15			\$ -
16			\$ -
17			\$ -
18			\$ -
19			\$ -
20			\$ -
21			\$ -
22			\$ -
23			\$ -
24			\$ -
25			\$ -
26			\$ -
27			\$ -
28			\$ -
29			\$ -
30			\$ -
Total - List Item			\$ 4,501.93
Less 15%			\$ 675.29
Total			\$ 3,826.64

Balance c/f

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Date :	10.10.2019
Vehicle No :	SGT 9921 U
Veh Make/Model :	Daihatsu Copen
YOM :	2007
Chassis No :	L880K0038207
Date of Accident :	10.10.2019

Date :	10.10.2019
Vehicle No :	SGT 9921 U
Veh Make/Model :	Daihatsu Copen
YOM :	2007
Chassis No :	L880K0038207
Date of Accident :	10.10.2019

550
400
200
x



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19018036/Ktf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 25-10-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SHD 3417X	Veh. Inspected
			SGT 9921U
	Policy No.		Coverage (\$)
			0.00
	Claim No.	D19006529MFSH	Excess (\$)
			0.00
	Assign From	JOANNE YONG	Assign Date
			14/10/2019
2. Vehicle Particulars & Condition			
	Make & Model	DAIHATSU COPEN (A)	c.c
			659
	Engine No.	HIDDEN	Year of Reg.
			2007
	Chassis No.	L880K0038207	Colour
			RED
	Odometer	88122	Steering
			IN ORDER
	Brakes	IN ORDER	Modification
			SPORTS RIM
	General	GOOD	
3. Conditions of Tyres			
		Size	Make
			Balance
	R/H Front Tyre	165/50 R15	FALKEN
			9 mm
	L/H Front Tyre	165/50 R15	FALKEN
			9 mm
	R/H Rear Tyre	165/50 R15	FALKEN
			9 mm
	L/H Rear Tyre	165/50 R15	FALKEN
			9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
	Accident Date	10/10/2019	Inspection Date
			15/10/2019
	Survey held at	ACCORD AUTO SERVICES PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTO POINT #03-11 SINGAPORE 568047	
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGT 9921U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT HEADLAMP (RH)	CRACKED	590.00	590.00
1	FRONT HEADLAMP BRACKET (RH)	SERVICEABLE	620.95	-
1	FRONT FENDER (RH)	TO REPAIR SEE LABOUR	422.75	-
1	FRONT FENDER SHIELD (RH)	SERVICEABLE	530.00	-
1	SET FRONT FENDER SHIELD CLIPS (RH)	NOT NECESSARY	50.00	-
1	FRONT BUMPER	MTG CRACKED	739.16	739.16
1	FRONT BUMPER SIDE RETAINER (RH)	SERVICEABLE	363.15	-
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	FRONT GRILLE TOP,CENTRE & LOWER (TOGETHER)	SERVICEABLE	486.76	-
1	FRONT FOG LAMP (RH)	SERVICEABLE	475.10	-
1	FRONT FOG LAMP BRACKET	SERVICEABLE	98.06	-
1	FRONT NUMBER PLATE GARNISH	SERVICEABLE	76.00	-
	LESS 15% DISCOUNT		-675.29	-206.87
			3,826.64	1,172.29
	LABOUR			
	SPRAY PAINTING ON ALL AFFECTED AREA.		600.00	550.00
	LABOUR REMOVE/REFIX ACCIDENT DAMAGES PARTS TO KNOCK,JACK,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA.INCLUSIVE OF THE REPAIR OF FRONT FENDER (RH).		800.00	400.00
	CHECK WIRING SYSTEM & LIGHT.		100.00	20.00
	ANTI RUST TREATMENT.	NOT NECESSARY	120.00	-
			1,620.00	970.00
	GRAND TOTAL		5,446.64	2,142.29
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,700.00

Report Ref No. CS/FCI19018036/Ktf3n2

MARKET VALUE: \$41,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$37,570.00=NETT VALUE: \$3,430.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.