

ASS. REC. BY:

REF:

CS/LR 190180431/Ky362

Special Instructions:

Surveyor Kenneth

ASSIGNMENT (Office)

From (Person): Kenny Lim

of

LPC

Date/Time: 14.10.19 12.17p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKV 5907E

Insured:

at Workshop m/s K. Tim Hin

Tel:

64527018

160 Sin Ming Drive #02-20

89400219

Policy No: 2/19/VP05/024317-001

Claim No: 19119/19/VP05/02478

Sum Insured:

Excess: \$4000.00

Make of Veh:

D.O.A. 6.10.2019

(Client's Record)

CA (REV) / REP. / REV 24 HRS

97172631 Simon

H.O.D. Endorsement:

Date/Time: 14.10.19 1.23p.m

Person Contacted:

Sandra

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKV 5907E: X
14/10/19	@ 18:00 pm revised PA to Kenny via email.

REF: LFC

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

16 days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Colour: _____

Sp. Reading: _____

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. _____

L/Bal. _____

D.O.A. _____

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 /

File pass to

16/10/19

Lompac Kenny said total loss

10/10/19

Already inform workshop total loss 17/10/19 Submit Uncommical + total loss

MV = \$71,000

LTA = \$43,804

Nett = \$27,196

18/10/19

Approval. Mandate by Chau Beng Lee

Excess \$4000

not exceeding

17/10/19

Lompac Kenny said Owner and Workshop will do undertake the repair \$17k

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum I.B.I. (\$

\$17,000

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee: _____

Transportation: _____

S + RS \$

Fees

Others

TOTAL

240

11

361

RECEIVED 15 MAR 2020

...CLAIM SUBFOLDER...(Pending for Approval)

IN
OD Longac

CLAIM SUBFOLDER TRACKING

Case	Created	Emergency	Est. Submitted	Est. Assigned	Est. Auth. est.	Status
Main	11 Oct 2019 14:55		12 Oct 2019 12:36 S\$49,897.98			Pending for Approval

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	BUJUNG, ID: S2692330A		
Vehicle Reg. No.:	SKV5907E	Date of Loss:	06/10/2019 09:00 - :59 [48 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD	Policy/Cover Note No.:	Z/19/VP05/024317-001 (Comprehensive)
		Excess:	
Repairer:	K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018		
Handling Insurer:	Lonpac Insurance Bhd (HQ) - Tel: +65 62507388		
Driver/Custodian:	DAVID IMANUEL TANAKA (25 / Male), NRIC: S9472201B, Tel: +6594887713 Email: T.DAVID9424@GMAIL.COM		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Friday, October 18, 2019 1:24 PM
To: Simon; SUR
Cc: KKH; JEROME KKH; Survey KKH
Subject: SKV 5907E OD (LPC) DOA - 06/10/2019
Attachments: UNDERTAKING.pdf

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle SKV5907E (**excess \$4000/-**).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

LUMP SUM REPAIR COST NOT EXCEEDING \$17,000.00

Please sign the undertaking letter attach and sent to me.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonne.wong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Simon [mailto:simon@kkimhin.com.sg]
Sent: Wednesday, October 16, 2019 10:01 AM
To: SUR <sur@lkkauto.com>
Cc: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; KKH <service@kkimhin.com.sg>; JEROME KKH <survey2@kkimhin.com.sg>; Survey KKH <survey@kkimhin.com.sg>
Subject: SKV 5907E OD (LPC) DOA - 06/10/2019

Dear Shirley,

We would like to request lump sum basis \$20,000.00

Hope to hear from you soon.

Regards
Simon
64527018
K. Kim Hin Auto Pte Ltd

From: service@kkimhin.com.sg
Sent: Monday, October 14, 2019 6:34 PM
To: simon@kkimhin.com.sg ; survey2@kkimhin.com.sg ; survey@kkimhin.com.sg
Cc: ShirleyHiew@lkkauto.com
Subject: FW: SKV 5907E OD (LPC) DOA - 06/10/2019

Simon, pls refer to email for LKK and reply.

Thanks & Regards
Sandra
6452 7018
9622 2116
K. Kim Hin Auto Pte Ltd

----- Forwarded message -----

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Date: Mon, Oct 14, 2019 at 4:32 PM
Subject: SKV 5907E OD (LPC) DOA - 06/10/2019
To: sandrakhong@gmail.com <sandrakhong@gmail.com>
Cc: SUR <sur@lkkauto.com>

Dear Sandra,

Kindly check the repair cost limit whether you are able to repair the vehicle not exceeding \$ 17,000.00 on lump sum basis.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

TO: LONPAC INSURANCE BHD

CLAIM NO:19/19/19/VP05/022478

WITHOUT PREJUDICE

LETTER OF UNDERTAKING

FOR THE REPAIR OF VEHICLE NO. SKV5907E

We, the undersigned, confirm that we will undertake to repair the vehicle bearing Registration No **SKV5907E** to its pre-accident condition, and to the satisfaction of its owner, at a total cost not exceeding LUMP SUM **17,000.00** (before excess) subject to no breach of Terms & Condition of the POLICY, and to the legal requirement of the local Land Transport Authority (LTA).

There should be **no further supplementary** to the repair cost.

Date

Workshop Stamp/ Signature

Date

Witness by surveyor

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse
Singapore 199555

Our File No: CS/LPC19018043/KYF3
Date: 17/10/2019

REFERENCE

Insured/Claimant: BUJUNG Policy No: Z/19/VP05/024317-001
Date of Loss: 06/10/2019 Nature of Claim: OD Claim No: 19/19/19/VP05/022478

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKV5907E**
Make & Model: CITROEN GRAND C4 PICASSO, 1.6 D e-HDi ETG6 Engine No: 10JBEX3057402
Halogen (A)
Reg. Date: 25/09/2015 (Man. Year: 2015) Chassis No: VF73A9HC8FJ657983
Colour: Silver Odometer: 0 km
Engine Capacity: 1560 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: Rear Tyre Size:
Front Left Side: 0 mm Rear Left Side: 0 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	43,967.98	43,967.98	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,930.00	5,930.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	49,897.98	49,897.98	0.00	0.00
- Excess (S\$)	0.00	4,000.00	-4,000.00	
(S\$)	49,897.98	45,897.98	4,000.00	8.02
+ GST 7.00/7.00% (S\$)	3,492.86	3,212.86	280.00	8.02
Nett Amount (S\$)	53,390.84	49,110.84	4,280.00	8.02

INSPECTION

Date of Assignment: 14/10/2019 Present Location: K Kim Hin Auto Pte Ltd (HQ)
K Kim Hin Auto Pte Ltd (HQ)
Date Inspected: 14/10/2019 Inspected At: 160 Sin Ming Drive #02-20, Sin Ming AutoCity
Singapore 575722
Estimated Period of Repair: 16.0 days

Adjuster: KENNETH KONG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

TOTAL LOSS ASPECT

Market Value :	\$71,000.00
OMV :	\$25,827.00
PARE Rebate (1) :	\$9,868.00
Quota Premium Paid :	\$57,089.00
COE Rebate (2) :	\$33,936.00
Total Rebate (1) + (2) = :	\$43,804.00

The total amount incurred will be Market Value \$71,000.00 minus Total Rebate \$43,804.00 = \$27,196.00

In view of the above, the vehicle is uneconomical to be repaired.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Kenny Lim

Date: 17 Oct 2019

Preliminary Advice

Vehicle No	: SKV5907E	Accident Date	: 06/10/2019
Make	: CITROEN GRAND C4 PICASSO	Policy No.	: Z/19/VP05/024317-001
Assignment Date	: 14/10/2019	Excess	: S\$4,000.00
Date of Inspection	: 14/10/2019	Est. Duration of Repair	: 16.00
Inspection At	: K KIM HIN AUTO PTE LTD (HQ) 160 SIN MING DRIVE #02-20, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	49,897.98
Revised Amount	:S\$	31,629.97
Check Items (Estimated)	:S\$	8,143.00
Total	:S\$	39,772.97
Lump Sum Repair	:S\$	17,000.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	61,000.00
COE / PARF Rebate	:S\$	43,804.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,196.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments The repairer able undertake lump sum not exceeding \$17,000.00.:

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Kenny Lim

Date: 17 Oct 2019

Preliminary Advice

Vehicle No	: SKV5907E	Accident Date	: 06/10/2019
Make	: CITROEN GRAND C4 PICASSO	Policy No.	: Z/19/VP05/024317-001
Assignment Date	: 14/10/2019	Excess	: S\$4,000.00
Date of Inspection	: 14/10/2019	Est. Duration of Repair	: 16.00
Inspection At	: K KIM HIN AUTO PTE LTD (HQ) 160 SIN MING DRIVE #02-20, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	49,897.98
Revised Amount	:S\$	31,629.97
Check Items (Estimated)	:S\$	8,143.00
Total	:S\$	39,772.97
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	61,000.00
COE / PARF Rebate	:S\$	43,804.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,196.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to total loss.
- () Other comments :

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Kenny Lim

Date: 16 Oct 2019

Preliminary Advice

Vehicle No	: SKV5907E	Accident Date	: 06/10/2019
Make	: CITROEN GRAND C4 PICASSO	Policy No.	: Z/19/VP05/024317-001
Assignment Date	: 14/10/2019	Excess	: S\$4,000.00
Date of Inspection	: 14/10/2019	Est. Duration of Repair	: 16.00
Inspection At	: K KIM HIN AUTO PTE LTD (HQ) 160 SIN MING DRIVE #02-20, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	49,897.98
Revised Amount	:S\$	31,629.97
Check Items (Estimated)	:S\$	8,143.00
Total	:S\$	39,772.97
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	61,000.00
COE / PARF Rebate	:S\$	43,804.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,196.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The repairer able undertake lump sum not excess \$20,000.00

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Kenny Lim

Date: 14 Oct 2019

Preliminary Advice

Vehicle No	: SKV5907E	Accident Date	: 06/10/2019
Make	: CITROEN GRAND C4 PICASSO	Policy No.	: Z/19/VP05/024317-001
Assignment Date	: 14/10/2019	Excess	: S\$4,000.00
Date of Inspection	: 14/10/2019	Est. Duration of Repair	: 16 days
Inspection At	: K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity Singapore 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident. The undercarriage affected due to collision.

Repairer's Estimate (Gross)	:S\$	49,897.98
Revised Amount	:S\$	31,629.97
Check Items (Estimated)	:S\$	8,143.00
Total	:S\$	39,772.97
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	61,000.00
COE / PARF Rebate	:S\$	43,804.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,196.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We are pending repair cost from repairer.

Yvonne Wong (LKK Auto)

From: Simon <simon@kkimhin.com.sg>
Sent: Wednesday, October 16, 2019 10:01 AM
To: SUR
Cc: Shirley Hiew (LKK Auto); KKH; JEROME KKH; Survey KKH
Subject: SKV 5907E OD (LPC) DOA - 06/10/2019

Dear Shirley,

We would like to request lump sum basis \$20,000.00
Hope to hear from you soon.

Regards
Simon
64527018
K. Kim Hin Auto Pte Ltd

From: service@kkimhin.com.sg
Sent: Monday, October 14, 2019 6:34 PM
To: simon@kkimhin.com.sg ; survey2@kkimhin.com.sg ; survey@kkimhin.com.sg
Cc: ShirleyHiew@lkkauto.com
Subject: FW: SKV 5907E OD (LPC) DOA - 06/10/2019

Simon, pls refer to email for LKK and reply.

Thanks & Regards
Sandra
6452 7018
9622 2116
K. Kim Hin Auto Pte Ltd

----- Forwarded message -----

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Date: Mon, Oct 14, 2019 at 4:32 PM
Subject: SKV 5907E OD (LPC) DOA - 06/10/2019
To: sandrakhong@gmail.com <sandrakhong@gmail.com>
Cc: SUR <sur@lkkauto.com>

Dear Sandra,

Kindly check the repair cost limit whether you are able to repair the vehicle not exceeding \$ 17,000.00 on lump sum basis.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

FW: SKV 5907E OD (LPC) DOA - 06/10/2019

service@kkimhin.com.sg

Mon 14/10/2019 6:34 PM

To: simon@kkimhin.com.sg <simon@kkimhin.com.sg>; survey2@kkimhin.com.sg <survey2@kkimhin.com.sg>; survey@kkimhin.com.sg <survey@kkimhin.com.sg>

Cc: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Simon, pls refer to email for LKK and reply.

Thanks & Regards

Sandra

6452 7018

9622 2116

K. Kim Hin Auto Pte Ltd

----- Forwarded message -----

From: **Shirley Hiew (LKK Auto)** <ShirleyHiew@lkkauto.com>

Date: Mon, Oct 14, 2019 at 4:32 PM

Subject: SKV 5907E OD (LPC) DOA - 06/10/2019

To: sandrakhong@gmail.com <sandrakhong@gmail.com>

Cc: SUR <sur@lkkauto.com>

Dear Sandra,

Kindly check the repair cost limit whether you are able to repair the vehicle not exceeding \$ 17,000.00 on lump sum basis.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail

Account No

S1000003/ICCI1

Document No

0

Document Date

08/10/2019

Customer Detail

Mr Ng Eng Teck
370H Alexandra Road
#06-07 The Anchorage
Singapore 159961

Mobile: 96511111

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	AEKGB S1	AXEH10R	22/01/2019	SMH3997H	0	17782	40D/SMH3997H/07101
Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On		
JTHB21B1802019526	A25AS098998	60	Wally Tan G H	08/10/2019	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
7	1	BP-SLANT SUPPLY SEALANT (NETT)				100.00 ✓
8	5	BP-ECU3 TO RESET ECU & REPROGRAMME (NETT)				216.50 ✓
9	1	BP-LPO SUPPLY REGR PLATE (PO#)				96.00 ✓
		FRONT (NETT)				
10	1	L81145-33F21 UNIT, HEADLAMP	1.00	3702.20		3702.20
11	2	L81185-33F21 UNIT, HEADLAMP	1.00	3702.20		3702.20
12	3	L81136-33J00 RIM, HEADLAMP	1.00	17.50		17.50
13	4	L81176-33J00 RIM, HEADLAMP	1.00	17.50		17.50
14	5	L81137-33J00 RIM, HEADLAMP	1.00	46.50		46.50
15	6	L81177-33J00 RIM, HEADLAMP	1.00	28.80		28.80
16	7	L53301-33260 HOOD SUB-ASSY	1.00	2962.10		2962.10
17	8	T90467-09050 CLIP	9.00	2.90		26.10
18	9	T88723-33170 LABEL, COOLER	1.00	4.20		4.20
19	0	T11293-36070 LABEL, ENGINE	1.00	7.30		7.30
20	1	TG9275-12010 LABEL, BATTERY	1.00	9.20		9.20
21	2	L53101-33670 GRILLE SUB-ASSY	1.00	1660.70		1660.70
22	3	L53112-33390 GRILLE, RADIATOR	1.00	223.40		223.40
23	4	L53141-33180 GARNISH, RADIATOR	1.00	2100.70		2100.70
24	5	L88210-33120 SENSOR ASSY	1.00	2125.80		2125.80
25	6	L52115-33110 SUPPORT, FR BUMPER	1.00	43.00		43.00

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 08/10/2019
TIME 16:49

VEHICLE NO SMH3997H

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	330A
Vehicle Details	
Vehicle No.:	SKV5907E
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Oct 2019
Vehicle Make:	CITROEN
Vehicle Model:	GRAND C4 PICASSO 1.6i EHDi ETG6 HALOGEN
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	10JBEX3057402
Chassis No.:	VF73A9HC8FJ657983
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$25,827.00
Original Registration Date:	25 Sep 2015
First Registration Date:	25 Sep 2015
Transfer Count:	0
Actual ARF Paid:	\$13,158.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Sep 2025
PARF Rebate Amount:	\$9,868.00
Intended COE Rebate Details	
COE Expiry Date:	24 Sep 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,089.00
COE Rebate Amount:	\$33,936.00
Total Rebate Amount:	\$43,804.00

The information contained herein is correct as at 14 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/10/2019 19:21
Date Of Accident	06/10/2019 09:20
Exact Location Of Accident	ALONG ROAD 1 GRANGE ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKV5907E
Insured/Policyholder	
Name Of Registered Owner	BUJUNG
NRIC No	S2692330A
Email Address	KHYLING@YAHOO.COM
Mobile Phone No	(LOCAL) +65-90616009
Alternative Phone No	OFFICE-90616009

Vehicle Particulars

Manufacturer	CITROEN
Model	GRAND C4 PICASSO-1.6 D E-HDI ETG6 HALOGEN (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z/19/VP05/024317-001
Cover Note Number	

Driver

Name of Driver	DAVID IMANUEL TANAKA
NRIC No	S9472201B
Date Of Birth	24/04/1994
Occupation	INDOOR
Date Of Driving Pass	06/02/2014
Driving Experience	5 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94887713
Fax Number	
Contact Number	
EEmail Address	T.DAVID9424@GMAIL.COM



Address	BLK 126A EDGEDALE PLAINS #10-348
Postcode	821126
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : FRANKY GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN & POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	
Details Of Properties	KERB & TRAFFIC LIGHT
Vehicle Category	NA/UNKNOWN
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 7/10/19 @ 12.10pm

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

SKETCH PLAN


$$f_1 = 5 \text{KV } 590716$$

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____

Date & Time:

Company Chop (if applicable)

Driver's Signature _____

(If driver is not the policyholder)

Date & Time: 7/10/19 @ 12:10 pm

Reporting Centre Personnel's Signature

Neatness

NRIC/FIN No.





**SINGAPORE
POLICE FORCE**



T/20191006/2044

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20191006/2044

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 06/10/2019 11:42		Vide Report No.: E/20191006/0081		Station Diary No.:	
Informant's Particulars					
Name of Informant: DAVID IMANUEL TANAKA			Address: 126A EDGEDALE PLAINS #10-348 SINGAPORE 821126		
ID Type / ID No.: NRIC NO / S9472201B			Contact No.: Home/Office: Mobile: 94887713		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 25	Date of Birth: 24/04/1994	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Student			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 06/10/2019 09:20	Type of Location:
Location: Along Road 1 GRANGE ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Moderate
Type of Collision:				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKV5907E	Car				Slightly Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20191006/2044

2 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20191006/2044

CONTINUATION OF REPORT

Driver			
Name	DAVID IMANUEL TANAKA	ID No.	S9472201B
Related Vehicle	SKV5907E (Car)	Contact No.	94887713
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the above mentioned date time and location,
I was travelling along Grange Rd, on the extreme left lane. I was sleepy, due to lack of sleep to study.
While driving, I accidentally close my eyes and the next thing that happen is I mounted the curb and collided onto a traffic light.



**SINGAPORE
POLICE FORCE**



T/20191006/2044

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20191006/2044

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: 
TP /
MOHAMED ZULKIFLI BIN MUHAMMAD HAIRI

Signature Of Informant:




Signature Of Interpreter:
Not applicable

Date/Time:
06/10/2019 11:42

Officer In Charge Of Case:
TP / AEIT /
Staff Sgt WONG SIEU LUI
Contact No: 65476151

Classification Of Case:

Authentication Stamp
NP168



CO. REG. NO: 199402370D

GST NO: M2-0123250-3



金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,

Sin Ming AutoCity, Singapore 575722

Tel: 6452 7018 Fax: 6458 3895

Email: service@kkinhin.com.sg

INSURER: **Lonpac Insurance Bhd (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	Z/19/VP05/024317-001	Date of Loss:	06/10/2019
Vehicle Reg. No.:	SKV5907E	Driveable?	
Driver Age/Info:	25 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	BUJUNG		
Driver:	DAVID IMANUEL TANAKA		

Make/Model:	CITROEN GRAND C4 PICASSO, 1.6 D E-HDI ETG6 HALOGEN (A)	Vehicle Reg. Date:	25/09/2015
Vehicle Colour:	SILVER		
Engine No:	10JBEX3057402	Chassis No:	VF73A9HC8FJ657983
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	16 ✓

No old bulb



Not Notified
11/10/19
Presumably After Police
Ex @ 4000h

Description of Accident/Loss	PLEASE REFER TO SKETCH PLAN & POLICE REPORT. Ex: 62564315
------------------------------	---

Remarks:	DEAR OFFICER, VEHICLE IS TOWED TO OUR WORKSHOP. DUE TO THE EXTENT OF DAMAGE, WE NEEDED MORE TIME TO DO THE ESTIMATE AND CHECK PRICES. KINDLY ARRANGE FOR SURVEY. MANY THANKS -SANDRA
----------	--

Present Location:	K KIM HIN AUTO PTE LTD (HQ)
-------------------	-----------------------------

COST OF CLAIMS

	Amount
Parts	43,967.98
Miscellaneous Items	0.00
Labour	5,930.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	49,897.98
+ GST 7.00% (\$\$)	3,492.86
Nett Amount (\$\$)	53,390.84

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before start spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

This claim is handled by: **SANDRA KHONG YEE TENG**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Oct 2019)

Parts: M1-MPV CITROEN GRAND C4 PICASSO 1.6 D e-HDi ETG6 Halogen (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKV5907E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BUMPER	M17 0.00	0.00	*640.00 F	—
2	1		*FRONT BUMPER SIDE RETAINER (SET)	CM 0.00	0.00	*65.00 F	—
3	2		*FRONT BUMPER FOG LAMP (LH/RH)	M15 0.00	0.00	*200.00 F	—
4	1		*FRONT BUMPER FOG LAMP WIRE HARNESS	T1 0.00	0.00	*450.00 F	—
5	2		*FRONT BUMPER FOG LAMP COVER (LH/RH)	M17 0.00	0.00	*190.00 F	—
6	1		*FRONT BUMPER REINFORCEMENT	R 0.00	0.00	*450.00 F	X
7	1		*FRONT BUMPER CENTRE LOWER GRILLE	M17 0.00	0.00	*225.00 F	—
8	1		*FRONT BUMPER CENTRE LOWER GRILLE SIDE COVER	M17 0.00	0.00	*65.00 F	—
9	1		*FRONT BUMPER CENTRE LOWER INNER INTAKE MODULE	Sm 0.00	0.00	*420.00 F	X
10	1		*FRONT BUMPER CENTRE LOWER CHROME MOULDING	M17 0.00	0.00	*200.00 F	—
11	1		*FRONT BUMPER BRACKET (SET)	R 0.00	0.00	*110.00 F	X
12	1		*FRONT BUMPER CENTRE BRACKET	R 0.00	0.00	*310.00 F	—
13	1		*FRONT GRILLE BRACKET (LOGO)	M17 0.00	0.00	*125.00 F	—
14	1		*FRONT GRILLE LOGO (CHROME)	M17 0.00	0.00	*195.00 F	—
15	2		*FRONT SIGNAL LAMP (LH/RH)	M17 0.00	0.00	*680.00 F	—
16	2		*FRONT SIGNAL LAMP OUTER CHROME (LH/RH)	M17 0.00	0.00	*330.00 F	—
17	2		*FRONT SIGNAL LAMP OUTER CHROME INNER BRACKET (LH/RH)	M17 0.00	0.00	*200.00 F	—
18	1		*TURBO COOLER AIR INTAKE DUCT	M17 0.00	0.00	*110.00 F	—
19	1		*TURBO COOLER	M17 0.00	0.00	*450.00 F	—
20	1		*TURBO COOLER TOP BRACKET	R1 0.00	0.00	*40.00 F	—
21	1		*TURBO COOLER CENTRE BRACKET	M17 0.00	0.00	*40.00 F	—
22	1		*TURBO COOLER LOWER BRACKET	M17 0.00	0.00	*40.00 F	—
23	1		*TURBO COOLER INTAKE HOSE	R1 0.00	0.00	*140.00 F	—
24	1		*TURBO COOLER OUTLET HOSE	R1 0.00	0.00	*140.00 F	—
25	1		*FRONT BUMPER UNDERCOVER	CM 0.00	0.00	*250.00 F	—
26	10		*FRONT BUMPER CLIPS	RC 0.00	0.00	*55.00 F	—
27	1		*O/S FRONT FENDER	R1 0.00	0.00	*360.00 F	—
28	1		*O/S FRONT FENDER INNER VERTICAL GARNISH	M17 0.00	0.00	*75.00 F	—
29	1		*O/S FRONT FENDER INNER SHIELD	T1 0.00	0.00	*180.00 F	—
30	8		*O/S FRONT FENDER INNER SHIELD CLIPS	M1 0.00	0.00	*44.00 F	—
31	1		*O/S FRONT FENDER TOP SEAL	M1 0.00	0.00	*65.00 F	—
32	1		*O/S FRONT FENDER INNER PANEL (OUTER)	R1 0.00	0.00	*300.00 F	—
33	1		*O/S FRONT FENDER INNER FRAME PANEL	R1 0.00	0.00	*360.00 F	—
34	1		*O/S FRONT FENDER WHEEL HOUSING PANEL	R1 0.00	0.00	*460.00 F	—
35	1		*FRONT SUPPORT PANEL - TOP	CM 0.00	0.00	*230.00 F	—
36	1		*FRONT SUPPORT PANEL - LOWER	R 0.00	0.00	*120.00 F	X
37	1		*FRONT SUPPORT PANEL SIDE - RH	R1 0.00	0.00	*120.00 F	—
38	1		*FRONT SUPPORT PANEL SIDE - LH	R 0.00	0.00	*120.00 F	X
39	1		*FRONT SUPPORT PANEL AIR GUIDE - RH	R1 0.00	0.00	*95.00 F	X
40	1		*FRONT SUPPORT PANEL AIR GUIDE - LH	Sm 0.00	0.00	*95.00 F	—
41	1		*FRONT SUPPORT PANEL TOP GARNISH	M17 0.00	0.00	*135.00 F	—
42	5		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	RC 0.00	0.00	*27.50 F	—
43	1		*BONNET	R1 0.00	0.00	*680.00 F	—
44	2		*BONNET HINGES (LH/RH)	D17 0.00	0.00	*240.00 F	—

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
45	1		*BONNET LOCK		0.00	0.00	*45.00 F	X
46	1		*BONNET LOCK PULL LEVER		0.00	0.00	*70.00 F	X
47	1		*BONNET LOCK PULL CABLE		0.00	0.00	*120.00 F	X
48	2		*HEADLAMP ASSY (LH/RH)	015 R20	0.00	0.00	*900.00 F	4
49	2		*HEADLAMP PANEL (LH/RH)	015 R2	0.00	0.00	*180.00 F	4
50	1		*WIPER WASHER TANK	R2	0.00	0.00	*145.00 F	-
51	1		*WIPER WASHER TANK NECK	011	0.00	0.00	*45.00 F	-
52	1		*WIPER WASHER TANK MOTOR	Sm	0.00	0.00	*55.00 F	7
53	1		*WIPER WASHER TANK CAP COVER	NU	0.00	0.00	*25.00 F	L
54	1		*WIPER WASHER TANK LEVEL SENSOR	Sm	0.00	0.00	*60.00 F	X
55	1		*FRONT WINDSCREEN GLASS, GLASS MOULDING	CM	0.00	0.00	*1,450.00 F	L
56	1		*FRONT WIPER PANEL GARNISH	CM	0.00	0.00	*240.00 F	L
57	1		*O/S FRONT WIPER PANEL GARNISH SPONGE	T2	0.00	0.00	*80.00 F	L
58	1		*O/S FRONT WIPER ARM	Sm	0.00	0.00	*125.00 F	X
59	1		*O/S FRONT WIPER ARM CAP COVER	NU	0.00	0.00	*35.00 F	L
60	1		*O/S FRONT WIPER LINKAGE	Sm	0.00	0.00	*210.00 F	X
61	2		*O/S FRONT WIPER BLADES (LH/RH)	Sm	0.00	0.00	*190.00 F	L
62	1		*O/S FRONT FENDER 1/4 GLASS MOULDING	011	0.00	0.00	*240.00 F	L
63	1		*AIR CON CONDENSER	Sm	0.00	0.00	*390.00 F	X
64	1		*AIR CON LIQUID PIPE	Sm	0.00	0.00	*135.00 F	X
65	1		*AIR CON DISCHARGE PIPE	Sm	0.00	0.00	*430.00 F	X
66	1		*AIR CON SUCTION PIPE	Sm	0.00	0.00	*200.00 F	X
67	1		*AIR CON COMPRESSOR	R	0.00	0.00	*1,400.00 F	X
68	1		*RADIATOR	Sm	0.00	0.00	*350.00 F	X
69	1		*RADIATOR LOWER HOSE	Sm	0.00	0.00	*60.00 F	X
70	1		*RADIATOR FAN ASSY	Sm	0.00	0.00	*420.00 F	X
71	1		*RADIATOR SPARE TANK	NU	0.00	0.00	*95.00 F	L
72	1		*ENGINE MOUNTING - RH	Sm	0.00	0.00	*170.00 F	X
73	1		*ENGINE MOUNTING - LH	Sm	0.00	0.00	*110.00 F	X
74	1		*ENGINE MOUNTING - REAR	Sm	0.00	0.00	*90.00 F	X
75	2		*FRONT SPORT RIM (LH/RH)	NU	0.00	0.00	*1,400.00 F	L
76	2		*FRONT LOWER ARM (LH/RH)	015 R2 N15 R2	0.00	0.00	*430.00 F	L
77	2		*FRONT LOWER ARM BALL JOINT (LH/RH)	015 R2 N15 R2	0.00	0.00	*150.00 F	L
78	2		*FRONT KNUCKLE ARM (LH/RH), ARM BEARING (LH/RH), BEARING HUB (LH/RH)	R2	0.00	0.00	*1,200.00 F	L
79	2		*FRONT DRIVE SHAFT (LH/RH)	015 R2 N15 R2	0.00	0.00	*920.00 F	L
80	1		*FRONT STEERING RACK & PINION	AT/IN	0.00	0.00	*2,100.00 F	L
81	1		*FRONT STABILIZER BAR, BAR BUSH (2PCS)	Sm	0.00	0.00	*360.00 F	X
82	2		*FRONT STABILIZER BAR LINKAGE (LH/RH)	015 R2 N15 R2	0.00	0.00	*90.00 F	X
83	1		*FRONT STEERING CROSSMEMBER	Sm	0.00	0.00	*1,050.00 F	X
84	2		*FRONT TIE ROD END (LH/RH)	015 R2 N15 R2	0.00	0.00	*170.00 F	X
85	2		*FRONT BRAKE SENSOR (LH/RH)	Sm	0.00	0.00	*120.00 F	X
86	2		*FRONT SHOCK ABSORBER (LH/RH)	R2	0.00	0.00	*380.00 F	L
87	2		*FRONT SHOCK ABSORBER MOUNTING	015 R2 N15 R2	0.00	0.00	*130.00 F	4
88	2		*FRONT SHOCK ABSORBER BEARING	Sm	0.00	0.00	*110.00 F	X
89	2		*FRONT SHOCK ABSORBER STOPPER	Sm	0.00	0.00	*110.00 F	X
90	1		*O/S ENGINE LOWER SIDE COVER	CM	0.00	0.00	*110.00 F	L
91	1		*ENGINE UNDER COVER	CM	0.00	0.00	*480.00 F	L
92	1		*RADIATOR SPARE TANK BYPASS HOSE	CM	0.00	0.00	*40.00 F	2
93	1		*STEERING AIR BAG	Bush	0.00	0.00	*500.00 F	L
94	1		*STEERING AIR BAG CLOCK SPRING	Sm	0.00	0.00	*630.00 F	L
95	1		*STEERING AIR BAG CRASH SENSOR	Sm	0.00	0.00	*100.00 F	L
96	1		*DASHBOARD ASSY	T2	0.00	0.00	*3,400.00 F	L
97	1		*DASHBOARD AIR BAG	Bush	0.00	0.00	*750.00 F	L
98	1		*DASHBOARD AIR BAG CRASH SENSOR	Sm	0.00	0.00	*100.00 F	L
99	1		*AIR BAG CONTROL UNIT	Sm	0.00	0.00	*460.00 F	L
100	1		*DRIVER SEAT BELT	T2	0.00	0.00	*300.00 F	L
101	1		*DRIVER SEAT BELT BUCKLE	Sm	0.00	0.00	*135.00 F	X

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
102	1		*FRONT PASSENGER SEAT BELT	<i>Tn</i> 0.00	0.00	*300.00 F	<i>L</i>
103	1		*FRONT PASSENGER SEAT BELT BUCKLE	<i>Sn</i> 0.00	0.00	*135.00 F	<i>7</i>
104	1		*O/S FRONT DOOR OUTER A PILLAR	<i>R</i> 0.00	0.00	*2,150.00 F	<i>X</i>
105	1		*O/S ROCKER PANEL	<i>R</i> 0.00	0.00	*840.00 F	<i>X</i>
106	1		*FRONT BUMPER LOWER ABSORBER (SET)	<i>Sn</i> 0.00	0.00	*75.00 F	<i>X</i>
107	1		*FRONT NUMBER PLATE	<i>mi</i> 0	0.00	*40.00 FS	<i>L</i>
108	1		*O/S HEADLAMP WIREHARNES (LOCAL REPAIR)	<i>Sn</i> 0	0.00	*300.00 FS	<i>7</i>
109	1		*FRONT WINDSCREEN GLASS SEALANT	<i>Rn</i> 0	0.00	*40.00 FS	<i>L</i>
110	1		*FRONT WINDSCREEN GLASS DAMPING SEAL	<i>Rn</i> 0	0.00	*20.00 FS	<i>-</i>
111	1		*ERP BRACKET	<i>Rn</i> 0	0.00	*26.00 FS	<i>-</i>
112	1		*FRONT WINDSCREEN SOLAR FILM	<i>Rn</i> 0	0.00	*280.00 FS	<i>7</i>
113	1		*O/S FRONT FENDER 1/4 GLASS SEALANT	<i>Rn</i> 0	0.00	*30.00 FS	<i>-</i>
114	1		*RADIATOR COOLANT	<i>Rn</i> 0	0.00	*48.00 FS	<i>-</i>
115	2		*FRONT TYRES (LH/RH)	<i>Pn</i> 0	0.00	*500.00 FS	<i>8ok</i>

F=Franchise part. S=SpocNett.

Sub Total (S\$)	38,400.50
+ Margin on L,N Items 15.00% (S\$)	5,567.48
Total Parts (S\$)	43,967.98

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO TOW ACCIDENT VEHICLE TO WORKSHOP BY NORMAL TOWING. FOC	New	0.00
2	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	New	1600 2,200.00
3	TO REMOVE AND RENEW FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	120.00
4	TO REMOVE AIRCON CONDENSER, PIPES AND DRIERS. VACUUM AND RECHARGE GAS.	New	180 450.00
5	TO REMOVE FRONT INSTRUMENT PANEL ASSY AND REWIRING TO FACILITATE REPAIR WORKS.	New	250 380.00
6	TO REMOVE AND REFIT ENGINE ASSY IN ORDER TO FACILITATE REPAIRING WORKS.	New	280 350.00
7	TO DISMANTLE AND CHECK FRONT UNDERCARRIAGES. TO REPLACE AFFECTED PORTIONS.	New	280 350.00
8	TO CONDUCT FRONT WHEEL ALIGNMENT TEST.	New	60 80.00
9	TO CHECK AND REALIGNMENT ON CHASSIS MEMBER.	New	250 300.00
10	TO REMOVE AND RENEW AIR BAG SENSORS SEAT BELTS ASSY, TO REWIRING AND RE-SETTING PROGRAM	New	300 450.00
11	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	1000 1,200.00
12	TO FOCUS HEADLAMPS. TO CHECK FRONT WIRING AND LIGHTING OPERATION.	New	30 50.00
Gross Labour Cost (S\$)			5,930.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

CO. REG. NO: 199402370D

GST NO: M2-0123250-3

KIM KIM HIN AUTO PTE LTD

金興(戴)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,

Sin Ming AutoCity, Singapore 575722

Tel: 6452 7018 Fax: 6458 3895

Email: service@kkimhin.com.sg

INSURER: **Lompac Insurance Bhd (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	Z/19/VP05/024317-001	Date of Loss:	06/10/2019
Vehicle Reg. No.:	SKV5907E	Driveable?	
Driver Age/Info:	25 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	BUJUNG		
Driver:	DAVID IMANUEL TANAKA		

Make/Model:	CITROEN GRAND C4 PICASSO, 1.6	Vehicle Reg. Date:	25/09/2015
	D E-HDI ETG6 HALOGEN (A)		
Vehicle Colour:	SILVER	Chassis No:	VF73A9HC8FJ657983
Engine No:	10JB1EX3057402		
Odometer:	0 KM		

Paint Type:
Total Loss?
Est. Duration of Repair (day)

NO

16 ✓

Mtds Culc:

1/25

Not Notified
1/10/19
Resurvey After Repair
Ex @ 4000ph

Description of Accident/Loss

PLEASE REFER TO SKETCH PLAN & POLICE REPORT. Ref: 62564315

Remarks:

DEAR OFFICER, VEHICLE IS TOWED TO OUR WORKSHOP. DUE TO THE EXTENT OF DAMAGE, WE NEEDED MORE TIME TO DO THE ESTIMATE AND CHECK PRICES. KINDLY ARRANGE FOR SURVEY. MANY THANKS -SANDRA

Present Location:

K KIM HIN AUTO PTE LTD (HQ)

COST OF CLAIMS

Parts
Miscellaneous Items
Labour
Paintwork Labour
Towing

	Amount
Parts	43,967.98
Miscellaneous Items	0.00
Labour	5,930.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	49,897.98
+ GST 7.00% (\$\$)	3,492.86
Nett Amount (\$\$)	53,390.84

This claim is handled by: **SANDRA KHONG YEE TENG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Oct 2019)

Parts: M1-MPV CITROEN GRAND C& PICASSO 1.6 D e-HDi ETG6 Halogen (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKV5907E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BUMPER	0.00	0.00	*340.00 F	✓
2	1		*FRONT BUMPER SIDE RETAINER (SET)	0.00	0.00	*65.00 F	✓
3	2		*FRONT BUMPER FOG LAMP (LH/RH)	0.00	0.00	*200.00 F	✓
4	1		*FRONT BUMPER FOG LAMP WIRE HARNESS	0.00	0.00	*450.00 F	✓
5	2		*FRONT BUMPER FOG LAMP COVER (LH/RH)	0.00	0.00	*190.00 F	✓
6	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	*450.00 F	X
7	1		*FRONT BUMPER CENTRE LOWER GRILLE	0.00	0.00	*225.00 F	✓
8	1		*FRONT BUMPER CENTRE LOWER GRILLE SIDE COVER	0.00	0.00	*65.00 F	✓
9	1		*FRONT BUMPER CENTRE LOWER INNER INTAKE MODULE	0.00	0.00	*420.00 F	X
10	1		*FRONT BUMPER CENTRE LOWER CHROME MOULDING	0.00	0.00	*200.00 F	✓
11	1		*FRONT BUMPER BRACKET (SET)	0.00	0.00	*110.00 F	X
12	1		*FRONT BUMPER CENTRE BRACKET	0.00	0.00	*310.00 F	✓
13	1		*FRONT GRILLE BRACKET (LOGO)	0.00	0.00	*125.00 F	✓
14	1		*FRONT GRILLE LOGO (CHROME)	0.00	0.00	*195.00 F	✓
15	2		*FRONT SIGNAL LAMP (LH/RH)	0.00	0.00	*680.00 F	✓
16	2		*FRONT SIGNAL LAMP OUTER CHROME (LH/RH)	0.00	0.00	*330.00 F	✓
17	2		*FRONT SIGNAL LAMP OUTER CHROME INNER BRACKET (LH/RH)	0.00	0.00	*200.00 F	✓
18	1		*TURBO COOLER AIR INTAKE DUCT	0.00	0.00	*110.00 F	✓
19	1		*TURBO COOLER	0.00	0.00	*450.00 F	✓
20	1		*TURBO COOLER TOP BRACKET	0.00	0.00	*40.00 F	✓
21	1		*TURBO COOLER CENTRE BRACKET	0.00	0.00	*40.00 F	✓
22	1		*TURBO COOLER LOWER BRACKET	0.00	0.00	*40.00 F	✓
23	1		*TURBO COOLER INTAKE HOSE	0.00	0.00	*140.00 F	✓
24	1		*TURBO COOLER OUTLET HOSE	0.00	0.00	*140.00 F	✓
25	1		*FRONT BUMPER UNDERCOVER	0.00	0.00	*250.00 F	✓
26	10		*FRONT BUMPER CLIPS	0.00	0.00	*55.00 F	✓
27	1		*O/S FRONT FENDER	0.00	0.00	*360.00 F	✓
28	1		*O/S FRONT FENDER INNER VERTICAL GARNISH	0.00	0.00	*75.00 F	✓
29	1		*O/S FRONT FENDER INNER SHIELD	0.00	0.00	*180.00 F	✓
30	8		*O/S FRONT FENDER INNER SHIELD CLIPS	0.00	0.00	*44.00 F	✓
31	1		*O/S FRONT FENDER TOP SEAL	0.00	0.00	*65.00 F	✓
32	1		*O/S FRONT FENDER INNER PANEL (OUTER)	0.00	0.00	*300.00 F	✓
33	1		*O/S FRONT FENDER INNER FRAME PANEL	0.00	0.00	*360.00 F	✓
34	1		*O/S FRONT FENDER WHEEL HOUSING PANEL	0.00	0.00	*460.00 F	✓
35	1		*FRONT SUPPORT PANEL - TOP	0.00	0.00	*230.00 F	✓
36	1		*FRONT SUPPORT PANEL - LOWER	0.00	0.00	*120.00 F	X
37	1		*FRONT SUPPORT PANEL SIDE - RH	0.00	0.00	*120.00 F	✓
38	1		*FRONT SUPPORT PANEL SIDE - LH	0.00	0.00	*120.00 F	X
39	1		*FRONT SUPPORT PANEL AIR GUIDE - RH	0.00	0.00	*95.00 F	X
40	1		*FRONT SUPPORT PANEL AIR GUIDE - LH	0.00	0.00	*95.00 F	X
41	1		*FRONT SUPPORT PANEL TOP GARNISH	0.00	0.00	*135.00 F	✓
42	5		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	0.00	0.00	*27.50 F	✓
43	1		*BONNET	0.00	0.00	*680.00 F	✓
44	2		*BONNET HINGES (LH/RH)	0.00	0.00	*240.00 F	✓

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
45	1		*BONNET LOCK	R	0.00	0.00	*45.00 F	X
46	1		*BONNET LOCK PULL LEVER	R	0.00	0.00	*70.00 F	X
47	1		*BONNET LOCK PULL CABLE	R	0.00	0.00	*120.00 F	X
48	2		*HEADLAMP ASSY (LH/RH)	O/S R/O	NIS ?	0.00	*900.00 F	4
49	2		*HEADLAMP PANEL (LH/RH)	O/S R/O	NIS ?	0.00	*180.00 F	4
50	1		*WIPER WASHER TANK	R	0.00	0.00	*145.00 F	✓
51	1		*WIPER WASHER TANK NECK	D/S	0.00	0.00	*45.00 F	✓
52	1		*WIPER WASHER TANK MOTOR		0.00	0.00	*55.00 F	?
53	1		*WIPER WASHER TANK CAP COVER	R	0.00	0.00	*25.00 F	✓
54	1		*WIPER WASHER TANK LEVEL SENSOR		0.00	0.00	*60.00 F	?
55	1		*FRONT WINDSCREEN GLASS, GLASS MOULDING	C/M	0.00	0.00	*1,450.00 F	✓
56	1		*FRONT WIPER PANEL GARNISH	C/M	0.00	0.00	*240.00 F	✓
57	1		*O/S FRONT WIPER PANEL GARNISH SPONGE	T	0.00	0.00	*80.00 F	✓
58	1		*O/S FRONT WIPER ARM		0.00	0.00	*125.00 F	?
59	1		*O/S FRONT WIPER ARM CAP COVER	R	0.00	0.00	*35.00 F	✓
60	1		*O/S FRONT WIPER LINKAGE		0.00	0.00	*210.00 F	?
61	2		*O/S FRONT WIPER BLADES (LH/RH)	R	0.00	0.00	*190.00 F	✓
62	1		*O/S FRONT FENDER 1/4 GLASS MOULDING	D/S	0.00	0.00	*240.00 F	✓
63	1		*AIR CON CONDENSER	L	0.00	0.00	*390.00 F	X
64	1		*AIR CON LIQUID PIPE		0.00	0.00	*135.00 F	?
65	1		*AIR CON DISCHARGE PIPE		0.00	0.00	*430.00 F	?
66	1		*AIR CON SUCTION PIPE		0.00	0.00	*200.00 F	?
67	1		*AIR CON COMPRESSOR		0.00	0.00	*1,400.00 F	?
68	1		*RADIATOR	L	0.00	0.00	*350.00 F	X
69	1		*RADIATOR LOWER HOSE	R	0.00	0.00	*60.00 F	X
70	1		*RADIATOR FAN ASSY	L	0.00	0.00	*420.00 F	X
71	1		*RADIATOR SPARE TANK	R	0.00	0.00	*95.00 F	✓
72	1		*ENGINE MOUNTING - RH		0.00	0.00	*170.00 F	?
73	1		*ENGINE MOUNTING - LH		0.00	0.00	*110.00 F	?
74	1		*ENGINE MOUNTING - REAR		0.00	0.00	*90.00 F	?
75	2		*FRONT SPORT RIM (LH/RH)	R	0.00	0.00	*400.00 F	✓
76	2		*FRONT LOWER ARM (LH/RH)	O/S R/O	NIS ?	0.00	*430.00 F	4
77	2		*FRONT LOWER ARM BALL JOINT (LH/RH)	O/S R/O	NIS ?	0.00	*150.00 F	4
78	2		*FRONT KNUCKLE ARM (LH/RH), ARM BEARING (LH/RH), BEARING HUB (LH/RH)	R	0.00	0.00	*1,200.00 F	✓
79	2		*FRONT DRIVE SHAFT (LH/RH)	O/S R/O	NIS ?	0.00	*920.00 F	4
80	1		*FRONT STEERING RACK & PINION	RAT L	0.00	0.00	*2,100.00 F	✓
81	1		*FRONT STABILIZER BAR, BAR BUSH (2PCS)		0.00	0.00	*360.00 F	?
82	2		*FRONT STABILIZER BAR LINKAGE (LH/RH)	O/S R/O	NIS ?	0.00	*90.00 F	4
83	1		*FRONT STEERING CROSSMEMBER		0.00	0.00	*1,050.00 F	?
84	2		*FRONT TIE ROD END (LH/RH)	O/S R/O	NIS ?	0.00	*170.00 F	4
85	2		*FRONT BRAKE SENSOR (LH/RH)		0.00	0.00	*120.00 F	?
86	2		*FRONT SHOCK ABSORBER (LH/RH)	R	0.00	0.00	*380.00 F	✓
87	2		*FRONT SHOCK ABSORBER MOUNTING	O/S R/O	NIS ?	0.00	*130.00 F	4
88	2		*FRONT SHOCK ABSORBER BEARING		0.00	0.00	*110.00 F	?
89	2		*FRONT SHOCK ABSORBER STOPPER		0.00	0.00	*110.00 F	?
90	1		*O/S ENGINE LOWER SIDE COVER	C/M	0.00	0.00	*110.00 F	✓
91	1		*ENGINE UNDER COVER	C/M	0.00	0.00	*480.00 F	✓
92	1		*RADIATOR SPARE TANK BYPASS HOSE	C/M	0.00	0.00	*40.00 F	✓
93	1		*STEERING AIR BAG	R	0.00	0.00	*500.00 F	✓
94	1		*STEERING AIR BAG CLOCK SPRING	R	0.00	0.00	*630.00 F	✓
95	1		*STEERING AIR BAG CRASH SENSOR	R	0.00	0.00	*100.00 F	✓
96	1		*DASHBOARD ASSY	T	0.00	0.00	*3,400.00 F	✓
97	1		*DASHBOARD AIR BAG	R	0.00	0.00	*750.00 F	✓
98	1		*DASHBOARD AIR BAG CRASH SENSOR	R	0.00	0.00	*100.00 F	✓
99	1		*AIR BAG CONTROL UNIT	R	0.00	0.00	*460.00 F	✓
100	1		*DRIVER SEAT BELT	T	0.00	0.00	*300.00 F	✓
101	1		*DRIVER SEAT BELT BUCKLE		0.00	0.00	*135.00 F	?

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
102	1		*FRONT PASSENGER SEAT BELT	7.2	0.00	*300.00 F	✓
103	1		*FRONT PASSENGER SEAT BELT BUCKLE		0.00	*135.00 F	?
104	1		*O/S FRONT DOOR OUTER A PILLAR	11	0.00	*2,150.00 F	X
105	1		*O/S ROCKER PANEL	11	0.00	*840.00 F	X
106	1		*FRONT BUMPER LOWER ABSORBER (SET)	8.2	0.00	*75.00 F	X
107	1		*FRONT NUMBER PLATE	21.7	0.00	*40.00 FS	✓
108	1		*O/S HEADLAMP WIREHARNES (LOCAL REPAIR)	0	0.00	*300.00 FS	?
109	1		*FRONT WINDSCREEN GLASS SEALANT	11.2	0	*40.00 FS	✓
110	1		*FRONT WINDSCREEN GLASS DAMPING SEAL	11.2	0	*20.00 FS	✓
111	1		*ERP BRACKET	11.2	0	*26.00 FS	✓
112	1		*FRONT WINDSCREEN SOLAR FILM	11.2	0	*280.00 FS	X
113	1		*O/S FRONT FENDER 1/4 GLASS SEALANT	11.2	0	*30.00 FS	✓
114	1		*RADIATOR COOLANT	11.2	0	*48.00 FS	✓
115	2		*FRONT TYRES (LH/RH)	11.2	0	*500.00 FS	400

F=Franchise part. S=SpclVett.

Sub Total (\$\$) 38,400.50
+ Margin on L/H Items 15.00% (\$\$) 5,567.48
Total Parts (\$\$) 43,967.98

Report was unsubmitted during this print-out
Generated using Merimen e-Claims IEAS

6296.50
5910
7176.50
600
270
130
150
20
25
150
200
20

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO TOW ACCIDENT VEHICLE TO WORKSHOP BY NORMAL TOWING. FOC	New	0.00
2	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	New	1600 2,200.00
3	TO REMOVE AND RENEW FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	120.00 ✓
4	TO REMOVE AIRCON CONDENSER, PIPES AND DRIERS. VACUUM AND RECHARGE GAS.	New	450.00 180
5	TO REMOVE FRONT INSTRUMENT PANEL ASSY AND REWIRING TO FACILITATE REPAIR WORKS.	New	250 330.00
6	TO REMOVE AND REFIT ENGINE ASSY IN ORDER TO FACILITATE REPAIRING WORKS.	New	280 350.00
7	TO DISMANTLE AND CHECK FRONT UNDERCARRIAGES. TO REPLACE AFFECTED PORTIONS.	New	280 350.00
8	TO CONDUCT FRONT WHEEL ALIGNMENT TEST.	New	60 80.00
9	TO CHECK AND REALIGNMENT ON CHASSIS MEMBER.	New	250 300.00
10	TO REMOVE AND RENEW AIR BAG SENSORS SEAT BELTS ASSY, TO REVIRING AND RE-SETTING PROGRAM	New	300 450.00
11	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	1000 1,200.00
12	TO FOCUS HEADLAMPS. TO CHECK FRONT WIRING AND LIGHTING OPERATION.	New	30 50.00
Gross Labour Cost (S\$)			5,930.00

Report was unsubmitted during this print-out.
Generated using Merlimen e-Claims IEAS

< END OF ESTIMATES >

TO: LONPAC INSURANCE BHD

CLAIM NO:19/19/19/VP05/022478

WITHOUT PREJUDICE

LETTER OF UNDERTAKING


FOR THE REPAIR OF VEHICLE NO. SKV5907E

We, the undersigned, confirm that we will undertake to repair the vehicle bearing Registration No **SKV5907E** to its pre-accident condition, and to the satisfaction of its owner, at a total cost not exceeding LUMP SUM **17,000.00** (before excess) subject to no breach of Terms & Condition of the POLICY, and to the legal requirement of the local Land Transport Authority (LTA).

There should be **no further supplementary** to the repair cost.

18.10.19

Date


Workshop Stamp/ Signature



Date

Witness by surveyor

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Oct 2019 Sendback Est	12 Oct 2019 12:36 S\$49,897.98	14 Oct 2019 12:17 Edit Adj Rpt	S\$17,000.00 Edit Estimates	S\$17,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: BUJUNG , ID: S2692330A									
Vehicle Reg. No.: SKV5907E		Date of Loss: 06/10/2019 09:00 - :59 [48 Months and 11 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 19/19/19/VP05/022478		Policy/Cover Note No.: Z/19/VP05/024317-001 (Comprehensive)							
		Excess: S\$4,000.00							
Repairer: K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018									
Handling Insurer: Lonpac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Kenny Lim - 62799256]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 23/10/2019]									
Driver/Custodian: DAVID IMANUEL TANAKA (25 / Male), NRIC: S9472201B, Tel: +6594887713 Email: T.DAVID9424@GMAIL.COM									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• LONPAC_HQ (18/10/2019): Alert - Adj Mandate Approved (S\$17000.00) - SKV5907E - Claim Handler: Kenny Lim									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKV5907E (19/19/19/VP05/022478)

OD

Oct 6 2019 9:00AM

[BUJUNG]

K Kim Hin Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	07/10/19 19:27	Video - Accident [Linked Accident Report Documents]	Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	12/10/19 12:36	Repairer Estimates	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/10/19 18:00	Adjuster Immediate Advice	Load HTM	
2	16/10/19 12:10	Adjuster Immediate Advice	Load HTM	
3	17/10/19 10:31	Adjuster Immediate Advice	Load HTM	
4	17/10/19 18:02	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/10/19 11:44	General View	Load JPG	☒
2	16/10/19 11:44	General View	Load JPG	☒
3	16/10/19 11:44	General View	Load JPG	☒
4	16/10/19 11:44	General View	Load JPG	☒
5	16/10/19 11:44	General View	Load JPG	☒
6	16/10/19 11:44	General View	Load JPG	☒
7	16/10/19 11:44	General View	Load JPG	☒
8	16/10/19 11:44	General View	Load JPG	☒
9	16/10/19 11:44	General View	Load JPG	☒
10	16/10/19 11:44	General View	Load JPG	☒
11	16/10/19 11:44	General View	Load JPG	☒
12	16/10/19 11:44	General View	Load JPG	☒
13	16/10/19 11:44	General View	Load JPG	☒
14	16/10/19 11:44	General View	Load JPG	☒
15	16/10/19 11:44	General View	Load JPG	☒
16	16/10/19 11:44	General View	Load JPG	☒
17	16/10/19 11:44	General View	Load JPG	☒
18	16/10/19 11:44	General View	Load JPG	☒
19	16/10/19 11:44	General View	Load JPG	☒
20	16/10/19 11:44	General View	Load JPG	☒
21	16/10/19 11:44	General View	Load JPG	☒
22	16/10/19 11:44	General View	Load JPG	☒
23	16/10/19 11:44	General View	Load JPG	☒
24	16/10/19 11:44	General View	Load JPG	☒
25	16/10/19 11:44	General View	Load JPG	☒
26	16/10/19 11:44	General View	Load JPG	☒
27	16/10/19 11:44	General View	Load JPG	☒

Video			1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
28	16/10/19 11:44	General View	 Load JPG	☒
29	16/10/19 11:44	General View	 Load JPG	☒
30	16/10/19 11:44	General View	 Load JPG	☒
31	16/10/19 11:44	General View	 Load JPG	☒
32	16/10/19 11:44	General View	 Load JPG	☒
33	16/10/19 11:44	General View	 Load JPG	☒
34	16/10/19 11:44	General View	 Load JPG	☒
35	16/10/19 11:44	General View	 Load JPG	☒
36	16/10/19 11:44	General View	 Load JPG	☒
37	16/10/19 11:44	General View	 Load JPG	☒
38	16/10/19 11:44	General View	 Load JPG	☒
39	16/10/19 11:44	General View	 Load JPG	☒
40	16/10/19 11:44	General View	 Load JPG	☒
41	16/10/19 11:44	General View	 Load JPG	☒
42	16/10/19 11:44	General View	 Load JPG	☒
43	16/10/19 11:44	General View	 Load JPG	☒
44	16/10/19 11:44	General View	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	11/10/19 16:16	COE Rebate	 Load PDF	
2	11/10/19 16:16	Driver DL	 Load PDF	
3	11/10/19 16:16	Transfer fee	 Load PDF	
4	11/10/19 16:18	CI	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/10/19 16:36	ESTIMATE.pdf	 Load PDF	
2	28/02/20 09:12	Undertaking letter	 Load PDF	

Linked Accident Report Documents

Video			1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	07/10/19 19:27	Video - Accident	 Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	06/12/19 18:34	Accident Statement	 Load HTM	
2	06/12/19 18:35	Accident Statement	 Load HTM	
3	06/12/19 18:35	Accident Statement	 Load HTM	
4	06/12/19 18:35	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	07/10/19 19:26	Accident Photo	 Load JPG	☒
2	07/10/19 19:26	Accident Photo	 Load JPG	☒
3	07/10/19 19:26	Accident Photo	 Load JPG	☒
4	07/10/19 19:26	Accident Photo	 Load JPG	☒
5	07/10/19 19:26	Accident Photo	 Load JPG	☒
6	07/10/19 19:26	Accident Photo	 Load JPG	☒
7	07/10/19 19:52	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print

Video			1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	07/10/19 19:25	Sketch Plan	 Load TIF	
2	07/10/19 19:25	Sketch Plan #2	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse
Singapore 199555

Our File No: CS/LPC19018043/KYF3E2

Date: 05/03/2020

REFERENCE

Insured/Claimant: BUJUNG Policy No: Z/19/VP05/024317-001
Date of Loss: 06/10/2019 Nature of Claim: OD Claim No: 19/19/VP05/022478

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKV5907E**
Make & Model: CITROEN GRAND C4 PICASSO, 1.6 D e-HDi ETG6 Engine No: 10JBEX3057402
Halogen (A)
Reg. Date: 25/09/2015 (Man. Year: 2015) Chassis No: VF73A9HC8FJ657983
Colour: Metallic Pearl White Odometer: 0 km
Engine Capacity: 1560 cc
Market Value/New Car Price: S\$71,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R17 Rear Tyre Size: 205/55 R17
Front Left Side: Pirelli 8 mm Rear Left Side: Pirelli 8 mm
Front Right Side: Pirelli 8 mm Rear Right Side: Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	43,967.98	28,429.98	15,538.00	35.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,930.00	4,350.00	1,580.00	26.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	49,897.98	32,779.98	17,118.00	34.31
Approved Total (Overridden) (S\$)		17,000.00		
- Excess (S\$)	0.00	4,000.00	-4,000.00	
(S\$)	49,897.98	13,000.00	36,897.98	73.95
+ GST 7.00/7.00% (S\$)	3,492.86	910.00	2,582.86	73.95
Nett Amount (S\$)	53,390.84	13,910.00	39,480.84	73.95

INSPECTION

Date of Assignment: 14/10/2019 Present Location:
Date Inspected: 14/10/2019 Inspected At:

K Kim Hin Auto Pte Ltd (HQ)
K Kim Hin Auto Pte Ltd (HQ)
160 Sin Ming Drive #02-20, Sin Ming
AutoCity
Singapore 575722

Estimated Period of Repair: 16.0 days

Adjuster: KENNETH KONG**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Mar 2020)
Parts:	M1-MPV	CITROEN GRAND C4 PICASSO 1.6 D e-HDi ETG6 Halogen (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKV5907E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Missing	640.00 F	*640.00 F
2	1		*FRONT BUMPER SIDE RETAINER (SET) (WCP)	Cracked	65.00 F	*65.00 F
3	2		*FRONT BUMPER FOG LAMP (LH/RH) (WCP)	Missing	200.00 F	*200.00 F
4	1		*FRONT BUMPER FOG LAMP WIRE HARNESS (WCP)	Torn	450.00 F	*450.00 F
5	2		*FRONT BUMPER FOG LAMP COVER (LH/RH) (WCP)	Missing	190.00 F	*190.00 F
6	1		*FRONT BUMPER REINFORCEMENT (WCP)	Repair	450.00 F	*- F
7	1		*FRONT BUMPER CENTRE LOWER GRILLE (WCP)	Missing	225.00 F	*225.00 F
8	1		*FRONT BUMPER CENTRE LOWER GRILLE SIDE COVER (WCP)	Missing	65.00 F	*65.00 F
9	1		*FRONT BUMPER CENTRE LOWER INNER INTAKE MODULE (WCP)	Serviceable	420.00 F	*- F
10	1		*FRONT BUMPER CENTRE LOWER CHROME MOULDING (WCP)	Missing	200.00 F	*200.00 F
11	1		*FRONT BUMPER BRACKET (SET) (WCP)	Repair	110.00 F	*- F
12	1		*FRONT BUMPER CENTRE BRACKET (WCP)	Repair	310.00 F	*- F
13	1		*FRONT GRILLE BRACKET (LOGO) (WCP)	Missing	125.00 F	*125.00 F
14	1		*FRONT GRILLE LOGO (CHROME) (WCP)	Missing	195.00 F	*195.00 F
15	2		*FRONT SIGNAL LAMP (LH/RH) (WCP)	Missing	680.00 F	*680.00 F
16	2		*FRONT SIGNAL LAMP OUTER CHROME (LH/RH) (WCP)	Missing	330.00 F	*330.00 F
17	2		*FRONT SIGNAL LAMP OUTER CHROME INNER BRACKET (LH/RH) (WCP)	Missing	200.00 F	*200.00 F
18	1		*TURBO COOLER AIR INTAKE DUCT (WCP)	Missing	110.00 F	*110.00 F
19	1		*TURBO COOLER (WCP)	Bent / Punctured	450.00 F	*450.00 F
20	1		*TURBO COOLER TOP BRACKET (WCP)	Bent	40.00 F	*40.00 F
21	1			Missing	40.00 F	*40.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
22	1		*TURBO COOLER CENTRE BRACKET (WCP)			
			*TURBO COOLER LOWER BRACKET (WCP)	Missing	40.00 F	*40.00 F
23	1		*TURBO COOLER INTAKE HOSE (WCP)	Punctured	140.00 F	*140.00 F
24	1		*TURBO COOLER OUTLET HOSE (WCP)	Punctured	140.00 F	*140.00 F
25	1		*FRONT BUMPER UNDERCOVER (WCP)	Cracked	250.00 F	*250.00 F
26	10		*FRONT BUMPER CLIPS (WCP)	Necessary	55.00 F	*55.00 F
27	1		*O/S FRONT FENDER (WCP)	Bent	360.00 F	*360.00 F
28	1		*O/S FRONT FENDER INNER VERTICAL GARNISH (WCP)	Missing	75.00 F	*75.00 F
29	1		*O/S FRONT FENDER INNER SHIELD (WCP)	Torn	180.00 F	*180.00 F
30	8		*O/S FRONT FENDER INNER SHIELD CLIPS (WCP)	Necessary	44.00 F	*44.00 F
31	1		*O/S FRONT FENDER TOP SEAL (WCP)	Necessary	65.00 F	*65.00 F
32	1		*O/S FRONT FENDER INNER PANEL (OUTER) (WCP)	Bent	300.00 F	*300.00 F
33	1		*O/S FRONT FENDER INNER FRAME PANEL (WCP)	Bent	360.00 F	*360.00 F
34	1		*O/S FRONT FENDER WHEEL HOUSING PANEL (WCP)	Bent	460.00 F	*460.00 F
35	1		*FRONT SUPPORT PANEL - TOP (WCP)	Cracked	230.00 F	*230.00 F
36	1		*FRONT SUPPORT PANEL - LOWER (WCP)	Repair	120.00 F	*- F
37	1		*FRONT SUPPORT PANEL SIDE - RH (WCP)	Bent	120.00 F	*120.00 F
38	1		*FRONT SUPPORT PANEL SIDE - LH (WCP)	Repair	120.00 F	*- F
39	1		*FRONT SUPPORT PANEL AIR GUIDE - RH (WCP)	Serviceable	95.00 F	*- F
40	1		*FRONT SUPPORT PANEL AIR GUIDE - LH (WCP)	Serviceable	95.00 F	*- F
41	1		*FRONT SUPPORT PANEL TOP GARNISH (WCP)	Dented / Cut	135.00 F	*135.00 F
42	5		*FRONT SUPPORT PANEL TOP GARNISH CLIPS (WCP)	Necessary	27.50 F	*27.50 F
43	1		*BONNET (WCP)	Bent	680.00 F	*680.00 F
44	2		*BONNET HINGES (LH/RH) (WCP)	Distorted	240.00 F	*240.00 F
45	1		*BONNET LOCK (WCP)	Repair	45.00 F	*- F
46	1		*BONNET LOCK PULL LEVER (WCP)	Serviceable	70.00 F	*- F
47	1		*BONNET LOCK PULL CABLE (WCP)	Serviceable	120.00 F	*- F
48	1		*HEADLAMP ASSY (LH/RH) (WCP)	O/S Broken / N/S Serviceable	900.00 F	*450.00 F
49	1		*HEADLAMP PANEL (LH/RH) (WCP)	O/S Bent	180.00 F	*90.00 F
50	1		*WIPER WASHER TANK (WCP)	Bent	145.00 F	*145.00 F
51	1		*WIPER WASHER TANK NECK (WCP)	Distorted	45.00 F	*45.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*WIPER WASHER TANK MOTOR (WCP)	Serviceable	55.00 F	*- F
53	1		*WIPER WASHER TANK CAP COVER (WCP)	Dented	25.00 F	*25.00 F
54	1		*WIPER WASHER TANK LEVEL SENSOR (WCP)	Serviceable	60.00 F	*- F
55	1		*FRONT WINDSCREEN GLASS, GLASS MOULDING (WCP)	Cracked	1,450.00 F	*1,450.00 F
56	1		*FRONT WIPER PANEL GARNISH (WCP)	Cracked	240.00 F	*240.00 F
57	1		*O/S FRONT WIPER PANEL GARNISH SPONGE (WCP)	Torn	80.00 F	*80.00 F
58	1		*O/S FRONT WIPER ARM (WCP)	Serviceable	125.00 F	*- F
59	1		*O/S FRONT WIPER ARM CAP COVER (WCP)	Dented	35.00 F	*35.00 F
60	1		*O/S FRONT WIPER LINKAGE (WCP)	Serviceable	210.00 F	*- F
61	2		*O/S FRONT WIPER BLADES (LH/RH) (WCP)	Serviceable	190.00 F	*- F
62	1		*O/S FRONT FENDER 1/4 GLASS MOULDING (WCP)	Distorted	240.00 F	*240.00 F
63	1		*AIR CON CONDENSER (WCP)	Serviceable	390.00 F	*- F
64	1		*AIR CON LIQUID PIPE (WCP)	Serviceable	135.00 F	*- F
65	1		*AIR CON DISCHARGE PIPE (WCP)	Serviceable	430.00 F	*- F
66	1		*AIR CON SUCTION PIPE (WCP)	Serviceable	200.00 F	*- F
67	1		*AIR CON COMPRESSOR (WCP)	Repair	1,400.00 F	*- F
68	1		*RADIATOR (WCP)	Serviceable	350.00 F	*- F
69	1		*RADIATOR LOWER HOSE (WCP)	Serviceable	60.00 F	*- F
70	1		*RADIATOR FAN ASSY (WCP)	Serviceable	420.00 F	*- F
71	1		*RADIATOR SPARE TANK (WCP)	Dented	95.00 F	*95.00 F
72	1		*ENGINE MOUNTING - RH (WCP)	Serviceable	170.00 F	*- F
73	1		*ENGINE MOUNTING - LH (WCP)	Serviceable	110.00 F	*- F
74	1		*ENGINE MOUNTING - REAR (WCP)	Serviceable	90.00 F	*- F
75	2		*FRONT SPORT RIM (LH/RH) (WCP)	Dented	1,400.00 F	*1,400.00 F
76	1		*FRONT LOWER ARM (LH/RH) (WCP)	O/S Bent / N/S Serviceable	430.00 F	*215.00 F
77	1		*FRONT LOWER ARM BALL JOINT (LH/RH) (WCP)	O/S Bent / N/S Serviceable	150.00 F	*75.00 F
78	2		*FRONT KNUCKLE ARM (LH//RH), ARM BEARING (LH/RH), BEARING HUB (LH/RH) (WCP)	Bent	1,200.00 F	*1,200.00 F
79	1		*FRONT DRIVE SHAFT (LH/RH) (WCP)	O/S Bent / N/S Repair	920.00 F	*460.00 F
80	1		*FRONT STEERING RACK & PINION (WCP)	Bent / Jammed	2,100.00 F	*2,100.00 F
81	1		*FRONT STABILIZER BAR, BAR BUSH (2PCS) (WCP)	Serviceable	360.00 F	*- F
82	1				90.00 F	*45.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*FRONT STABILIZER BAR LINKAGE (LH/RH) (WCP)	O/S Bent / N/S Serviceable		
83	1		*FRONT STEERING CROSSMEMBER (WCP)	Serviceable	1,050.00 F	*- F
84	1		*FRONT TIE ROD END (LH/RH) (WCP)	O/S Bent / N/S Serviceable	170.00 F	*85.00 F
85	2		*FRONT BRAKE SENSOR (LH/RH) (WCP)	Serviceable	120.00 F	*- F
86	2		*FRONT SHOCK ABSORBER (LH/RH) (WCP)	Bent	380.00 F	*380.00 F
87	1		*FRONT SHOCK ABSORBER MOUNTING (WCP)	O/S Bent / N/S Serviceable	130.00 F	*65.00 F
88	2		*FRONT SHOCK ABSORBER BEARING (WCP)	Serviceable	110.00 F	*- F
89	2		*FRONT SHOCK ABSORBER STOPPER (WCP)	Serviceable	110.00 F	*- F
90	1		*O/S ENGINE LOWER SIDE COVER (WCP)	Cracked	110.00 F	*110.00 F
91	1		*ENGINE UNDER COVER (WCP)	Cracked	480.00 F	*480.00 F
92	1		*RADIATOR SPARE TANK BYPASS HOSE (WCP)	Cracked	40.00 F	*40.00 F
93	1		*STEERING AIR BAG (WCP)	Burst	500.00 F	*500.00 F
94	1		*STEERING AIR BAG CLOCK SPRING (WCP)	Necessary	630.00 F	*630.00 F
95	1		*STEERING AIR BAG CRASH SENSOR (WCP)	Necessary	100.00 F	*100.00 F
96	1		*DASHBOARD ASSY (WCP)	Torn	3,400.00 F	*3,400.00 F
97	1		*DASHBOARD AIR BAG (WCP)	Burst	750.00 F	*750.00 F
98	1		*DASHBOARD AIR BAG CRASH SENSOR (WCP)	Necessary	100.00 F	*100.00 F
99	1		*AIR BAG CONTROL UNIT (WCP)	Necessary	460.00 F	*460.00 F
100	1		*DRIVER SEAT BELT (WCP)	Jammed	300.00 F	*300.00 F
101	1		*DRIVER SEAT BELT BUCKLE (WCP)	Serviceable	135.00 F	*- F
102	1		*FRONT PASSENGER SEAT BELT (WCP)	Jammed	300.00 F	*300.00 F
103	1		*FRONT PASSENGER SEAT BELT BUCKLE (WCP)	Serviceable	135.00 F	*- F
104	1		*O/S FRONT DOOR OUTER A PILLAR (WCP)	Repair	2,150.00 F	*- F
105	1		*O/S ROCKER PANEL (WCP)	Repair	840.00 F	*- F
106	1		*FRONT BUMPER LOWER ABSORBER (SET) (WCP)	Serviceable	75.00 F	*- F
107	1		*FRONT NUMBER PLATE	Missing	40.00 FS	*40.00 FS
108	1		*O/S HEADLAMP WIREHARNES (LOCAL REPAIR)	Serviceable	300.00 FS	*- FS
109	1		*FRONT WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
110	1		*FRONT WINDSCREEN GLASS DAMPING SEAL	Necessary	20.00 FS	*20.00 FS
111	1		*ERP BRACKET	Necessary	26.00 FS	*26.00 FS
112	1		*FRONT WINDSCREEN SOLAR FILM	Not Insured	280.00 FS	*- FS
113	1		*O/S FRONT FENDER 1/4 GLASS SEALANT	Necessary	30.00 FS	*30.00 FS
114	1		*RADIATOR COOLANT	Necessary	48.00 FS	*48.00 FS
115	2		*FRONT TYRES (LH/RH) (80%)	Punctured	500.00 FS	*400.00 FS

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Sub Total (S\$)					38,400.50	24,800.50
+ Margin on L,N Items 15.00/15.00% (S\$)					5,567.48	3,629.48
Total Parts (S\$)					43,967.98	28,429.98

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW ACCIDENT VEHICLE TO WORKSHOP BY NORMAL TOWING. (NPA)	New	0.00	0.00
2	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	New	2,200.00	1,600.00
3	TO REMOVE AND RENEW FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	120.00	120.00
4	TO REMOVE AIRCON CONDENSER, PIPES AND DRIERS. VACUUM AND RECHARGE GAS.	New	450.00	180.00
5	TO REMOVE FRONT INSTRUMENT PANEL ASSY AND REWIRING TO FACILITATE REPAIR WORKS.	New	380.00	250.00
6	TO REMOVE AND REFIT ENGINE ASSY IN ORDER TO FACILITATE REPAIRING WORKS.	New	350.00	280.00
7	TO DISMANTLE AND CHECK FRONT UNDERCARRIAGES. TO REPLACE AFFECTED PORTIONS.	New	350.00	280.00
8	TO CONDUCT FRONT WHEEL ALIGNMENT TEST.	New	80.00	60.00
9	TO CHECK AND REALIGNMENT ON CHASSIS MEMBER.	New	300.00	250.00
10	TO REMOVE AND RENEW AIR BAG SENSORS SEAT BELTS ASSY, TO REWIRING AND RE-SETTING PROGRAM	New	450.00	300.00
11	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	1,200.00	1,000.00
12	TO FOCUS HEADLAMPS. TO CHECK FRONT WIRING AND LIGHTING OPERATION.	New	50.00	30.00
Gross Labour Cost (\$\$)			5,930.00	4,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >