

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19018059/KEA3Q2

Date: 23/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800156041

Claimant
Vehicle No : SMM5490M **Insured Vehicle No :** SMA911L

Date of Loss: 10/10/2019 Nature of Claim: TP Claim No: 7980316442SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM5490M		
Make & Model:	HONDA FREED, 1.5 (A)	Engine No:	LEB5613880
Reg. Date:	03/07/2019 (Man. Year: 2018)	Chassis No:	GB71078083
Colour:	Metallic Black	Odometer:	25747 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,572.32	2,021.20	551.12	21.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,780.00	1,140.00	1,640.00	58.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,352.32	3,161.20	2,191.12	40.94
+ GST 7.00/7.00% (S\$)	374.66	221.28	153.38	40.94
Nett Amount (S\$)	5,726.98	3,382.48	2,344.50	40.94
+ Car Rental (5.0 x S\$83.00/day) (S\$)		415.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,804.93		

INSPECTION

Date of Assignment: 11/10/2019

Date Inspected: 11/10/2019 Inspected At:

Esteem Performance Pte Ltd - Sin
Ming (HQ)
385 Sin Ming Drive
Singapore 575718

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REVERSE SENSOR	Not Necessary	200.00 FS	*- FS
2	1		*REAR BUMPER	Buckled	955.00 FL	*955.00 FL
3	10		*REAR BUMPER CLIP	Necessary	35.00 FL	*35.00 FL
4	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	34.00 FL	*- FL
5	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	34.90 FL	*- FL
6	1		*TAIL DOOR	Bent	1,193.00 FL	*1,193.00 FL
7	1		*TAIL DOOR LOCK	Repair	189.50 FL	*- FL
8	1		*TAIL DOOR EMBLEM	Necessary	38.50 FL	*38.50 FL
9	1		*WORDING FREED	Necessary	55.00 FL	*55.00 FL
10	1		*WORDING HYBRID	Necessary	75.00 FL	*75.00 FL
11	1		*REAR WINDSCREEN MOULDING	Necessary	125.00 FL	*125.00 FL
12	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
13	1		*BOOT WEATHERSTRIP	Serviceable	168.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,152.90	2,516.50
- List Item Discount on L Items 20.00/20.00% (\$)	580.58	495.30
Total Parts (\$)	2,572.32	2,021.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (REAR BUMPER ,TAILDOOR ,END PANEL)	New	1,000.00	400.00
2	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (REAR BUMPER ,TAILDOOR ,END PANEL)	New	1,000.00	440.00
3	TO CHECK WIRING	New	50.00	20.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	120.00	50.00
5	TO REMOVE & REFIT SPARE TYRE ,SPARE TYRE BOARD ,CARPET TRIM TO ASSIST WORK LOAD	New	150.00	0.00
6	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
7	TO TUFF KOTE	New	100.00	30.00
8	TO TRANSFER BOOT MECHANISM TO NEW BOOT	New	120.00	60.00
9	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AID AND SEALING	New	120.00	20.00
Gross Labour Cost (\$\$)			2,780.00	1,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >