



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBP 802U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	HANDLE BAR (CONSISTENT)	NOT NECESSARY	220.00	-
2	HAND GUARD (LH,RH) (CONSISTENT)	SCRATCHED	380.00	380.00
2	SIGNAL LIGHT (CONSISTENT)	BROKEN	240.00	240.00
1	WINDSCREEN (CONSISTENT)	SCRATCHED	320.00	320.00
1	TANK (CONSISTENT)	BENT	1,400.00	1,400.00
1	TANK COVER (LH) (CONSISTENT)	SCRATCHED	180.00	180.00
1	TANK COVER (RH) (CONSISTENT)	SCRATCHED	180.00	180.00
1	RADIATOR (CONSISTENT)	BENT	950.00	950.00
1	BOX (CONSISTENT)	BENT	850.00	850.00
1	CRASH BAR (CONSISTENT)	BENT	450.00	450.00
1	SPORT LIGHT (CONSISTENT)	SCRATCHED	250.00	250.00
2	MIRROR (CONSISTENT)	MISSING (1 PCS ONLY)	190.00	95.00
1	BRAKE LEVER & CLUTCH LEVER (CONSISTENT)	SCRATCHED	180.00	180.00
1	MUDGUARD (CONSISTENT)	CUT	240.00	240.00
1	HELMET (CONSISTENT)	SCRATCHED	350.00	350.00
1	SIDE STAND (CONSISTENT)	TO REPAIR SEE LABOUR	180.00	-
1	FRONT FOOTREST (CONSISTENT)	NOT NECESSARY	58.00	-
1	SIDE FAIRING (LH) (CONSISTENT)	SCRATCHED	180.00	180.00
1	SIDE FAIRING (RH) (CONSISTENT)	SCRATCHED	180.00	180.00
1	EXHAUST PIPE (CONSISTENT)	BENT	1,900.00	1,900.00
1	MASTER PUMP (CONSISTENT)	SCRATCHED	380.00	380.00
	LESS 10% DISCOUNT		-925.80	-870.50
			8,332.20	7,834.50
<b><u>SPECIAL NETT ITEMS</u></b>				
1	COOLANT WATER (CONSISTENT) (SN)	NECESSARY	50.00	50.00
1	FRONT NUMBER PLATE (CONSISTENT) (SN)	NECESSARY	12.00	10.00
			62.00	60.00
<b><u>LABOUR</u></b>				
	ALIGNMENT FORK .		150.00	60.00

Report Ref No. CC4/ASM19018066/R1ga3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TRANSPORT.		45.00	45.00
	LABOUR.INCLUSIVE OF THE REPAIR OF SIDE STAND .		380.00	280.00
			575.00	385.00
<b>GRAND TOTAL</b>			<b>8,969.20</b>	<b>8,279.50</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>6,600.00</b>

Report Ref No. CC4/ASM19018066/R1ga3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.