

22/03/2002
ASS. REC. BY:

CTI

REF: CS/17/10105345 / ESFB

Special Instruction:

SUBMITTED BY: STARR

ASSIGNMENT (Office)

From (Person): TAN KAH LEONG

Date/Time: 14.6.19 9.49A.M

Estimated Cost:

Bill to:

OD (TP/WS/TP RES / OD RES / EVA / INV / MV / CS

Insured: GBE 63447

To Inspect Vehicle No: GBC 16236

Tel: 68442475

at Workshop m/s LEOMWOOD GARAGE
of 53 Ubi Ave 1 # 01-24

Claim No: SMM 1902026702

Policy No: DM CVSN 3007581900

Excess:

Sum Insured:

D.O.A. 11.6.19

Make of Vehl:
(Client's Record)

"sup"

CA / REV / REP. / REV 24 HRS

H.O.D. Employment:

Person Contacted: SUSAN

Vehicle IN/OUT

Date/Time: 14.6.19 9.59A.M

Date/Time Action/Instruction (V) Estimate

GBC 16236 - NM / AWA 19010524 / K4 DOA - 11/06/2019

GBE 63447 - WA / AWA 19010524 / K4 DOA - 11/06/2019

14/10/19 Re-open case for change the claim reference
minimum case, assign by Chae Teoping. File pass to
typist after re-open (give info) 19.

19/10/19 Reopen MV. RECALCULASS * IMPACT \$ DOA 11/10/19

Steve

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 QD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop n/v: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GBC 16236 Yt Regn: 30/6/11
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Nissan URVAN G: 2953
 Colour: Blue A/C Insured / Std / NI
 Sp. Reading: 255239 T/Rvlin: Insured / Std / NI
 Eng/No: _____
 C/No: JN1M64E 252 0795695
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim. STD A/Rim or
 Tyro Size: F: _____ R: 195R15C
 BS / DUN / EXNOVA / GY / FS / LIZA MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front R/Bal. 5 mm R/Bal. 5
 L/Bal. 5 mm L/Bal. 5
 D.O.A. 11/6/19 D.O.I. 14/6/19
 Survey held at Team work
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to c

X	
N/S	O/S

Date / Time: Action / Instruction
19/9/19 Finalize confirm \$6650.00; 7 days (Down)
MV - 18,000
PV - 4846
NV - 13,154
\$ 11,341.29 Red - 63%
 Steve, - RECEIVED 20 SEP 2019
 pls see me.
 20/9/2019

Date/Time, File Pass to: 20/09/19
 1) Type: : Prel. Report
 : Final Report
 Date/Time, File Return to:

Days Of Repair: 7
 Resurvey No. of Trip: 2
 Survey Fee: 7X15=

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Inv (\$)
 : Weekend (\$)

Report Format:
 Lump Sum / I.B.L: 6,650 / LIS

Transportation	50
3 - R. S	50+
Photos	45
Index	80
TOTAL	600



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

TEAMWORK GARAGE PTE LTD
53 UBI AVENUE 1 #01-24
SINGAPORE 408934
ON BEHALF OF HOCK TONG HUAT PTE LTD

INV No. AC1910155
INV Date 07/10/2019
Reference CS/TP19010535/Esd3e2
Code TP376



PROFESSIONAL SERVICE FEE

Vehicle No. GBC 1623G

Insured Veh.

Claim No.

Policy No.

Accident Date 11/06/2019

Inspection Date 14/06/2019

Description	Total
Survey Inspection	600.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	600.00
GST (7%)	42.00
Grand Total	642.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
TEAMWORK GARAGE PTE LTD		Ref : CS/TP19010535/Esd3e2	
53 UBI AVENUE 1 #01-24SINGAPORE 408934		Date : 07-10-2019	
ON BEHALF OF HOCK TONG HUAT PTE LTD		Code : TP376	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.		Veh. Inspected	GBC 1623G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	TAN KAH LEONG	Assign Date	14/06/2019
2. Vehicle Particulars & Condition			
Make & Model	NISSAN URVAN	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	JN1MG4E25Z0795695	Colour	SILVER
Odometer	255239	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15C	MICHELIN	5 mm
L/H Front Tyre	195 R15C	MICHELIN	5 mm
R/H Rear Tyre	195 R15C	MICHELIN	5 mm
L/H Rear Tyre	195 R15C	MICHELIN	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	11/06/2019	Inspection Date	14/06/2019
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 1623G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	BROKEN	695.10	695.10
1	FRONT PANEL	DENTED	1,675.32	1,430.00
1	FRONT RH CORNER PANEL	DENTED	635.50	635.50
1	FRONT BUMPER BRACKET	O/S BROKEN	110.70	55.35
2	FRONT BUMPER RETAINER	BROKEN	91.70	91.70
1	FRONT BUMPER REINFORCEMENT	DENTED	390.80	236.00
2	FRONT BUMPER FOG LAMP	NOT NECESSARY	641.70	-
1	FRONT BUMPER FOG LAMP COVER	O/S CUT	262.66	131.31
1	FRONT GRILLE	BROKEN	476.62	476.62
1	FRONT GRILLE EMBLEM	NECESSARY	66.20	66.20
1	FRONT SIGNAL LAMP	O/S BROKEN	198.90	99.45
2	FRONT HEADLAMP	BROKEN	1,048.98	1,048.98
1	AIRCON CONDENDER	NOT NECESSARY	956.60	-
1	AIRCON LIQUID PIPE	NOT NECESSARY	93.50	-
1	AIRCON RECEIVER DRIER	NOT NECESSARY	218.10	-
1	AIRCON BLOWER ASSY	NOT NECESSARY	739.40	-
1	AIRCON EVAPORATOR	NOT NECESSARY	2,066.43	-
1	AIR INTER COOLER RH	NOT NECESSARY	2,053.67	-
1	WIPER PANEL GARNISH	BROKEN	165.20	165.20
1	FRONT WINDSCREEN MOULDING	NECESSARY	108.70	108.70
1	FRONT DASHBOARD	CRUSHED	1,796.30	1,256.00
1	WIPER LINK ROD	DENTED	272.00	272.00
1	FRONT PANEL INNER	DENTED	526.24	526.24
	LESS 10% DISCOUNT		-1,529.03	-729.44
			13,761.29	6,564.91
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	40.00	30.00
1	SET FRONT GRILLE CLIP (SN)	NECESSARY	30.00	20.00
1	WINDSCREEN SEALANT (SN)	NECESSARY	150.00	40.00
			220.00	90.00
<u>LABOUR</u>				
	CHECK FRONT WIRING AND LIGHTING SYSTEM.		60.00	30.00
	REMOVE,RENEW CONDENSER AND TOP UP GAS.		150.00	100.00

Report Ref No. CS/TP19010535/Esd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND RENEW INTERCOOLER.		150.00	30.00
	REMOVE AND RENEW FRONT WINDSCREEN.		150.00	100.00
	REMOVE AND REFIT FRONT DASHBOARD.		500.00	100.00
	PANEL BEATING ON AFFECTED AREAS.		1,400.00	800.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,600.00	500.00
			4,010.00	1,660.00
	GRAND TOTAL		17,991.29	8,314.91
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,650.00

Report Ref No. CS/TP19010535/Esd3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/06/2019 17:49
Date Of Accident	11/06/2019 15:20
Exact Location Of Accident	566 SIXTH AVENUE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC1623G
Insured/Policyholder	
Name Of Registered Owner	HOCK TONG HUAT PTE LTD
Co Reg No	- 198 902 954K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-86942026
Alternative Phone No	OFFICE-86942026

Vehicle Particulars

Manufacturer	NISSAN
Model	-
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	ALLIED WORLD ASSURANCE COMPANY, LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	AVCP5B0092171800
Cover Note Number	

Driver

Name of Driver	LOGANATHAN MANIVANNAN
NRIC No	S7209744J
Date Of Birth	26/03/1972
Occupation	OUTDOOR
Date Of Driving Pass	07/02/2017
Driving Experience	2 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86942026
Fax Number	
Contact Number	OTHERS-86942026
EEmail Address	NOEMAIL

Address	BLK 467 TAMPINES STREET 44 #06-144
Postcode	520467
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE6344T
Vehicle Make/Model/Colour	TOYOTA / DYNA
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ALEX TANG
NRIC/Passport Number	F1499872K
Contact Number	94887222
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	LOGANATHAN MANIVANNAN
------	-----------------------

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

ARM

GBC1623G

YES

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


- 1) Please report **correctly** on the details of the accident to speed up the claims process.
- 2) This form must **be completed by the policy holder and/or the authorised driver.**
- 3) Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
- 4) The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5) **Any false reporting may be referred to the police for investigation.**
- 6) The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
- 7) By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8) **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in the [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firm, the Monetary Authority of Singapore and any relevant government agency/authority (such as police), for the purpose(s) of:
 - (i) Processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigations the accident and/or my claims;
 - (iii) Carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) Administering my claims (including the mailing of correspondence, statement, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mall packages); and/or
 - (v) Complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "purposes")
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyer/law firms, may/are permitted to collect, use, disclose and/or process my personal information for one or more of the above purposes; and
- (c) My personal information may/can be disclosed by any of the insurer and/or GIA to their third party service providers or agents (including their lawyer/law firms), which may be sited outside of Singapore, for one or more of the above purposes.
- (d) My personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) The information so collected under (d) above may be shared / disclosed:
 - (i) To all insurers and/or any other third parties that assist in evaluating, investigation, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposed stated, or
 - (ii) For complying with requirements under my regulations, laws or court orders.

HOCK TONG HUAT PTE LTD
20 Kaki Bukit View
Singapore 415956
Tel: 6288 5772 Fax: 6283 0185

Policy holder's signature
Date / time:




Driver's signature
(if driver is not policy holder)
Date / time:



reporting centre personnel's Signature
Date / time:

Sketch Pian #2

SKETCH PLAN



A - GBC 1623G
B - GBE 6344T

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling straight along 566 Sixth Avenue. Vehicle B which was in front of me suddenly made a wide turn to Queen Astrid Park which lorries are not allowed to enter. However, he still ignore the sign and make a turn and collide onto my front right portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

HOCK TONG HUAT PTE LTD

20 Kaki Bukit View

Singapore 415956

Policy holder's signature

Date & time:

Driver's signature

(If driver is not policy holder)

Date & time:

reporting centre personnel's Signature

NRIC/FIN No.:

13/6/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Jun 2019		14 Jun 2019 09:49 Edit Adj Rpt	S\$6,650.00 Edit Estimates	S\$6,650.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	HOCK TONG HUAT PTE LTD , Co. Reg. No.: -								
Vehicle Reg. No.:	GBC1623G	Date of Loss: 11/06/2019 15:00 - :59 [95 Months and 12 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / SNM19D202607C02	Policy/Cover Note No.: DMCVSN3007581900							
Vehicle Reg. No. (Insured):	GBE6344T	Policy No. (Claimant): AVCPSB0092171800							
		Excess: S\$350.00							
Repairer:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]								
Claimant's Insurer:	Allied World Assurance Company, Ltd (HQ) - Tel: 62201188								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 25/06/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/> View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBC1623G (SNM19D202607C02)
 [GBE6344T]
 TP
HOCK TONG HUAT PTE LTD
 Jun 11 2019 3:00PM
 [-]
Teamwork Garage Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser
Photos/Images									3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
2	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
3	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
4	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
5	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
6	19/06/19 10:28	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>					
7	19/06/19 10:28	Chassis Number		Load JPG	<input checked="" type="checkbox"/>					
8	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
9	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
10	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
11	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
12	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
13	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
14	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
15	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
16	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
17	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
18	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
19	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
20	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
21	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
22	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
23	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
24	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
25	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
26	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
27	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
28	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
29	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
30	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
31	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
32	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
33	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
34	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
35	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
36	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
37	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
38	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
39	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
40	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
41	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
42	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					
43	19/06/19 10:28	General View		Load JPG	<input checked="" type="checkbox"/>					

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	19/06/19 10:28	General View	 Load JPG	<input checked="" type="checkbox"/>
45	19/06/19 10:28	General View	 Load JPG	<input checked="" type="checkbox"/>
46	19/06/19 10:28	General View	 Load JPG	<input checked="" type="checkbox"/>
47	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	21/06/19 19:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	19/09/19 17:58	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
91	19/09/19 17:58	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
92	19/09/19 17:58	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
93	19/09/19 17:58	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
94	19/09/19 17:58	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
95	19/09/19 17:58	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	13/06/19 18:11	Accident Statement	 Load HTM	<input type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	13/06/19 18:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	13/06/19 18:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	13/06/19 18:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	13/06/19 18:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	13/06/19 18:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	13/06/19 18:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	13/06/19 18:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	13/06/19 18:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	13/06/19 18:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	13/06/19 18:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	13/06/19 18:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	13/06/19 18:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	13/06/19 18:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	13/06/19 18:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	13/06/19 18:04	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	13/06/19 18:04	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>
3	13/06/19 18:04	Sketch Plan #3	 Load JPG	<input checked="" type="checkbox"/>
4	13/06/19 18:04	Sketch Plan #4	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p>Note: Remarks are private unless you show it to other parties.</p>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CT119010535/ESF3E2**Date:** 15/10/2019REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN3007581900

Claimant Vehicle No : GBC1623G Insured Vehicle No : GBE6344T

Date of Loss: 11/06/2019 Nature of Claim: TP Claim No: SNM19D202607C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBC1623G**

Make & Model: NISSAN URVAN, 3.0 5MT ABS AB 5DR LWB PANEL (A) Engine No: ZD30284008K

Reg. Date: 30/06/2011 (Man. Year: 2011) Chassis No: JN1MG4E25Z0795695

Colour: Silver Odometer: 255239 km

Engine Capacity: 2953 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C

Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	13,981.29	6,654.91	7,326.38	52.40	
Miscellaneous Items	0.00	0.00	0.00		
Labour	4,010.00	1,660.00	2,350.00	58.60	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	17,991.29	8,314.91	9,676.38	53.78	
Approved Total (Overridden) (S\$)		6,650.00			
	(S\$)	17,991.29	6,650.00	11,341.29	63.04
+ GST 7.00/7.00% (S\$)		1,259.39	465.50	793.89	63.04
Nett Amount (S\$)	19,250.68	7,115.50	12,135.18	63.04	

INSPECTION

Date of Assignment: 14/06/2019

Date Inspected: 14/06/2019 Inspected At: Teamwork Garage Pte Ltd (HQ)
53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park
Singapore 408934

Estimated Period of Repair: 7.0 days

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 15 Oct 2019)	
Parts:	N/A	NISSAN URVAN 3.0 5MT ABS AB 5DR LWB PANEL (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC1623G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	695.10 FL	*695.10 FL
2	1		*FRONT PANEL	Dented	1,675.32 FL	*1,430.00 FL
3	1		*FRONT RH CORNER PANEL	Dented	635.50 FL	*635.50 FL
4	1		*FRONT BUMPER BRACKET	O/S Broken	110.70 FL	*55.35 FL
5	2		*FRONT BUMPER RETAINER	Broken	91.70 FL	*91.70 FL
6	1		*FRONT BUMPER REINFORCEMENT	Dented	390.80 FL	*236.00 FL
7	2		*FRONT BUMPER FOG LAMP	Not Necessary	641.70 FL	*- FL
8	1		*FRONT BUMPER FOG LAMP COVER	O/S Cut	262.66 FL	*131.31 FL
9	1		*FRONT GRILLE	Broken	476.62 FL	*476.62 FL
10	1		*FRONT GRILLE EMBLEM	Necessary	66.20 FL	*66.20 FL
11	1		*FRONT SIGNAL LAMP	O/S Broken	198.90 FL	*99.45 FL
12	2		*FRONT HEADLAMP	Broken	1,048.98 FL	*1,048.98 FL
13	1		*AIRCON CONDENSER	Not Necessary	956.60 FL	*- FL
14	1		*AIRCON LIQUID PIPE	Not Necessary	93.50 FL	*- FL
15	1		*AIRCON RECEIVER DRIER	Not Necessary	218.10 FL	*- FL
16	1		*AIRCON BLOWER ASSY	Not Necessary	739.40 FL	*- FL
17	1		*AIRCON EVAPORATOR	Not Necessary	2,066.43 FL	*- FL
18	1		*AIR INTER COOLER RH	Not Necessary	2,053.67 FL	*- FL
19	1		*WIPER PANEL GARNISH	Broken	165.20 FL	*165.20 FL
20	1		*FRONT WINDSCREEN MOULDING	Necessary	108.70 FL	*108.70 FL
21	1		*FRONT DASHBOARD	Crushed	1,796.30 FL	*1,256.00 FL
22	1		*WIPER LINK ROD	Dented	272.00 FL	*272.00 FL
23	1		*FRONT PANEL INNER	Dented	526.24 FL	*526.24 FL
24	1		*SET FRONT BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
25	1		*SET FRONT GRILLE CLIP	Necessary	30.00 FS	*20.00 FS
26	1		*WINDSCREEN SEALANT	Necessary	150.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	15,510.32	7,384.35
- List Item Discount on L Items 10.00/10.00% (\$)	1,529.03	729.44
Total Parts (\$)	13,981.29	6,654.91

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK FRONT WIRING AND LIGHTING SYSTEM	New	60.00	30.00
2	REMOVE, RENEW CONDENSER AND TOP UP GAS	New	150.00	100.00
3	REMOVE AND RENEW INTERCOOLER	New	150.00	30.00
4	REMOVE AND RENEW FRONT WINDSCREEN	New	150.00	100.00
5	REMOVE AND REFIT FRONT DASHBOARD	New	500.00	100.00
6	PANEL BEATING ON AFFECTED AREAS	New	1,400.00	800.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	1,600.00	500.00
Gross Labour Cost (S\$)			4,010.00	1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >