Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19018078/APA3Q2

Date: 23/06/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00015218

Claimant

Insured Vehicle No: SLV820S SJV9236T Vehicle No:

ΤP Date of Loss: Nature of Claim: 12/10/2019 Claim No: 1201900030956

DESCRIPTION & IDENTIFICATION OF VEHICLE

SJV9236T Reg No:

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4976869

Reg. Date: 23/02/2010 (Man. Year: 2010) Chassis No: MR053ZEE106168100

Colour: Odometer: 225033 km Grey

Engine Capacity: 1598 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Rear Left Side: Falken 6 mm Falken 6 mm Front Right Side: Rear Right Side: Falken 6 mm Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,517.96	2,448.12	1,069.84	30.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,550.00	1,750.00	800.00	31.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,067.96	4,198.12	1,869.84	30.81
Approved Total (Overridden) (S\$)		3,300.00		
(S\$)	6,067.96	3,300.00	2,767.96	45.62
+ GST 7.00/7.00% (S\$)	424.76	231.00	193.76	45.62
Nett Amount (S\$)	6,492.72	3,531.00	2,961.72	45.62
+ Car Rental (8.0 x S\$100.00/day) (S\$) + Doc/Search Fee (S\$)		800.00		
		37.00		
Ne	tt Liability (S\$)	4,368.00		

INSPECTION

Date of Assignment: 14/10/2019

Date Inspected: 14/10/2019 Inspected At: Precise Auto Service (HQ)

No 1 Kaki Bukit Ave 6, #02-34/36

Singapore 417883

Estimated Period of Repair: 7.0 days Adjuster Report Page 2 of 4

Adjuster: ADRIAN LING Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 May 2020)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJV9236T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

Condition

Total Parts (S\$) 3,517.96

Repairer's

Amount

2.448.12

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts No. Qty Part No. Particulars

	αι,	i ditito.	1 di dedidi 3	Contaition	repairer 3	Amount
1	1		*REAR BUMPER FASCIA	Deformed	372.85 FL	*372.85 FL
2	2		*REAR BUMPER SIDE RETAINER -LH & RH	Necessary	264.50 FL	*114.00 FL
3	2		*REAR BUMPER SIDE ATTACHMENT -LH & RH	Not Necessary	282.80 FL	*- FL
4	10		*REAR BUMPER CLIPS	Necessary	129.00 FL	*30.00 FL
5	1		*REAR BUMPER SPONGE	Cracked	182.60 FL	*182.60 FL
6	1		*REAR BUMPER BEAM	Not Necessary	372.25 FL	*- FL
7	1		*REAR BUMPER STAY-LH & RH	N/S Bent	282.80 FL	*85.60 FL
8	1		*BOOT LID	Buckled	781.75 FL	*781.75 FL
9	1		*BOOT LID WEATHERSTRIPE	Cut	182.25 FL	*182.25 FL
10	1		*BOOT LID RUBBER STOPPER	Not Necessary	43.10 FL	*- FL
11	1		*BOOT LID EMBLEM 1.6	Necessary	41.90 FL	*41.90 FL
12	1		*BOOT LID EMBLEM COROLLA	Necessary	41.35 FL	*41.35 FL
13	1		*BOOT LID EMBLEM ALTIS	Necessary	43.10 FL	*43.10 FL
14	1		*BOOT LID BADGE	Necessary	41.10 FL	*41.10 FL
15	1		*REAR END PANEL	Dented	781.10 FL	*781.10 FL
16	1		*REAR END PANEL TOP TRIM	Deformed	289.90 FL	*289.90 FL
17	4		*REAR END PANEL TOP TRIM CLIPS	Necessary	51.60 FL	*10.00 FL
18	1		*REVERSE SENSOR WITH CONTROL UNIT	Damaged	380.00 FS	*200.00 FS
F=Fra	nchise	part. S=Spc	Nett. L=ListItemDisc.	,		
				Sub Total (S\$)	4,563.95	3,197.50
	- List Item Discount on L Items 25.00/25.00% (S\$)			1,045.99	749.38	
				,		

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WIRING SYSTEM	New	50.00	30.00
2	TO TUFF COAT AFFECTED AREAS	New	180.00	60.00
3	TO REMOVE & REFIX INTERIOR UPHOLSTERY	New	120.00	60.00
4	TO REMOVE & REFIX REVERSE SENSOR	New	120.00	50.00
5	TO REMOVE & REFIX BOOT LID MECHANISM	New	180.00	50.00
6	TO RESPRAY AFFECTED AREAS	New	1,000.00	800.00
7	TO RENEW DAMAGES PARTS ,STRAIGHTEN & REPAIR & ALIGNED ALL PARTS	New	900.00	700.00
	Gross Labour Cost (S\$)		2,550.00	1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >