

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315





ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8565Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	553.00	-
10	REAR BUMPER CLIPS	NOT NECESSARY	22.00	-
1	REAR DOOR (LH)	TO REPAIR SEE LABOUR	2,201.10	-
1	LH ROCKER PANEL (OUTER) (NPA)	TO REPAIR SEE LABOUR	-	-
1	LH FRONT DOOR (NPA)	TO REPAIR SEE LABOUR	-	-
1	LH REAR FENDER (NPA)	TO REPAIR SEE LABOUR	-	-
1	LH REAR RIM COVER	SCRATCHED	107.10	107.10
	LESS 20% DISCOUNT		-576.64	-21.42
			2,306.56	85.68
	SPECIAL NETT ITEMS			
1	REAR DOOR COMFORTDELGRO & APPS STICKER (LH) (SN)	NECESSARY	80.00	72.00
1	FRONT DOOR COLOURED COMFORT LOGO (LH) (SN)	NECESSARY	75.00	67.50
			155.00	139.50
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER, REAR DOOR (LH), LH ROCKER PANEL (OUTER), LH FRONT DOOR AND LH REAR FENDER.		560.00	420.00
	SPRAY PAINTING CHARGE.		800.00	800.00
	TUFF KOTE.	NOT NECESSARY	50.00	-
	TRANSFER OF DOOR.	NOT NECESSARY	80.00	-
	REAR WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
			1,570.00	1,220.00
	GRAND TOTAL		4,031.56	1,445.18

RECOMMENDED COST OF LUMP SUM REPAIRS		1,150.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC19018113/Fsf3s2





Report Ref No. NS/INC19018113/Fsf3s2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

Th

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser