

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/MSG19013095/R1TF3E2-1**Date:** 17/10/2019REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 27413149

Claimant
Vehicle No : SLB4940H**Insured Vehicle No :** SGH3266E

Date of Loss: 18/07/2019

Nature of Claim: TP Claim No: 600489

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLB4940H**

Make & Model: MERCEDES-BENZ E200, 2.0 (A)

Engine No: 27186030200056

Reg. Date: 30/06/2011 (Man. Year: 2011)

Chassis No: WDD2120482A398580

Colour: Grey

Odometer: 74047 km

Engine Capacity: 1796 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45Z R17 Rear Tyre Size: 245/45Z R17

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,621.78	500.00	7,121.78	93.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,260.00	1,020.00	1,240.00	54.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	9,881.78	1,520.00	8,361.78	84.62

INSPECTION

Date of Assignment: 24/07/2019

Date Inspected: 30/07/2019 Inspected At:

Ghee Seng Paint Spraying Works -
Buroh (HQ)
10 BUROH STREET, #08-22 WEST
CONNECT BUILDING
Singapore 627564

Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Oct 2019)
Parts: 143	MERCEDES-BENZ E200 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB4940H)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR O/S DOOR	Repair	2,279.00 F	*- FN
2	1		*REAR O/S FENDER	Repair	2,297.70 F	*- FN
3	1		*REAR BUMPER	Repair	2,067.00 F	*- FN
4	1		*REAR O/S WHEEL RIM (ORIGINAL)	Dented/Warped	978.08 FS	*500.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	7,621.78	500.00
- Nett Item Discount on N Items 0.00/10.00% (S\$)	0.00	0.00
Total Parts (S\$)	7,621.78	500.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE THE NECESSARY AFFECTED PARTS,STRAIGHTEN REAR O/S FENDER AND WHEEL ARCH,REPAIR REAR BUMPER AND REPLACE PARTS	New	980.00	300.00
2	PUTTY AND SPRAYPAINT ON ALL AFFECTED PARTS	New	800.00	600.00
3	CHECK ELECTRICAL	New	100.00	0.00
4	REMOVE AND REFIT REAR O/S DOOR PARTS	New	150.00	0.00
5	RESET WHEEL ALIGNMENT	New	100.00	60.00
6	TUFF KOTE	New	100.00	40.00
7	REMOVE AND REFIT REAR O/S WHEEL RIM	New	30.00	20.00
			Gross Labour Cost (\$\$)	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >