

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19018135/ABA3Q2

Date: 16/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800128688-01

Claimant
Vehicle No : SJG751K **Insured Vehicle No :** SMF1531S

Date of Loss: 13/10/2019 **Nature of Claim:** TP **Claim No:** 3894250043SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJG751K	Engine No:	1NZX768942
Make & Model:	TOYOTA VIOS, 1.5 (A)	Chassis No:	MR053HY9305068928
Reg. Date:	20/06/2008 (Man. Year: 2008)	Odometer:	369489 km
Colour:	Black		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,404.53	4,549.62	3,854.91	45.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,960.00	1,830.00	2,130.00	53.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,364.53	6,379.62	5,984.91	48.40
Approved Total (Overridden) (S\$)		5,100.00		
Nett Amount (S\$)	12,364.53	5,100.00	7,264.53	58.75
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,507.45		
Global Sum Settlement (S\$)		5,500.00		

INSPECTION

Date of Assignment: 14/10/2019

Date Inspected: 14/10/2019 Inspected At:

Premium Carz Services Pte Ltd (HQ)
1 Kaki Bukit Ave 6 #01-90
Autobay@Kaki
Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH (NPA)	Not Necessary	0.00 FL	*- FL
2	1		*FRONT FENDER LH	Dented	565.00 FL	*565.00 FL
3	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	181.80 FL	*- FL
4	1		*FRONT FENDER INNER SHIELD LH	Torn	181.80 FL	*181.80 FL
5	1		*FRONT FENDER VVTI EMBLEM RH	Not Necessary	48.60 FL	*- FL
6	1		*FRONT FENDER VVTI EMBLEM LH	Necessary	48.60 FL	*48.60 FL
7	1		*FRONT WHEELHOUSE LH (NPA)	Repair	0.00 FL	*- FL
8	1		*FRONT KNUCKLE ARM LH	Not Necessary	455.00 FL	*- FL
9	1		*FRONT KNUCKLE ARM BEARING LH	Not Necessary	355.00 FL	*- FL
10	1		*FRONT LOWER ARM LH	Not Necessary	980.00 FL	*- FL
11	1		*FRONT ABSORBER LH	Not Necessary	445.00 FL	*- FL
12	1		*FRONT BUMPER	Distorted	531.20 FL	*531.20 FL
13	1		*FRONT BUMPER SIDE RETAINER RH	Not Necessary	66.20 FL	*- FL
14	1		*FRONT BUMPER SIDE RETAINER LH	Damaged	66.20 FL	*66.20 FL
15	1		*FRONT BUMPER LOWER LID	Cracked	625.73 FS	*550.00 FS
16	1		*FRONT BUMPER LOWER GRILLE	Cracked	85.40 FL	*85.40 FL
17	1		*FOG LAMP LH	Cut	267.80 FL	*267.80 FL
18	1		*FOG LAMP CHROME LH	Not Necessary	121.30 FL	*- FL
19	1		*FOG LAMP GARNISH LH	Deformed	151.30 FL	*151.30 FL
20	1		*FRONT BUMPER REINFORCEMENT	Bent	391.80 FL	*391.80 FL
21	1		*HEADLAMP RH	Not Necessary	461.80 FL	*- FL
22	1		*HEADLAMP LH	Cracked	461.80 FL	*461.80 FL
23	1		*HEADLAMP TOP BRACKET LH	Bent	90.50 FL	*90.50 FL
24	1		*FRONT GRILLE	Not Necessary	265.00 FL	*- FL
25	1		*FRONT GRILLE CHROME (NPA)	Not Necessary	0.00 FL	*- FL
26	1		*FRONT GRILLE TOYOTA LOGO	Not Necessary	55.20 FL	*- FL
27	1		*BONNET	Dented	581.90 FL	*581.90 FL
28	1		*BONNET STAND (NPA)	Not Necessary	0.00 FL	*- FL
29	1		*BONNET STAND CLIP (NPA)	Not Necessary	0.00 FL	*- FL
30	2		*BONNET HINGES	Bent	110.00 FL	*110.00 FL
31	1		*BONNET LOCK	Damaged	80.20 FL	*80.20 FL
32	1		*AIR FILTER HOUSING	Cracked	477.80 FL	*477.80 FL
33	1		*FUSE BOX	Cracked	388.50 FL	*388.50 FL
34	1		*WIPER GARNISH LH	Cut	38.50 FL	*38.50 FL
35	1		*SUPPORT SIDE PANEL BRACKET LH	Bent	58.90 FL	*58.90 FL
36	1		*SUPPORT SIDE PANEL LH (NPA)	Repair	0.00 FL	*- FL
37	1		*ENGINE UNDER COVER (NPA)	Not Necessary	0.00 FL	*- FL
38	1		*AIR BAG SENSOR LH	Cracked	245.40 FL	*245.40 FL
39	1		*FRONT TYRE LH	Not Necessary	350.00 FS	*- FS
40	1		*FRONT RIM LH	Not Necessary	550.00 FS	*- FS
41	10		*FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
42	8		*FRONT GRILLE CLIP	Not Necessary	40.00 FS	*- FS
43	8		*SUPPORT PANEL GARNISH CLIP	Not Necessary	40.00 FS	*- FS
44	10		*ENGINE UNDER COVER CLIP	Not Necessary	50.00 FS	*- FS
45	1		*FRONT FENDER INNER SHIELD CLIP (16 PCS)	Necessary	80.00 FS	*30.00 FS
46	1		*COOLANT	Necessary	80.00 FS	*40.00 FS
47	1		*FOG LAMP BULB LH	Not Necessary	18.00 FS	*- FS
48	1		*HEADLAMP BULB LH	Not Necessary	15.00 FS	*- FS
49	1		*SIGNAL BULB LH	Not Necessary	15.00 FS	*- FS
50	1		*LIGHT BULB LH	Not Necessary	15.00 FS	*- FS
51	1		*FRONT CHASSIS EXTENSION LH	Bent	376.90 FL	*376.90 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Sub Total (S\$)					10,563.13	5,849.50
- List Item Discount on L Items 25.00/25.00% (S\$)					2,158.60	1,299.88
Total Parts (S\$)					8,404.53	4,549.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING AND REFOCUS HEADLAMP	New	80.00	30.00
2	PANEL BEATING CHARGES TO REMOVE AND REPLACE ,TO CUT AND WELD ,TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS	New	1,200.00	800.00
3	SPRAY PAINTING ALL AFFECTED PARTS & AREAS	New	1,400.00	800.00
4	TO KNOCK AND RESHAPE FRONT CHASSIS LH	New	250.00	0.00
5	TO SPRAY ANTI-RUST UNDERCOAT	New	90.00	80.00
6	TO CHECKAND ALIGN WHEELS WITH COMPUTERIZED WHEEL ALIGNMENT	New	120.00	0.00
7	TO CUT AND WELD ,TO KNOCK AND RESHAPE FRONT SUPPORT PANEL AND FRONT WHEELHOUSE LH PANEL	New	350.00	0.00
8	TO REMOVE AND REFIT RADIATOR AND AIR-CON CONDENSER ,TO CHARGE UP AIR CON GAS TO FACILITATE WITH REPAIR	New	250.00	120.00
9	TO REMOVE AND REPLACE FRONT LH UNDERCARRIAGE AND SUSPENSION PARTS	New	220.00	0.00
Gross Labour Cost (\$)			3,960.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >