

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19018148/HGA3Q2
Date: 15/06/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	YP3469G	Insured Vehicle No :	SHA6774K
Date of Loss:	07/10/2019	Nature of Claim:	TP
		Claim No:	MCT19100169

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP3469G	Engine No:	6M60215179
Make & Model:	MITSUBISHI FUSO, 7.5 D FK62FMZ1RDEB (M)	Chassis No:	FK62FMA30111
Reg. Date:	04/08/2016 (Man. Year: 2016)	Odometer:	78256 km
Colour:	White		
Engine Capacity:	7545 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/70 R19.5	Rear Tyre Size:	245/70 R19.5
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,870.00	1,550.00	7,320.00	82.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	700.00	1,200.00	63.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,770.00	2,250.00	8,520.00	79.11
Approved Total (Overridden) (S\$)		1,800.00		

(S\$)	10,770.00	1,800.00	8,970.00	83.29
+ GST 7.00/7.00% (S\$)	753.90	126.00	627.90	83.29
Nett Amount (S\$)	11,523.90	1,926.00	9,597.90	83.29
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		2,355.00		

INSPECTION

Date of Assignment: 14/10/2019

Date Inspected: 15/10/2019

Estimated Period of Repair: 3.0 days

Inspected At:

Focus Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #02-48/50 Autobay
 Singapore 417883

Adjuster: LEE HOCK ANN**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Apr 2021)	
Parts:	N/A	MITSUBISHI FUSO 7.5 D FK62FMZ1RDEB (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP3469G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PROTECTOR BAR-RH	Bent	750.00 FS	*400.00 FS
2	2		*PROTECTOR BRACKET -RH	Bent	500.00 FS	*300.00 FS
3	1		*CRANEL STAY HYDRAULIC PUMP (LOCAL REPAIR)	Damaged	6,500.00 FS	*600.00 FS
4	4		*LITER HYDRAULIC PUMP OIL -RH	Damaged	1,120.00 FS	*250.00 FS
					Total Parts (\$)	8,870.00
						1,550.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	450.00	200.00
2	TO REMOVE & REPLACE HYDRAULIC	New	1,200.00	300.00
3	TO SPRAY PAINTING	New	250.00	200.00
Gross Labour Cost (\$\$)			1,900.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >