

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





Accident Photo




)

Accident Photo



Accident Photo



)

Accident Photo



Accident Photo



Accident Photo





## BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28  
(Unit C) #01-51/53/55 Singapore 417883  
Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088  
Website: [www.bluwel.com.sg](http://www.bluwel.com.sg) Email: [bluwel2088@yahoo.com.sg](mailto:bluwel2088@yahoo.com.sg)  
Co. Reg. No.: 200704951N  
GST Reg. No.: 200704951N

Vehicle No : SMC 1138 K Date : 24-Sep-19  
Make/Model : Volkswagen Golf  
Name : Ong Kar Chye  
Address : c/o No.1 Kaki Bukit Ave 6  
#01-53/55 AutoBay@ Kaki Bukit  
Singapore 417883

QTY	ITEM	AMT (\$S)
-----	------	-----------

Lump sum repair costs	\$	9,500.00
GST 7 %	\$	665.00
Grand-total	\$	<u>10,165.00</u>

Dollars : Ten Thousand One Hundred And Sixty Five Only

# MC-COY

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883  
Tel: 6748 6653 Fax: 67471017 Registration No: 200725252D

Billing Name & Address

Ong Kar Chye  
c/o No.1 Kaki Bukit Ave 6  
#01-53/55 AutoBay@ Kaki Bukit  
Singapore 417883

Invoice No 19011-09/AY

Date 24 Sep 2019

Vehicle No : SMC 1138 K

Model : Volkswagen Golf

Item	Descriptions	Amount S\$
1	Date of inspection : <u>11 Sep 2019</u> A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Develop photographs - Storage of digital photographs - Submission of photographs <u>129</u> copies	
3	Transportation Charges	
4	2nd Inspection & Final Inspection	
	Total	<u>\$ 829.00</u>
	SDLS : EIGHT HUNDRED AND TWENTY-NINE ONLY	

Notes :

1. All cheque payment should be "Crossed" and made payable to "Mc-Coy Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



Official Stamp

E & O E





No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883  
Tel: 6748 6653 Fax: 67471017 Registration No: 200725252D

Report Reference : TP / 19011-09/AY / 2019  
Date of Report : 24 Sep 2019

Ong Kar Chye  
c/o No.1 Kaki Bukit Ave 6  
#01-53/55 AutoBay@ Kaki Bukit  
Singapore 417883

**THIRD PARTY SURVEY**  
**ACCIDENT HAPPENED ON 7 Sep 2019**

Workshop Address : Bluwel Automotive Service Pte Ltd  
No.1 Kaki Bukit Ave 6  
#01-53/55 AutoBay@ Kaki Bukit  
Singapore 417883

As per your instruction dated **11 Sep 2019** with regard to the above matter. We have carried out a physical inspection on the said vehicle **SMC 1138 K**. We enclosed herewith our report and findings as follows:

**1. VEHICLE PARTICULARS**

Registration No	: SMC 1138 K	Engine No	: CZD512309
Model	: Volkswagen Golf	Mileage	: 60816
Year / Capacity	: 2016/1395	Colour	: White
Chassis No	: WVVZZZAUZGW274713		

**2. TYRES CONDITION**

	<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT O/S	: 235/40 R18	Yokohama	4.00	mm	Sport
REAR O/S	: 235/40 R18	Yokohama	4.00	mm	Sport
FRONT N/S	: 235/40 R18	Yokohama	4.00	mm	Sport
REAR N/S	: 235/40 R18	Yokohama	4.00	mm	Sport



No. 1 Kaki Bukit Ave 6 #01-26 AutoBay @ Kaki Bukit Singapore 417883  
Tel: 6748 6659 Fax: 67471017 Registration No: 200725252D

### 3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the front portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 8 working days to complete.
5. Enclosed number of photograph : 129 copies.
6. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey was done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.
7. Should you discover any discrepancy in the report, please kindly notify us within 2 weeks, or the report will be treated as correct.

#### Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: SMC 1138 K  
Report No: TP/ 19011-09/AY / 2019

# SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Bonnet	SMC Damage	\$ 1380.97	\$ 1380.97
1	Bonnet lock	SMC Damage	\$ 230.76	\$ 230.76
1	Bonnet rubber	SMC Damage	\$ 129.75	\$ 129.75
2	Front headlamps	CNE Damage	\$ 4019.42	\$ 4019.42
1	Front bumper	1076.45 DO/DE Damage	\$ 1600.91	\$ 1600.91
1	Front bumper top beam	DD Damage	\$ 189.30	\$ 189.30
1	Front bumper bracket	Set Damage	\$ 61.30	\$ 61.30
1	Front bumper o/s fog lamp	CNE Damage	\$ 291.75	\$ 291.75
1	Front bumper o/s fog lamp cover	SCR Damage	\$ 68.90	\$ 68.90
1	Front bumper lower grille	TOA Damage	\$ 366.93	\$ 366.93
1	Front bumper side retainer	Set Necessary	\$ 79.80	\$ 79.80
1	Front bumper nozzle pen	SMC Damage	\$ 211.70	\$ 211.70
1	Front bumper inner sponge	TOA Damage	\$ 139.86	\$ 139.86
2	Front bumper sensors	208.85 SHD Damage	\$ 439.40	\$ 439.40
2	Front fenders	R Repair	\$ 1598.60	\$ 1598.60
1	Front bumper centre chrome	NT Damage	\$ 214.40	\$ 214.40
1	Front bumper o/s side chrome	NT Damage	\$ 163.30	\$ 163.30
Discount 10.0%			\$ 11187.05	\$ 9588.45
			\$ 1118.71	\$ 958.85
			\$ 10068.34	\$ 8629.60
<u>Special Nett Items</u>				
2	Front headlamp lips (2 set)	SMC Necessary	\$ 400.00	\$ 400.00
1	Front grille	CNE Damage	\$ 950.00	\$ 950.00
1	Front number plate	CNE Damage	\$ 80.00	\$ 80.00
			\$ 1430.00	\$ 1430.00

8244.04  
102  
7419.63

Spare Parts Total \$ 11498.34 \$ 10059.60

Vehicle No: SMC 1138 K  
Report No: TP/ 19011-09/AY / 2019

**LABOUR COST**

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 11498.34	\$ 10059.60
1	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$ 50.00	\$ 40.00 30
2	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 1100.00	\$ 880.00 600
3	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1100.00	\$ 880.00 780
4	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 150.00	\$ 30.00
Total		\$ 13898.34	\$ 11889.60

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 9500.00

(0000.00)

SDLS: NINE THOUSAND FIVE HUNDRED ONLY

  
Qualified Appraiser

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Sep 2019		10 Sep 2019 15:29 <a href="#">Edit Adj Rpt</a>	<b>S\$8,000.00</b> <a href="#">Edit Estimates</a>	<b>S\$8,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>AHMAD SAIFUL RIJAL BIN HASSAN</b> , ID: S8615726H								
Main Claimant:	<b>ONG KAR CHYE</b> , ID: S1542185A								
Vehicle Reg. No.:	<b>SMC1138K</b>	Date of Loss:	07/09/2019 23:00 - :59 [39 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / CMTD1904271</b>	Policy/Cover Note No.:	D18MTPV01014494 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SJT2676M</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Bluwel Automotive Service Pte Ltd (HQ)</b> 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088								
Handling Insurer:	<b>Sompo Insurance Singapore Pte. Ltd. (HQ)</b> - Tel: 6461 6555 ... [Handled by <b>Ruth Chua Gek Tiang</b> - 6329 5153]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... <b>[Final Rpt due 19/09/2019]</b>								
Driver/Custodian (Insured):	MUHAMMAD SIDDIQ MASHKUR BIN HASSAN (), NRIC: S9349711B, Tel: +6596170725 Email:								
Adj Asg. Remarks:	WS: SALLY 67452088								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SMC1138K (CMTD1904271)**

**[SJT2676M]**

**TP**

**ONG KAR CHYE**

**Sep 7 2019 11:00PM**

**[AHMAD SAIFUL RIJAL BIN HASSAN]**


















































**Bluwel Automotive Service Pte Ltd**

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports			1 per page ▼	✓
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	10/09/19 15:27	<b>Accident Statement</b> From:SC - Reg. No: SJT2676M, Claimant: AHMAD SAIFUL RIJAL BIN HASSAN	1 Load HTM	
Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
2	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
3	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
4	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
5	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
6	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
7	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
8	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
9	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
10	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
11	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
12	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
13	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
14	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
15	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
16	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
17	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
18	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
19	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
20	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
21	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
22	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
23	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
24	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
25	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
26	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
27	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
28	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
29	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
30	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
31	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
32	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
33	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
34	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
35	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓
36	27/09/19 08:55	<b>General View</b>	1 Load JPG	✓



Assessment Reports			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
37	27/09/19 08:55	General View	 Load JPG	<input checked="" type="checkbox"/>
38	27/09/19 08:55	General View	 Load JPG	<input checked="" type="checkbox"/>
39	27/09/19 08:55	General View	 Load JPG	<input checked="" type="checkbox"/>
40	27/09/19 08:55	General View	 Load JPG	<input checked="" type="checkbox"/>
41	27/09/19 08:55	General View	 Load JPG	<input checked="" type="checkbox"/>
42	27/09/19 08:55	General View	 Load JPG	<input checked="" type="checkbox"/>
43	27/09/19 08:55	General View	 Load JPG	<input checked="" type="checkbox"/>
44	27/09/19 08:55	General View	 Load JPG	<input checked="" type="checkbox"/>
45	27/09/19 08:55	General View	 Load JPG	<input checked="" type="checkbox"/>
46	27/09/19 08:55	General View	 Load JPG	<input checked="" type="checkbox"/>
47	27/09/19 08:55	General View	 Load JPG	<input checked="" type="checkbox"/>
48	27/09/19 08:55	General View	 Load JPG	<input checked="" type="checkbox"/>
49	27/09/19 08:55	General View	 Load JPG	<input checked="" type="checkbox"/>
50	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	27/09/19 08:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	27/09/19 08:56	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>



## Documents Checklist

[https://singapore.merlmen.com/claims/index.cfm?fusebox=MTRdoc&fuseaction=dsp\\_docview&domainid=1&corole=4&objid=865014&extid=3164...](https://singapore.merlmen.com/claims/index.cfm?fusebox=MTRdoc&fuseaction=dsp_docview&domainid=1&corole=4&objid=865014&extid=3164...) 3/3

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/SMO19016045/UVF3S2-1  
**Date:** 18/10/2019

## REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D18MTPV01014494  
**Claimant Vehicle No :** SMC1138K **Insured Vehicle No :** SJT2676M  
Date of Loss: 07/09/2019 Nature of Claim: TP Claim No: CMTD1904271

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SMC1138K**  
Make & Model: VOLKSWAGEN GOLF, 1.4 (A) Engine No: CZD512309  
Reg. Date: 25/05/2016 (Man. Year: 2016) Chassis No: WVVZZZAUZGW274713  
Colour: White Odometer: 60816 km  
Engine Capacity: 1395 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 235/40 R15 Rear Tyre Size: 235/40 R15  
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm  
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,498.34	8,569.64	2,928.70	25.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	1,440.00	960.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,898.34</b>	<b>10,009.64</b>	<b>3,888.70</b>	<b>27.98</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>8,000.00</b>		
<b>(S\$)</b>	13,898.34	8,000.00	5,898.34	42.44
<b>+ GST 7.00/7.00% (S\$)</b>	972.88	560.00	412.88	42.44
<b>Nett Amount (S\$)</b>	<b>14,871.22</b>	<b>8,560.00</b>	<b>6,311.22</b>	<b>42.44</b>

## INSPECTION

Date of Assignment: 10/09/2019

Date Inspected: 11/09/2019 Inspected At:

Estimated Period of Repair: 6.0 days

Bluwel Automotive Service Pte Ltd (HQ)  
1 Kaki Bukit Avenue 6, #01-28/37/53/55/56  
Autobay@Kaki Bukit  
Singapore 417883

**Adjuster:** MARCUS CHUA

**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 18 Oct 2019)
<b>Parts:</b> 144	VOLKSWAGEN GOLF 1.4 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMC1138K)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	1,380.97 FL	*1,380.97 FL
2	1		*BONNET LOCK	Twisted	230.76 FL	*230.76 FL
3	1		*BONNET RUBBER	Necessary	129.75 FL	*129.75 FL
4	2		*FRONT HEADLAMPS	Cracked	4,019.42 FL	*4,019.42 FL
5	1		*FRONT BUMPER	Dented / Deformed	1,600.91 FL	*1,076.45 FL
6	1		*FRONT BUMPER TOP BEAM	Dented	189.30 FL	*189.30 FL
7	1		*FRONT BUMPER BRACKET	Bent	61.30 FL	*61.30 FL
8	1		*FRONT BUMPER O/S FOG LAMP	Cracked	291.75 FL	*291.75 FL
9	1		*FRONT BUMPER O/S FOG LAMP COVER	Scratched	68.90 FL	*68.90 FL
10	1		*FRONT BUMPER LOWER GRILLE	Torn	366.93 FL	*366.93 FL
11	1		*FRONT BUMPER SIDE RETAINER	Bent	79.80 FL	*79.80 FL
12	1		*FRONT BUMPER NOZZLE PEN	Serviceable	211.70 FL	*- FL
13	1		*FRONT BUMPER INNER SPONGE	Torn	139.86 FL	*139.86 FL
14	1		*FRONT BUMPER SENSORS	Shorted 1pc Only	439.40 FL	*208.85 FL
			2pcs			
15	1		*FRONT FENDERS	Repair	1,598.60 FL	*- FL
16	1		*FRONT BUMPER CENTRE CHROME	Not fitted	214.40 FL	*- FL
17	1		*FRONT BUMPER O/S SIDE CHROME	Not fitted	163.30 FL	*- FL
18	2		*SET FRONT HEADLAMP LIPS	Necessary	400.00 FS	*300.00 FS
19	1		*FRONT GRILLE	Cracked	950.00 FS	*800.00 FS
20	1		*FRONT NUMBER PLATE	Cracked	80.00 FS	*50.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>12,617.05</b>	<b>9,394.04</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	<b>1,118.71</b>	<b>824.40</b>
<b>Total Parts (S\$)</b>	<b>11,498.34</b>	<b>8,569.64</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIT DAMAGE PARTS, TEST FOR PROPER FUNCTIONING AND FOCUS OF HEADLAMPS.	New	50.00	30.00
2	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.	New	1,100.00	600.00
3	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.	New	1,100.00	780.00
4	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.	New	150.00	30.00
Gross Labour Cost (S\$)			2,400.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >