



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 3940B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT FENDER LH	DENTED	2,855.00	1,365.00
1	FRONT FENDER INNER SHIELD LH	BROKEN	1,355.00	355.00
1	FRONT DOOR LH	BENT	863.00	863.00
1	FRONT DOOR UPPER HINGE LH	SERVICEABLE	142.00	-
1	FRONT DOOR LOWER HINGE LH	SERVICEABLE	210.00	-
1	FRONT SPORT RIM LH	SCRATCHED	145.00	145.00
1	FRONT LOWER ARM RH	SERVICEABLE	650.00	-
1	FRONT KNUCKLE ARM RH	SERVICEABLE	580.00	-
1	FRONT KNUCKLE BEARING RH	SERVICEABLE	433.00	-
1	FRONT ABSORBER RH	SERVICEABLE	598.00	-
	LESS 20% DISCOUNT		-1,566.20	-545.60
			6,264.80	2,182.40
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT LH TYRE (SN)	SERVICEABLE	250.00	-
			250.00	-
	<b><u>LABOUR</u></b>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS.		1,000.00	400.00
	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR.	NOT NECESSARY	250.00	-
	WHEEL ALIGNMENT.		120.00	60.00
	TO TRANSFER MECHANICAL PART TO NEW FRONT DOOR ASSY.		200.00	60.00
	TO REMOVE AND REPLACE FRONT & REAR TYRE & SPORT RIMS AND CONDUCT WHEEL BALANCING.		120.00	30.00
	TO REMOVE AND REFIX FRONT UNDERCARRIAGE.	NOT NECESSARY	250.00	-
	TO REMOVE / REFIX WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS.		150.00	30.00
	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED.		600.00	400.00
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS.		100.00	30.00

Report Ref No. CS/INC19018163/Qtf3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY UNDERCOATING ON PARTS REPLACED.		100.00	30.00
			2,890.00	1,040.00
GRAND TOTAL			9,404.80	3,222.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,550.00

Report Ref No. CS/INC19018163/Qtf3e2

OI SUN PIN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.