

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

GK21202609

TAN PUAY SEE ALICE
BLK 537 HOUGANG ST 52
#15-92
S 530537

TPAXA
Xiao Tony

Date :18.10.2019
Vehicle No :SMA 8547 C
Make/Model :HONDA SHUTTLE
Accident date :11.10.2019

No	DESCRIPTION	Qty	Amount (\$\$)
List Items			
1	Rear windscreen rubber <i>new</i>	1	\$ 71.5 ✓
2	Rear tailgate <i>Distorted</i>	1	\$ 1078 ✓
3	Rear tailgate hinges @ \$ 90.20 <i>Hse Nec</i>	2	\$ 180.4 X
4	Rear tailgate shock absorber @ \$ 198.00 <i>Hse Nec</i>	2	\$ 396 X
5	Rear tailgate upper lock <i>Damaged</i>	1	\$ 159.5 ✓
6	Rear tailgate lower lock <i>new</i>	1	\$ 104.5 X
7	Rear tailgate weather strip <i>ht</i>	1	\$ 118.8 ✓
8	Rear tailgate inner board <i>could</i>	1	\$ 341 ✓
9	Rear tailgate H emblem <i>Nec</i>	1	\$ 41.8 ✓
10	Rear tailgate handle <i>new</i>	1	\$ 170.5 X
11	Rear tailgate Shuttle emblem <i>Nec</i>	1	\$ 50.6 ✓
12	Rear Dream sticker <i>Nec</i>	1	\$ 82.5 50(SN)
13	Rear tailgate reflector @ \$ 341.00 <i>LH ut</i>	2	\$ 682 341
14	Rear tailgate inner handle <i>new</i>	1	\$ 42.9 X
15	Rear tailgate side moulding <i>new</i>	1	\$ 99 ✓
16	Rear lamp @ \$ 506.00 <i>new</i>	2	\$ 1032 X
17	Rear end panel <i>Scuffed</i>	1	\$ 484 ✓
18	Rear end panel inner top garnish <i>Sehnd</i>	1	\$ 121 ✓
19	Rear bumper <i>Deformed</i>	1	\$ 979 ✓
20	Rear bumper side holder @ \$ 41.80 <i>Nec</i>	2	\$ 83.6 ✓
21	Rear bumper side reflector @ \$ 53.90 <i>new</i>	2	\$ 107.8 X
22	Rear bumper side reflector garnish @ \$ 53.90 <i>LH Deformed</i>	2	\$ 107.8 53.90
23	Rear bumper clips (1 set) <i>Nec</i>	1	\$ 66 30
24	Rear bumper LH side inner rubber <i>could</i>	1	\$ 75.9 X
25	Rear LH side lower cover <i>Delid</i>	1	\$ 214.5 ✓
26	Rear fender inner side garnish @ \$ 539.00 <i>LH Delid</i>	2	\$ 1078 355
27	Rear spare tyre top board <i>Delid</i>	1	\$ 429 295
28	Rear spare tyre top tool board <i>could</i>	1	\$ 429 ✓
29	Rear spare tyre well <i>Repair</i>	1	\$ 1760 X
			\$ 10586.6
			\$ 2117.3
			\$ 8469.3

5426.10
4340.88

Less 20% Disc

Total

S N: 50

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

TAN PUAY SEE ALICE
BLK 537 HOUGANG ST 52
#15-92
S 530537

Date :18.10.2019
Vehicle No :SMA 8547 C
Make/Model :HONDA SHUTTLE
Accident date :11.10.2019

No	DESCRIPTION	Qty	Amount (\$)
----	-------------	-----	-------------

Special Nett Items

1	Rear bumper reverse sensor (1 set) <i>Damaged</i>		\$ 380-200
2	Rear camera <i>Damaged</i>		\$ 800 450
	Total		\$ 1180

Labour Cost

1	To supply rear windscreen sealant		\$ 50 ✓
2	To supply rear end panel inner sealant		\$ 200-60
3	Remove & reinstall rear windscreen		\$ 150-120
4	Remove & reinstall bootlid inner garnish		\$ 200-80
5	Remove & reinstall reverse sensor		\$ 150-50
6	Remove & reinstall exhaust pipe	2470	\$ 100 *
7	Remove ,replace & repair consistent to the accident		\$ 1800 1000
8	Respray painting		\$ 1300 1000
9	Tuff kote		\$ 150-60
10	Remove and reinstall rear camera <i>150 50</i>		\$ 150-60
	Total		\$ 4100

Grand Total \$ 13749.3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 7510.88

4/5 6k

06 Days