

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG19018179/ATF3E2
Date: 16/12/2020

REFERENCE

Insured/Claimant: WU WENXIAN Policy No: 1800128688-01
Date of Loss: 13/10/2019 Nature of Claim: OD Claim No: 3894250043SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMF1531S**
Make & Model: AUDI Q2, 1.4 (A) Engine No: CZE841731
Reg. Date: 29/10/2018 (Man. Year: 2018) Chassis No: WAUZZZGAXKA004650
Colour: Silver Odometer: 14143 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$113,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,848.00	11,748.80	7,099.20	37.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,152.00	6,152.00	7,000.00	53.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,000.00	17,900.80	14,099.20	44.06
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	31,600.00	17,500.80	14,099.20	44.62
+ GST 7.00/7.00% (S\$)	2,212.00	1,225.06	986.94	44.62
Nett Amount (S\$)	33,812.00	18,725.86	15,086.14	44.62

INSPECTION

Date of Assignment: 15/10/2019
Date Inspected: 15/10/2019 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 10.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,706.00 FS	*1,364.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	314.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTER	Cracked	179.00 FS	*143.20 FS
4	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Distorted	154.00 FS	*122.80 FS
5	1		*FRONT BUMPER END CAP - RH	Broken	31.00 FS	*24.40 FS
6	1		*FRONT BUMPER SPOILER	Deformed	273.00 FS	*218.00 FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Broken	142.00 FS	*113.20 FS
8	1		*FRONT WHEEL SPOILER - RH	Not Necessary	31.00 FS	*- FS
9	1		*FRONT BUMPER ADAPTER - RH	Broken	38.00 FS	*30.32 FS
10	1		*RADIATOR GRILLE	Cracked	1,301.00 FS	*1,040.80 FS
11	1		*RADIATOR GRILLE STRIKER PLATE	Broken	114.00 FS	*91.20 FS
12	1		*FRONT BUMPER CARRIER	Dented	625.00 FS	*499.60 FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	71.00 FS	*56.08 FS
14	1		*FRONT BUMPER TOP COVER	Deformed	91.00 FS	*72.56 FS
15	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	32.00 FS	*- FS
16	1		*AC STICKER	Necessary	7.00 FS	*5.12 FS
17	1		*CAUTION SIGN STICKER	Necessary	13.00 FS	*9.76 FS
18	1		*SIGNAL HORN - RH HIGH TONE	Cracked	180.00 FS	*143.60 FS
19	1		*SPRING SHACKLE - RH	Bent	29.00 FS	*22.72 FS
20	1		*FRONT FENDER - RH	Not Necessary	1,047.00 FS	*- FS
21	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	36.00 FS	*- FS
22	1		*FRONT FENDER BRACKET - RH	Not Necessary	43.00 FS	*- FS
23	1		*FRONT FENDER TOP BRACKET - RH	Not Necessary	14.00 FS	*- FS
24	1		*FRONT FENDER BRACE - RH	Not Necessary	29.00 FS	*- FS
25	1		*FRONT FENDER BRACKET	Not Necessary	21.00 FS	*- FS
26	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	183.00 FS	*146.00 FS
27	1		*FRONT WHEEL HOUSING ATTACHMENT PARTS	Not Necessary	52.00 FS	*41.20 FS
28	1		*HEADLIGHT MOUNTING - RH	Cracked	107.00 FS	*85.60 FS
29	1		*LED HEADLIGHT - RH	Cut	4,491.00 FS	*3,592.80 FS
30	1		*MAIN LIGHT ELECTRONIC POWER MODULE	Not Necessary	693.00 FS	*- FS
31	1		*LED WITH HEAT SINK - RH	Not Necessary	666.00 FS	*- FS
32	1		*LIGHT CONTROL SYSTEM CONTROL UNIT	Not Necessary	508.00 FS	*- FS
33	2		*HEADLIGHT COMPENSATING PIECE	Not Necessary	87.00 FS	*- FS
34	1		*HEADLIGHT HOSE - RH	Not Necessary	26.00 FS	*- FS
35	1		*LIFT CYLINDER - RH	Cracked	128.00 FS	*102.00 FS
36	1		*HEADLIGHT HOSE - RH	Not Necessary	170.00 FS	*- FS
37	1		*LOCK CARRIER	Cracked	907.00 FS	*725.60 FS
38	4		*READY MIX COOLANT	Necessary	165.00 FS	*131.84 FS
39	1		*A/C CONDENSER	Dented	503.00 FS	*402.00 FS
40	1		*REFRIGERANT LINE A/C CONDENSER > CUT-OFF POINT	Bent	579.00 FS	*463.20 FS
41	1		*REFRIGERANT LINE A/C COMPRESSOR > A/C CONDENSER	Bent	461.00 FS	*368.80 FS
42	1		*EXTERNAL TEMPERATURE SENSOR	Not Necessary	54.00 FS	*- FS
43	1		*RADIATOR AIR GUIDE - RH	Broken	27.00 FS	*21.36 FS
44	1		*RADIATOR AIR GUIDE - UPPER CENTRE	Not Necessary	19.00 FS	*- FS
45	2		*FRONT WHEEL COVER - LH / RH	Necessary	588.00 FS	*469.60 FS
46	1		*FRONT NO PLATE	Dented	40.00 FS	*40.00 FS
47	1		*SUNDRIES	Necessary	400.00 FS	*9.28 FS
48	1		*ADDITIONAL RADIATOR	Dented	858.00 FS	*702.40 FS
49	1		*UPPER BRACKET FOR RADIATOR	Necessary	77.00 FS	*61.28 FS
50	1		*BOWDEN CABLE CENTRE	Broken	53.00 FS	*41.68 FS
51	1		*BOWDEN CABLE COVER	Broken	9.00 FS	*7.12 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
52	1		*BONNET RELEASE ELEMENT	Broken	53.00 FS	*41.68 FS	
53	1		*NOISE INSULATION	Broken	239.00 FS	*191.20 FS	
54	1		*LID LOCK WITH MICRO SWITCH	Damaged	184.00 FS	*146.80 FS	
					Total Parts (\$)	18,848.00	11,748.80

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND RENEW AIRCON CONDENSER, TO REINSTALL RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,400.00	1,400.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,200.00	2,000.00
4	TO RESPRAY FRONT BUMPER, BONNET AND RHS FRONT FENDER	New	3,200.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO REPAIR AND RESPRAY BOTH FRONT FENDERS	New	2,800.00	1,100.00
			Gross Labour Cost (\$\$)	13,152.00
				6,152.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >