

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19018188/AYD3E2

Date: 08/04/2020

REFERENCE

Insured/Claimant:	TAN NYUK CHOON	Policy No:	2100476146-03	
Date of Loss:	12/10/2019	Nature of Claim:	OD	Claim No: 8575595405SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGP117E			
Make & Model:	AUDI A3, 1.4 TFSI (A)	Engine No:	CZC567394	
Reg. Date:	27/07/2016 (Man. Year: 2016)	Chassis No:	WAUZZZ8V5G1107306	
Colour:	White	Odometer:	54257 km	
Engine Capacity:	1395 cc			
Market Value/New Car Price:	S\$80,000.00			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,990.00	2,690.40	2,299.60	46.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,672.00	2,222.00	2,450.00	52.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,662.00	4,912.40	4,749.60	49.16
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	9,062.00	4,312.40	4,749.60	52.41
+ GST 7.00/7.00% (\$\$)	634.34	301.87	332.47	52.41
Nett Amount (\$\$)	9,696.34	4,614.27	5,082.07	52.41

INSPECTION

Date of Assignment:	15/10/2019	
Date Inspected:	15/10/2019	Inspected At:
		Premium Automobiles Pte Ltd (UBI)
		55 Ubi Road 1
		Singapore 408699
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR - LH	Dented	2,279.00 FS	*1,823.20 FS
2	1		*FRONT DOOR OUTER SEAL - LH	Necessary	146.00 FS	*116.80 FS
3	1		*BONDING AGENT	Not Necessary	45.00 FS	*- FS
4	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
5	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	218.00 FS	*- FS
6	1		*FRONT DOOR CATCH	Not Necessary	96.00 FS	*- FS
7	1		*EXTERIOR MIRROR MOUNTING - LH	Damaged	938.00 FS	*750.40 FS
8	1		*MIRROR CAP - LH	Not Necessary	136.00 FS	*- FS
9	1		*MIRROR GLASS - LH	Not Necessary	209.00 FS	*- FS
10	1		*CORNER TRIM - LH	Not Necessary	41.00 FS	*- FS
11	1		*WINDOW GUIDE TRIM STRIP - LH	Not Necessary	235.00 FS	*- FS
12	1		*WINDOW SLOT SEAL - LH FRONT	Not Necessary	282.00 FS	*- FS
13	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					4,990.00	2,690.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER LHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	280.00	280.00
2	TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW LHS WING MIRROR ASSY	New	300.00	0.00
3	TO DISMANTLE AND RENEW LHS FRONT DOOR. TO REPAIR LHS REAR DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,400.00	500.00
4	TO RESPRAY LHS FRONT DOOR, LHS REAR DOOR AND LHS WING MIRROR COVER	New	2,500.00	1,250.00
5	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (S\$)			4,672.00	2,222.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >