

ASS. REC. BY:

REF: CS/FCI 19018193 / DT 12/13/19

Special Instruction:

Supervisor: Bryan ASSIGNMENT (Office)

From (Person): Jason Teache kiat of FCI Date/Time: 15.10.19 4.21pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 8541L Insured: SHA 1338 U

at Workshop m/s Chunni Tel: 65427162

of Amic Auto point, Soon Hock motor #01-05/06

Policy No: \_\_\_\_\_ Claim No: D19006574mpsh

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 12.10.2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 15.10.19 4.28p.m Person Contacted: Lynn H.O.D. Endorsement: \_\_\_\_\_  
Vehicle IN/OUT

Date/Time	Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate
	SHD 8541L - CS3 / FCI 19010342 / GCD352 D.O.A - 04/06/2019
	SHA 1338 U - CS / PCL 19002772 / Atd3n2 D.O.A - 08/02/2019
<u>18/10-3:19pm</u>	<u>Revised preli aduse via email</u>

ASS. REC. BY:

REF:

ASSIGNMENT

08 May 2024

2016 May

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s: \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SHD 8541L Yr Regn: 2016 May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai I40 c.c. 1685

Colour: Yellow A/C: Insured / Std / NI / NA

Sp. Reading: 566096 T/Radio: Insured / Std / NI / NA

Eng/No: D4FDEU496632

C/No: KMHLB41UM6U089088

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front R/Bal. S mm

L/Bal. S mm

D.O.A. 12/10/2019

Survey held at Chunni AMIC

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

~~Chunni~~ First report SHD 1338u

27/11/2021 Invoice 2/S 4902/- with 6 days of rev Chkd. 6986 (50%)

RECEIVED 08 NOV 2019

Date/Time, File Pass to?

01/11 Typist

: Preli. Report  
 : Final Report

Date/Time, File Return to?

2)

Report Format: TP

Lump sum / F.P. / C: 4902/-

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee:  Site Insp (\$)  Interview (\$)  Tech. Invs (\$)  Weekend (\$)

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

TOTAL

170 + 15
50
50
86
TOTAL 371



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19006574MFSH

Date: 18/10/2019

Our Ref: CS/FCI19018193/Dtf3

The Motor Claims Department  
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 8541L

Please be informed that we had conducted the inspection of the abovementioned vehicle 16/10/2019 at the premises of M/s Chun Ni have the following to report: -

Workshop Estimate Amount	: S\$ <u>11,886.60</u>
Revised Estimate Amount	: S\$ <u>6,244.92</u>
“Check” Items Amount	: S\$ <u>0.00</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:  
The vehicle sustained damages at the  
N/S rear parts.



**Comments/ Present Status:**  
Damages Consistent.

Yours faithfully  
Bryan Ang  
Automotive Assessor

**MOTOR SURVEY ASSIGNMENT**

**Date** 14-10-2019 **Our Ref No.** D19006574MFSH

**Accident Date** 12-10-2019 **Claim Type.** Third Party

**Insured Vehicle** SHA1338U **Third Party Vehicle.** SHD8541L

**Survey Location** AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06.  
**Contact Person.** LYNN OR IRENE - 65421726  
**Contact No.** 65427162/ 0 **Fax No.** 65426039

**Survey Type** WITHOUT PREJUDICE: NEED TO VIEW VIDEO BEFORE CONFIRMING LIABILITY

**Appointed Surveyor** LKK AUTO CONSULTANTS PTE LTD  
**Contact Person** NA **Fax No.** 68416315  
**Contact Number.** NA

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

**Cc : Workshop** CHUNNI MOTOR WORK PTE LTD **Attention.** NIL

**Cc : TP Solicitor** NA **TP Solicitor Fax No.** NA

**Officer Incharge** JASON TEA CHEE KIAT

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Friday, 18 October 2019 3:19 PM  
**To:** Admin-D (LKKAuto); 'CWS Motor Claims'; assignments; SUR  
**Cc:** 'Jason Tea'  
**Subject:** RE: SURVEY ASSESSMENT - D19006574MFSH/1  
**Attachments:** PRELI ADVISED OF SHD 8541L.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHD 8541L**  
Number of days (estimated) : 6 days

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Sent:** Tuesday, 15 October 2019 4:24 PM  
**To:** 'CWS Motor Claims' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Cc:** 'Jason Tea' <[JasonTea@msfirstcapital.com.sg](mailto:JasonTea@msfirstcapital.com.sg)>  
**Subject:** RE: SURVEY ASSESSMENT - D19006574MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

**Summer Lee** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>  
**Sent:** Tuesday, 15 October, 2019 4:21 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; Jason Tea <[JasonTea@msfirstcapital.com.sg](mailto:JasonTea@msfirstcapital.com.sg)>  
**Subject:** PRI: SURVEY ASSESSMENT - D19006574MFSH/1

Dear Sir/Mdm,

NAME  
ADDRESS

Home Tel.:  
VIN:  
Registration: SHD 8541 L  
Technician:  
Mileage: 566096  
Time Printed 16.10.19 10:16 AM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-1°10'		-3°00' 3°00'
4°04'		-0°19' 5°41'
0°23'		-1°30' 1°30'
13°33'		
12°22'		

Camber  
Caster  
Toe  
SAI  
Included Angle  
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
0°14'		-3°00' 3°00'
4°14'		-0°19' 5°41'
-0°53'		-1°30' 1°30'
14°32'		
14°46'		

Front

Cross Camber  
Cross Caster  
Cross SAI  
Total Toe  
Cross Turn Diff.

Actual	BEFORE	Specified Range
-1°24'		-3°00' 3°00'
-0°11'		-3°00' 3°00'
-1°00'		-3°00' 3°00'
-0°31'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-1°15'		-3°30' 2°30'
3°59'		-1°30' 1°30'

Camber  
Toe

Rear : Right

Actual	BEFORE	Specified Range
-1°56'		-3°30' 2°30'
-0°02'		-1°30' 1°30'

Rear

Cross Camber  
Total Toe  
Thrust Angle

Actual	BEFORE	Specified Range
0°42'		-3°00' 3°00'
3°58'		-3°00' 3°00'
2°00'		-3°00' 3°00'

**CHUNNI MOTOR WORK PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO : SHD 8541L

DATE : 14.10.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

FCI

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>Cut / crack</i>			\$ 553.00
	Rear Bumper Clip 10 pcs <i>Nec</i>			\$ 22.00
	Rear Bumper Bracket, LH <i>NH</i>			\$ 35.60
	Rear Fender With Housing (LH) <i>Distorted</i>		2020.00	\$ 4,736.80
	Rear Fender Inner Lining (LH) <i>distorted / torn</i>			\$ 169.30
	Rear Windscreen Moulding <i>Nec</i>			\$ 28.30
	Rocker Panel Outer Garnish (LH) <i>NH</i>			\$ 341.40
	Rear Tyre Rim (LH) <i>16"</i>			\$ 325.30
	Rear Wheel Hub-Cap (LH) <i>cut</i>			\$ 107.10
	Rear Wheelbearing IN & Hub <i>Distorted</i>			\$ 362.00
	Rear Trailing Arm (LH) <i>Distorted</i>			\$ 192.00
	Rear Assist (LH) <i>Distorted</i>			\$ 145.70
	Rear Shock Absorber (LH) <i>Distorted</i>			\$ 276.30
	Rear Shock Absorber Mounting (LH) <i>NH</i>			\$ 81.30
	Rear Crossmember <i>NH</i>			\$ 1,021.50
	Stabilizer Bar <i>NH</i>			\$ 199.60
	Stabilizer Link <i>NH</i>			\$ 85.90
	Rear Upper Arm (LH) <i>Distorted</i>			\$ 335.75
	Rear Lower Arm (LH) <i>Distorted</i>			\$ 353.80
	Rear Knuckle Arm (LH) <i>Distorted</i>			\$ 545.60
	<b>SUB TOTAL</b>			<b>\$ 9,918.25</b>
	<b>LESS 20%</b>			<b>\$ 1,983.65</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 7,934.60</b>
	Rear Bumper Rubber Mat <i>Nec</i>			\$ 50.00
	Rear Windscreen Sealant <i>Nec</i>			\$ 46.00
	Rear Tyre (LH) <i>SVC</i>			\$ 216.00
				<b>\$ 312.00</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 1,000.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Remove/Refix Fuel Tank			\$ 150.00
	Remove/Refix Undercarriage (RR)			\$ 200.00
	Rear Wheel Alignment			\$ 120.00
	Re-set Rear ABS System			\$ 200.00
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00
				<b>\$ 6,244.92</b>
				<b>\$ 4,900.00</b>
	<b>TOTAL LABOUR</b>			<b>\$ 3,640.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 11,886.60</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

~~1,760.00~~  
1,800.00

16/10/2019 @ 1000m  
NA Actual 6 days  
LH sum  
JRM JKK Auto

5436.15  
4348.92

96.00

✓  
✓  
X  
✓  
✓  
✓  
X  
✓  
✓  
✓  
✓  
X  
X  
X  
✓  
✓  
✓  
✓  
X  
X  
X  
✓  
✓  
✓  
X

600/-  
600/-  
7H  
40/-  
80/-  
80/-  
40/-  
7H  
150/-  
60/-  
150/-

\$ 3,640.00  
\$ 11,886.60




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FC19018193/Dtf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 15-11-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 1338U	Veh. Inspected	SHD 8541L
Policy No.		Coverage (\$)	0.00
Claim No.	D19006574MFSH	Excess (\$)	0.00
Assign From	JASON TEA CHEE KIAT	Assign Date	15/10/2019
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU089088	Colour	YELLOW
Odometer	566096	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	HANKOOK	5 mm
L/H Front Tyre	205/60 R16	HANKOOK	5 mm
R/H Rear Tyre	205/60 R16	HANKOOK	5 mm
L/H Rear Tyre	205/60 R16	HANKOOK	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/10/2019	Inspection Date	16/10/2019
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>6 Working Days</b>	





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 8541L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	CUT / CRACKED	553.00	553.00
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
1	REAR BUMPER BRACKET,LH	NOT NECESSARY	35.60	-
1	REAR FENDER (LH)	DENTED	4,736.80	2,020.00
1	REAR FENDER INNER LINING (LH)	DEFORMED / TORN	169.30	169.30
1	REAR WINDSCREEN MOULDING	NECESSARY	28.30	28.30
1	ROCKER PANEL OUTER GARNISH (LH)	NOT NECESSARY	341.40	-
1	REAR TYRE RIM (LH)	BENT	325.30	325.30
1	REAR WHEEL HUP-CAP (LH)	CUT	107.10	107.10
1	REAR WHEELBEARING ING & HUB	DAMAGED	362.00	362.00
1	REAR TRAILING ARM (LH)	DISTORTED	192.00	192.00
1	REAR ASSIST (LH)	DISTORTED	145.70	145.70
1	REAR SHOCK ABSORBER (LH)	DISTORTED	276.30	276.30
1	REAR SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	81.30	-
1	REAR CROSSMEMBER	NOT NECESSARY	1,021.50	-
1	STABILIZER BAR	NOT NECESSARY	199.60	-
1	STABILIZER LINK	NOT NECESSARY	85.90	-
1	REAR UPPER ARM (LH)	DISTORTED	335.75	335.75
1	REAR LOWER ARM (LH)	DISTORTED	353.80	353.80
1	REAR KNUCKLE ARM (LH)	DISTORTED	545.60	545.60
	LESS 20% DISCOUNT		-1,983.65	-1,087.23
			7,934.60	4,348.92
<b>SPECIAL NETT ITEMS</b>				
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR TYRE (LH)(SN)	SERVICEABLE	216.00	-
			312.00	96.00
<b>LABOUR</b>				
	PANEL BEATING.		1,000.00	600.00
	SPRAY PAINTING CHARGE.		1,000.00	600.00

Report Ref No. CS/FC119018193/Dtf3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	TUFF KOTE.		50.00	40.00
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.		120.00	80.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	40.00
	REMOVE/REFIX FUEL TANK.	NOT NECESSARY	150.00	-
	REMOVE/REFIX UNDERCARRIAGE (RR).		200.00	150.00
	REAR WHEEL ALIGNMENT.		120.00	60.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE }.		480.00	150.00
	RE-SET REAR ABS SYSTEM }.		200.00	-
			3,640.00	1,800.00
	<b>GRAND TOTAL</b>		<b>11,886.60</b>	<b>6,244.92</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>4,900.00</b>

Report Ref No. CS/FCI19018193/Dtf3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.