

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG19018207/ETF3E2

Date: 08/05/2020

REFERENCE

Insured/Claimant: LIM MEI LING, JENNY(LIN MEILING, JENNY)
Date of Loss: 29/08/2019

Policy No:
Nature of Claim: OD Claim No: 3767185175SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDH381K		
Make & Model:	AUDI Q2, 999cc 1.0 TFSI S TRONIC (A)	Engine No:	CHZ390643
Reg. Date:	24/07/2017 (Man. Year: 2017)	Chassis No:	WAUZZZGA3HA059997
Colour:	Red	Odometer:	32121 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$85,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,100.00	6,807.00	4,293.00	38.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,152.00	1,852.00	2,300.00	55.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	15,252.00	8,659.00	6,593.00	43.23
+ GST 7.00/7.00% (\$\$)	1,067.64	606.13	461.51	43.23
Nett Amount (\$\$)	16,319.64	9,265.13	7,054.51	43.23

INSPECTION

Date of Assignment:	16/10/2019	
Date Inspected:	15/10/2019	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$597.00 NETT)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	3		*FRONT BUMPER ASSY	Repair	1,706.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	314.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	179.00 FS	*- FS
4	1		*FRONT BUMPER END CAP - LH	Not Necessary	31.00 FS	*- FS
5	1		*FRONT BUMPER SPOILER	Cut	273.00 FS	*273.00 FS
6	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	142.00 FS	*- FS
7	1		*FRONT WHEEL SPOILER - LH	Not Necessary	31.00 FS	*- FS
8	1		*FRONT ADAPTER - LH	* Check	32.00 FS	*- FS
9	1		*RADIATOR GRILLE	Cut	1,301.00 FS	*1,301.00 FS
10	1		*RADIATOR GRILLE STRIKER PLATE	* Check	114.00 FS	*- FS
11	1		*FRONT BUMPER CARRIER	Not Necessary	625.00 FS	*- FS
12	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	71.00 FS	*- FS
13	1		*FRONT BUMPER COVER	Not Necessary	91.00 FS	*- FS
14	1		*FRONT BUMPER DISTANCE PIECE	* Check	12.00 FS	*- FS
15	1		*FRONT BUMPER GUIDE SECTION - LH	* Check	32.00 FS	*- FS
16	1		*HORN - LH LOW TONE	Not Necessary	262.00 FS	*- FS
17	1		*HORN SPRING SHACKLE - LH	Not Necessary	29.00 FS	*- FS
18	1		*MAIN BEAM HEADLIGHT MOUNTING	* Check	107.00 FS	*- FS
19	1		*LED HEADLIGHT - LH	Cut	4,491.00 FS	*4,491.00 FS
20	1		*LED HEADLIGHT LIFT CYLINDER - LH	Not Necessary	128.00 FS	*- FS
21	2		*FRONT WHEEL COVER - LH / RH	Necessary	588.00 FS	*588.00 FS
22	1		*RADIATOR AIR GUIDE - LH	Not Necessary	27.00 FS	*- FS
23	1		*CAUTION SIGN	Not Necessary	13.00 FS	*- FS
24	1		*AIRCON STICKER	Not Necessary	7.00 FS	*- FS
25	1		*FRONT NO PLATE	Not Necessary	40.00 FS	*- FS
26	1		*SUNDRIES	* Check	300.00 FS	*- FS
27	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Cut	154.00 FS	*154.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **11,100.00** **6,807.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,600.00	750.00
3	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (\$\$)			4,152.00	1,852.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >