

ASS. REC. BY:

REF:

CS/ICS190182361 Dqf3 CV

Special Instruction:

SUIVAPOR: Bryan

ASSIGNMENT (Office)

From (Person): Desmond Lee

of ECICS

Date/Time: 16.10.19 9.54am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGL 2506Z

Insured:

at Workshop m/s Virvo motordimic

Tel:

67022990

of MO 25 Kaki Bukit Road 4 #03-39

Policy No: MPC19A 00135600

Claim No:

DMPC1900263 H

Sum Insured:

Excess:

\$500.00

Make of Veh:

D.O.A.

12.10.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

16.10.19 10.17am

Person Contacted:

Bo Bo

Vehicle IN/OUT

Date/Time

Action/Instruction ( ✓ ) Estimate.

SGL 2506Z: X

18/10/19 @ 11.45am revert to Desmond Lee via Messman.

05/11/19 @ Desmond called to inform that they repudiated the claim &amp; have uploaded the repudiated letter to Messman.

05/11/19 @ informed Verne, insurance had repudiated the claim.

07/11/19 submit press. report. - We have not authorize repair.

ASS. REC. BY:

REF:

ASSIGNMENT

COP Sept 2021

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: 2GL2506Z Yr Regn: 2006 / Sept  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Toyota Wison c.c. 1794  
 Colour: Black A/C: Insured / Std / NI / NA  
 Sp. Reading: N.A. T/Radio: Insured / Std / NI / NA  
 Eng/No: 1222685106  
 C/No: ZNE100323973  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 215/45 R17  
 R: — 11 —

(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Kumho  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. 12/10/2019 D.O.I. 16/10/2019  
 Survey held at Verve Autoclinic Kaki St.

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rport: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 10 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
The vehicle caught fire at front left  
The UIC / Chassis frame / Body Structure affected due to collision.  
engine compartment. Cause of fire  
due to electrical nature to the  
wiring of the front left headlamp.

Date / Time	Action / Instruction
	ECICB OD
	MV 16K
	LTA 10.7K
	NL 5.3K
	RECEIVED 08 NOV 2019
	Repairer considering to put up estimate. will confirm again if can agree within <del>4K</del> 5K
	Desmond said to continue to do investigation.

Date/Time, File Pass to?  Preli. Report  
 Final Report  
 1) 02/11/2019  
 Date/Time, File Return to?  
 2) \_\_\_\_\_  
 Report Form  
 Lump Sum / UIC /

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_  
 Add Fee:  Site Insp (\$ )  
 Interview (\$ )  
 Tech. Invs (\$ ) 500  
 Wheel end (\$ )  
 Survey Fee: 390  
 Transportation: \_\_\_\_\_  
 S + RS: \_\_\_\_\_  
 Photos: \_\_\_\_\_  
 Others: 11  
 TOTAL: 401

**...CLAIM SUBFOLDER...(New Assignment)**

Midnight Accident

**THE REPAIRER HAS NOT SUBMITTED THEIR ESTIMATES**

If you wish to work on the report, contact the repairer below to submit it.  
You can authorize repairer submission after **5 days**.

**0 days** have passed since assignment.  
You can authorize the submission of the repairer's estimates in **120 HOURS**.

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Status
Main	15 Oct 2019 16:43		16 Oct 2019 09:54 <a href="#">Assign</a>			<b>New Assignment</b>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

**CLAIM SUBFOLDER DETAILS**

Insured:	MOHD YUNOS BIN MOHD JUMADI, ID: S8132687H, Tel: +6593280092, Email: <a href="mailto:vervemotorclinic@gmail.com">vervemotorclinic@gmail.com</a>		
Vehicle Reg. No.:	SGL2506Z	Date of Loss:	12/10/2019 00:00 - :59 [157 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / DMPC1900268H	Policy/Cover Note No.:	MPC19A00135600 (Comprehensive)
		Excess:	S\$500.00
Repairer:	Verve Motorclinic Pte Ltd (Kaki Bukit) No. 25 Kaki Bukit Road 4, #03-39 Synergy@KB, 417800 Kaki Bukit - Tel: 67022990		
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Desmond Lee - 6303 0167]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/10/2019]		
Adj Asg. Remarks:	Please assign Case to Bryan Ang - LKK		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

- ECICS (16/10/2019): Alert - Adj Mandate Revoked - SGL2506Z - Claim Handler: Desmond Lee

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited  
10 Eunos Road 8  
#09-04A Singapore Post Centre  
Singapore 408600From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Desmond Lee

Date: 18 Oct 2019

**Preliminary Advice**

Vehicle No	: SGL2506Z	Accident Date	: 12/10/2019
Make	: TOYOTA WISH	Policy No.	: MPC19A00135600
Assignment Date	: 16/10/2019	Excess	: S\$500.00
Date of Inspection	: 16/10/2019	Est. Duration of Repair	: 10.00
Inspection At	: VERVE MOTORCLINIC PTE LTD (KAKI BUKIT) NO. 25 KAKI BUKIT ROAD 4, #03-39 SYNERGY@KB SINGAPORE 417800		

**Point of Impact / General Description of Damages**

The vehicle caught fire.

Repairer's Estimate (Gross)	:S\$	13,302.60
Revised Amount	:S\$	7,922.10
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,922.10
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	16,000.00
COE / PARF Rebate	:S\$	10,744.00
Salvage Value	:S\$	
Margin for Repair	:S\$	5,256.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : REPAIRER ABLE TO UNDERTAKE THE REPAIR COST WITHIN MARGIN FOR REPAIR.

> [Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	687H
<b>Vehicle Details</b>	
Vehicle No.:	SGL2506Z
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 A
Primary Colour:	Black
Manufacturing Year:	2006
Engine No.:	1ZZ2685106
Chassis No.:	ZNE100323973
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$19,391.00
Original Registration Date:	08 Sep 2006
First Registration Date:	08 Sep 2006
Transfer Count:	1
Actual ARF Paid:	\$21,331.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	07 Sep 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$28,418.00
COE Rebate Amount:	\$10,744.00
<b>Total Rebate Amount:</b>	<b>\$10,744.00</b>
<b>Message</b>	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 17 Oct 2019

**SINGAPORE ACCIDENT STATEMENT**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**ACCIDENT STATEMENT**

Date Of Report 15/10/2019 16:51  
 Date Of Accident 12/10/2019 23:00  
 Exact Location Of Accident PASIR RIS DRIVE 8  
 Country/State of Loss SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number SGL2506Z  
 Insured/Policyholder  
 Name Of Registered Owner MOHD YUNOS BIN MOHD JUMADI  
 NRIC No S8132687H  
 Email Address VERVEMOTORCLINIC@GMAIL.COM  
 Mobile Phone No (LOCAL) +65-93280092  
 Alternative Phone No OFFICE-93280092

**Vehicle Particulars**

Manufacturer TOYOTA  
 Model WISH-1.8 (A)  
 Exact Purpose for which vehicle was being used at time of accident  
 Are you claiming under your own insurance policy for repair to your vehicle? YES  
 If No, Please state action to be taken  
 Vehicle Category PRIVATE CAR

**Insurance Company**

Name of Insurance Company ECICS LIMITED  
 Type Of Coverage COMPREHENSIVE  
 Fleet Policy NO  
 Policy Number  
 Cover Note Number

**Driver**

Name of Driver MOHD YUNOS BIN MOHD JUMADI  
 NRIC No S8132687H  
 Date Of Birth 27/10/1981  
 Occupation INDOOR  
 Date Of Driving Pass 09/04/2003  
 Driving Experience 16 YEARS AND 6 MONTHS  
 Gender MALE  
 Mobile Number (LOCAL) +65-93280092  
 Fax Number  
 Contact Number OFFICE-93280092  
 EMail Address VERVEMOTORCLINIC@GMAIL.COM

*Handwritten notes:*  
 Sister's here.  
 Punjani → Pasir Ris  
 not near 30m's drive.  
 front left bonnet smudge.  
 than a few seconds. fire fire  
 saw some area. Stop off engine  
 and open bonnet saw fire at right side  
 of engine cover  
 wife & sister and some boy  
 (land. kids inside.  
 Police. call on how  
 served at  
 last month. sin rooming.  
 2 mins once blow with LTA  
 -3 can't recall last input  
 blow when.  
 fire put out by him  
 with help of  
 possibly-SIDR arrived  
 after  
 driving drive, the high beam  
 indicator suddenly came on but  
 cannot after edit from TPB saw  
 from reflector of vehicle  
 input that the front  
 left headlamp broken. vehicle turned  
 to ATC.

Address	880A TAMPINES AVE 8 #01-298
Postcode	521880
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	FIRE, EXPLOSION OR LIGHTNING
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : MIGAWATI BINTE RANI GENDER: : FEMALE
Passenger 2	NAME: : SYASYA MARSYA BINTE MOHD YUNOS GENDER: : FEMALE
Passenger 3	NAME: : MISYA ALESYA BINTE MOHD YUNOS GENDER: : FEMALE
Passenger 4	NAME: : ADAWIYYAH BINTE MOHD JUMADI GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	


#### Circumstances of Accident

WHILST FILTERING TO THE MAIN ROAD, I SMELLED BURNING SMELL AND SAW SMOKE EMITTING FROM MY BONNET. NOT TOO LONG AFTER A FIRE BROKE OUT. I IMMEDIATELY STOPPED BY THE ROAD SIDE AND EXTINGUISHED THE FIRE.

#### Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Sketch Plan



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

WHILE FILTERING TO THE MAIN ROAD, I SMELLED BURNING SMELL AND SAW  
SMOKE EMITTING FROM MY BONNET. NOT TOO LONG AFTER A FIRE BROKE OUT.  
I IMMEDIATELY STOPPED BY THE ROADSIDE AND EXTINGUISHED THE FIRE.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Applicant's Signature  
Date & Place

Driver's Signature  
If employed by the applicant

Assessing Centre Personnel's Signature  
Name

**Verve Motorclinic Pte Ltd** (Co.Reg.No:201800568H)

No. 25 Kaki Bukit Road 4, #03-39 Synergy@KB

Singapore 417800

Tel: 67022990 Email: jaronranz92@gmail.com

INSURER:

**ECICS Limited (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC19A00135600	Date of Loss:	12/10/2019
Vehicle Reg. No.:	<b>SGL2506Z</b>	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	MOHD YUNOS BIN MOHD JUMADI	Contact No:	+6593280092
Make/Model:	TOYOTA WISH, 1.8 (A)	Vehicle Reg. Date:	08/09/2006
Vehicle Colour:	BLACK	Chassis No:	ZNE100323973
Engine No:	1ZZ2685106		
Odometer:	0 KM		
Paint Type:			
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	25		
Present Location:	VERVE MOTORCLINIC PTE LTD (KAKI BUKIT)		

**COST OF CLAIMS**

	<b>Amount</b>
Parts	10,242.60
Miscellaneous Items	0.00
Labour	3,060.00
Paintwork Labour	0.00
Towing	0.00
<b>Calculated Gross Total (S\$)</b>	<b>13,302.60</b>
<b>- Excess (S\$)</b>	<b>500.00</b>
<b>Nett Amount (S\$)</b>	<b>12,802.60</b>

**This claim is handled by: THAM WEI CHUEN KENNETH**

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

## REPAIR DETAILS

## Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Oct 2019)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Verve Motorclinic Pte Ltd/SGL2506Z/17/10/2019 14:33	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*BONNET burnt	0.00	0.00	*280.00 F	✓
2	1		*BONNET HINGE LH <i>new</i>	0.00	0.00	*35.00 F	X
3	1		*BONNET HINGE RH <i>new</i>	0.00	0.00	*35.00 F	X
4	1		*BONNET CHROME MOULDING <i>new</i>	0.00	0.00	*140.00 F	X
5	1		*BONNET LOGO <i>SVC</i>	0.00	0.00	*40.00 F	X
6	1		*BONNET SEAL <i>melted</i>	0.00	0.00	*30.00 F	✓
7	1		*BONNET INSULATOR <i>burnt.</i>	0.00	0.00	*160.00 F	✓
8	1		*HEADLIGHT RH <i>new</i>	0.00	0.00	*380.00 F	X
9	1		*HEADLIGHT LH <i>burnt</i>	0.00	0.00	*380.00 F	✓
10	1		*FRONT GRILLE <i>new</i>	0.00	0.00	*80.00 F	X
11	1		*BONNET LOCK <i>new</i>	0.00	0.00	*55.00 F	X
12	1		*FRONT BUMPER <i>melted</i>	0.00	0.00	*220.00 F	✓
13	1		*FRONT BUMPER RETAINER LH <i>new</i>	0.00	0.00	*35.00 F	X
14	1		*FRONT BUMPER RETAINER RH <i>new</i>	0.00	0.00	*35.00 F	X
15	1		*FOR LAMP COVER LH <i>Down</i>	0.00	0.00	*35.00 F	✓
16	1		*FRONT FENDER LH <i>burnt</i>	0.00	0.00	*200.00 F	✓
17	1		*FRONT FENDER COWLING LH <i>melted</i>	0.00	0.00	*85.00 F	✓
18	1		*FRONT WHEEL HOUSE LH <i>burnt.</i>	0.00	0.00	*210.00 F	✓
19	1		*FRONT APRON PANEL <i>new</i>	0.00	0.00	*200.00 F	X
20	1		*RADIATOR TOP COVER <i>NF</i>	0.00	0.00	*45.00 F	X
21	1		*RADIATOR ASSY <i>new</i>	0.00	0.00	*550.00 F	X
22	1		*RADIATOR FAN BLADE <i>new</i>	0.00	0.00	*75.00 F	X
23	1		*RADIATOR FAN MOTOR <i>new</i>	0.00	0.00	*95.00 F	X
24	1		*RADIATOR FAN COWLING <i>new</i>	0.00	0.00	*115.00 F	X
25	1		*AIR CLEANER ASSY <i>melted</i>	0.00	0.00	*220.00 F	✓
26	1		*AIR CLEANER INLET HOSE <i>melted</i>	0.00	0.00	*38.00 F	✓
27	1		*FRONT WINDSCREEN <i>SVC</i>	0.00	0.00	*850.00 F	X
28	1		*WINDSCREEN MOULDING <i>new</i>	0.00	0.00	*55.00 F	X
29	1		*FRONT WIPER GARNISH LH <i>melted</i>	0.00	0.00	*135.00 F	✓
30	1		*FRONT WIPER GARNISH RH <i>new</i>	0.00	0.00	*135.00 F	X
31	1		*FRONT WIPER PANEL <i>SVC new</i>	0.00	0.00	*240.00 F	X
32	1		*FRONT ENGINE FIRE WALL INSULATOR <i>SVC</i>	0.00	0.00	*350.00 F	X
33	1		*ENGINE FUSE BLOCK TOP COVER <i>melted</i>	0.00	0.00	*45.00 F	✓
34	1		*ENGINE FUSE BLOCK JUNCTION ASSY <i>melted</i>	0.00	0.00	*120.00 F	✓
35	1		*ENGINE FUSE BLOCK BOTTOM COVER <i>melted</i>	0.00	0.00	*85.00 F	✓
36	1		*ENGINE MAIN WIRE HARNESS <i>burnt</i>	0.00	0.00	*1,500.00 F	✓
37	1		*FRONT ENGINE WIRE HARNESS <i>burnt</i>	0.00	0.00	*920.00 F	✓
38	1		*FRONT SHOCK ABSORBER LH <i>SVC</i>	0.00	0.00	*180.00 F	X
39	1		*ENGINE HEAD COVER <i>new</i>	0.00	0.00	*120.00 F	X
40	1		*FRONT BUMPER CLIPS <i>new</i>	0.00	0.00	*16.00 F	✓
41	1		*BONNET INSULATOR CLIPS <i>new</i>	0.00	0.00	*16.00 F	✓
42	1		*FRONT FENDER COWLING CLIPS <i>new</i>	0.00	0.00	*16.00 F	✓
43	1		*A/C LIQUID PIPE <i>SVC</i>	0.00	0.00	*170.00 F	X
44	1		*TRANSMISSION MOUNTING LH <i>SVC</i>	0.00	0.00	*140.00 F	X
45	1		*BATTERY ASSY <i>melted</i>	0	0.00	*150.00 FS	✓

Verve Motorclinic Pte Ltd/SGL2506Z/17/10/2019 14:33. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*FRONT TYRE LH <i>melted</i>	0	0.00	*250.00 FS ✓
47	1		*FRONT WINDSCREEN SEALANT <i>HL</i>	0	0.00	*40.00 FS ✗
48	1		*A/C COOLANT <i>Nec</i>	0	0.00	*50.00 FS ✓
49	1		*FRONT SUPPORT PANEL (REPAIR) <i>Nec</i>	0.00	0.00	-
50	1		*FRONT WINDSCREEN PILLAR (REPAIR) <i>Nec</i>	0.00	0.00	-
51	1		*FRONT FENDER <i>LH</i> (REPAIR) <i>R</i> <i>RH</i>	0.00	0.00	-
<b>Sub Total (\$\$)</b>						<b>9,356.00</b>
+ Margin on L,N Items 10.00% (\$\$)						886.60
<b>Total Parts (\$\$)</b>						<b>10,242.60</b>

F=Franchise part. S=SpcNett.

Verve Motorclinic Pte Ltd/SGL2506Z/17/10/2019 14:33. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

# Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	TOWING <i>NW</i>	New	80.00 X
2	TO CHECK FRONT ELECTRICAL SYSTEM, REPLACE WIRE HARNESSSES AND FUSE BLOCK JUNCTION.	New	<del>540.00</del> 450
3	TO REMOVE AND REINSTALL A/C CONDENSER FOR NECESSARY REPAIR	New	<del>100.00</del> 80
4	TO REMOVE AND REPLACE RADIATOR ASSY	New	<del>80.00</del> 50
5	TO REMOVE AND REPLACE FRONT WINDSCREEN	New	120.00 <i>NW</i>
6	TO REMOVE AND REPLACE LHF SHOCK ABSORBER	New	<del>80.00</del> 50
7	TO CHECK WHEEL ALIGNMENT	New	-60.00 ✓
8	TO REPAIR FRONT AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,000.00 800
9	TO SPRAY PAINT ON FRONT AFFECTED AREA	New	1,000.00 800
<b>Gross Labour Cost (S\$)</b>			<b>3,060.00</b>

Verve Motorclinic Pte Ltd/SGL2506Z/17/10/2019 14:33. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

16/10/2019 @ 14:30m  
NOT Andrew  
L/survey Repair Limit.

*[Signature]*  
LKK Auto

*[Signature]*  
Photo after repair  
Excess TBA.  
Pending investigation on cause of fire

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

Midnight Accident

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Status
Main	15 Oct 2019 16:43	17 Oct 2019 14:33 <b>S\$13,302.60</b>	16 Oct 2019 09:54 <a href="#">Edit Adj Rpt</a>	<b>S\$7,922.10</b> <a href="#">Edit Estimates</a>	<b>S\$7,922.10</b> <a href="#">View Rpt</a>	<b>Pending for Survey Report</b>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	<b>MOHD YUNOS BIN MOHD JUMADI</b> , ID: S8132687H, Tel: +6593280092, Email: <a href="mailto:vervemotorclinic@gmail.com">vervemotorclinic@gmail.com</a>								
Vehicle Reg. No.:	<b>SGL2506Z</b>	Date of Loss:	12/10/2019 00:00 - :59 [157 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>OD / DMPC1900268H</b>	Policy/Cover Note No.:	MPC19A00135600 (Comprehensive)						
		Excess:	S\$500.00						
Repairer:	<b>Verve Motorclinic Pte Ltd (Kaki Bukit)</b> No. 25 Kaki Bukit Road 4, #03-39 Synergy@KB, 417800 Kaki Bukit - Tel: 67022990								
Handling Insurer:	<b>ECICS Limited (HQ)</b> - Tel: 63374779 /6303 0178 ... [Handled by <b>Desmond Lee</b> - 6303 0167]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>BRYAN TANI</b> ] ... [Final Rpt due 21/10/2019]								
Adj Asg. Remarks:	Please assign Case to Bryan Ang - LKK								
<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a>	<a href="#">Compose Case Mail</a>				
<ul style="list-style-type: none"> <li>ECICS (16/10/2019): Alert - Adj Mandate Revoked - SGL2506Z - Claim Handler: Desmond Lee</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>									
		<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

SGL2506Z (DMPC1900268H)  
OD  
Oct 12 2019 12:00AM  
[MOHD YUNOS BIN MOHD JUMADI]  
Verve Motorclinic Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Verve Motorclinic Pte Ltd (Kaki Bukit)		Thumbnail Print
1	17/10/19 14:33	Repairer Estimates	1	Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	18/10/19 11:45	Adjuster Immediate Advice	1	Load HTM
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Verve Motorclinic Pte Ltd (Kaki Bukit)		Thumbnail Print
1	15/10/19 16:40	Chassis Number	1	Load JPG <input checked="" type="checkbox"/>
2	15/10/19 16:40	Accident Photo	1	Load JPG <input checked="" type="checkbox"/>
3	15/10/19 16:40	Accident Photo	1	Load JPG <input checked="" type="checkbox"/>
4	15/10/19 16:40	Accident Photo	1	Load JPG <input checked="" type="checkbox"/>
5	15/10/19 16:40	Accident Photo	1	Load JPG <input checked="" type="checkbox"/>
6	15/10/19 16:40	Accident Photo	1	Load JPG <input checked="" type="checkbox"/>
7	15/10/19 16:40	Accident Photo	1	Load JPG <input checked="" type="checkbox"/>
8	15/10/19 16:40	Accident Photo	1	Load JPG <input checked="" type="checkbox"/>
9	15/10/19 16:40	Accident Photo	1	Load JPG <input checked="" type="checkbox"/>
10	15/10/19 16:40	Accident Photo	1	Load JPG <input checked="" type="checkbox"/>
11	15/10/19 16:41	Accident Photo	1	Load JPG <input checked="" type="checkbox"/>
12	15/10/19 16:41	Accident Photo	1	Load JPG <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	07/11/19 16:39	General View Right	1	Load JPG <input checked="" type="checkbox"/>
2	07/11/19 16:39	General View Left	1	Load JPG <input checked="" type="checkbox"/>
3	07/11/19 16:43	General View	1	Load JPG <input checked="" type="checkbox"/>
4	07/11/19 16:43	General View	1	Load JPG <input checked="" type="checkbox"/>
5	07/11/19 16:43	General View	1	Load JPG <input checked="" type="checkbox"/>
6	07/11/19 16:43	General View	1	Load JPG <input checked="" type="checkbox"/>
7	07/11/19 16:43	General View	1	Load JPG <input checked="" type="checkbox"/>
8	07/11/19 16:43	General View	1	Load JPG <input checked="" type="checkbox"/>
9	07/11/19 16:43	General View	1	Load JPG <input checked="" type="checkbox"/>
10	07/11/19 16:43	General View	1	Load JPG <input checked="" type="checkbox"/>
11	07/11/19 16:43	General View	1	Load JPG <input checked="" type="checkbox"/>
12	07/11/19 16:43	General View	1	Load JPG <input checked="" type="checkbox"/>
13	07/11/19 16:43	General View	1	Load JPG <input checked="" type="checkbox"/>
14	07/11/19 16:43	General View	1	Load JPG <input checked="" type="checkbox"/>
15	07/11/19 16:43	General View	1	Load JPG <input checked="" type="checkbox"/>
16	07/11/19 16:43	Chassis Number	1	Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ECICS Limited (HQ)		Thumbnail Print
1	17/10/19 09:05	OI SAS	1	Load PDF
2	05/11/19 16:06	Repudiation Letter	1	Load PDF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	17/10/19 11:09	Log card (if available)	1	Load PDF
2	18/10/19 11:31	ESTIMATE	1	Load PDF
3	08/11/19 15:08	Investigation Report	1	Load PDF

## Documents Checklist

**DOCUMENTS CHECKLIST**

Reset Save Print

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Repairer  Handling Insurer  
Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited  
10 Eunos Road 8, #09-04A Singapore Post Centre  
Singapore 408600

**Our File No:** CS/ICS19018236/DQF3E2  
**Date:** 08/11/2019

#### REFERENCE

Insured/Claimant: MOHD YUNOS BIN MOHD JUMADI Policy No: MPC19A00135600  
Date of Loss: 12/10/2019 Nature of Claim: OD Claim No: DMPC1900268H

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGL2506Z**  
Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 1ZZ2685106  
Reg. Date: 08/09/2006 (Man. Year: 2006) Chassis No: ZNE100323973  
Colour: Black Odometer: 0 km  
Engine Capacity: 1794 cc  
Market Value/New Car Price: S\$16,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17  
Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm  
Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,242.60	5,632.10	4,610.50	45.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,060.00	2,290.00	770.00	25.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,302.60</b>	<b>7,922.10</b>	<b>5,380.50</b>	<b>40.45</b>
<b>- Excess (S\$)</b>	<b>500.00</b>	<b>500.00</b>	<b>0.00</b>	<b>0.00</b>
<b>Nett Amount (S\$)</b>	<b>12,802.60</b>	<b>7,422.10</b>	<b>5,380.50</b>	<b>42.03</b>

#### INSPECTION

Date of Assignment: 16/10/2019 Present Location: Verve Motorclinic Pte Ltd (Kaki Bukit)  
Date Inspected: 16/10/2019 Inspected At: Verve Motorclinic Pte Ltd (Kaki Bukit)  
No. 25 Kaki Bukit Road 4, #03-39  
Synergy@KB  
Singapore 417800

Estimated Period of Repair: 10.0 days

**Adjuster:** BRYAN TANI

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 08 Nov 2019)	
<b>Parts:</b> M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)	
<b>Labour:</b> Repairer's	(Price-denominated Standard List)	
<b>Print Code:</b> (Unsubmitted, no print-code for SGL2506Z)		
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.		

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BONNET (WCP)	Burnt	280.00 F	*280.00 F
2	1	*BONNET HINGE LH (WCP)	Repair	35.00 F	*- F
3	1	*BONNET HINGE RH (WCP)	Repair	35.00 F	*- F
4	1	*BONNET CHROME MOULDING (WCP)	Not Necessary	140.00 F	*- F
5	1	*BONNET LOGO (WCP)	Serviceable	40.00 F	*- F
6	1	*BONNET SEAL (WCP)	Melted	30.00 F	*30.00 F
7	1	*BONNET INSULATOR (WCP)	Burnt	160.00 F	*160.00 F
8	1	*HEADLIGHT RH (WCP)	Not Necessary	380.00 F	*- F
9	1	*HEADLIGHT LH (WCP)	Burnt	380.00 F	*380.00 F
10	1	*FRONT GRILLE (WCP)	Not Necessary	80.00 F	*- F
11	1	*BONNET LOCK (WCP)	Not Necessary	55.00 F	*- F
12	1	*FRONT BUMPER (WCP)	Melted	220.00 F	*220.00 F
13	1	*FRONT BUMPER RETAINER LH (WCP)	Not Necessary	35.00 F	*- F
14	1	*FRONT BUMPER RETAINER RH (WCP)	Not Necessary	35.00 F	*- F
15	1	*FOR LAMP COVER LH (WCP)	Damaged	35.00 F	*35.00 F
16	1	*FRONT FENDER LH (WCP)	Burnt	200.00 F	*200.00 F
17	1	*FRONT FENDER COWLING LH (WCP)	Melted	85.00 F	*85.00 F
18	1	*FRONT WHEEL HOUSE LH (WCP)	Burnt	210.00 F	*210.00 F
19	1	*FRONT APRON PANEL (WCP)	Repair	200.00 F	*- F
20	1	*RADIATOR TOP COVER (WCP)	Not fitted	45.00 F	*- F
21	1	*RADIATOR ASSY (WCP)	Not Necessary	550.00 F	*- F
22	1	*RADIATOR FAN BLADE (WCP)	Not Necessary	75.00 F	*- F
23	1	*RADIATOR FAN MOTOR (WCP)	Not Necessary	95.00 F	*- F
24	1	*RADIATOR FAN COWLING (WCP)	Not Necessary	115.00 F	*- F
25	1	*AIR CLEANER ASSY (WCP)	Melted	220.00 F	*220.00 F
26	1	*AIR CLEANER INLET HOSE (WCP)	Melted	38.00 F	*38.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
27	1		*FRONT WINDSCREEN (WCP)	Serviceable	850.00 F	*- F
28	1		*WINDSCREEN MOULDING (WCP)	Not Necessary	55.00 F	*- F
29	1		*FRONT WIPER GARNISH LH (WCP)	Melted	135.00 F	*135.00 F
30	1		*FRONT WIPER GARNISH RH (WCP)	Not Necessary	135.00 F	*- F
31	1		*FRONT WIPER PANEL (WCP)	Repair	240.00 F	*- F
32	1		*FRONT ENGINE FIRE WALL INSULATOR (WCP)	Serviceable	350.00 F	*- F
33	1		*ENGINE FUSE BLOCK TOP COVER (WCP)	Melted	45.00 F	*45.00 F
34	1		*ENGINE FUSE BLOCK JUNCTION ASSY (WCP)	Melted	120.00 F	*120.00 F
35	1		*ENGINE FUSE BLOCK BOTTOM COVER (WCP)	Melted	85.00 F	*85.00 F
36	1		*ENGINE MAIN WIRE HARNESS (WCP)	Burnt	1,500.00 F	*1,500.00 F
37	1		*FRONT ENGINE WIRE HARNESS (WCP)	Burnt	920.00 F	*920.00 F
38	1		*FRONT SHOCK ABSORBER LH (WCP)	Serviceable	180.00 F	*- F
39	1		*ENGINE HEAD COVER (WCP)	Not Necessary	120.00 F	*- F
40	1		*FRONT BUMPER CLIPS (WCP)	Necessary	16.00 F	*16.00 F
41	1		*BONNET INSULATOR CLIPS (WCP)	Necessary	16.00 F	*16.00 F
42	1		*FRONT FENDER COWLING CLIPS (WCP)	Necessary	16.00 F	*16.00 F
43	1		*A/C LIQUID PIPE (WCP)	Serviceable	170.00 F	*- F
44	1		*TRANSMISSION MOUNTING LH (WCP)	Serviceable	140.00 F	*- F
45	1		*BATTERY ASSY	Melted	150.00 FS	*150.00 FS
46	1		*FRONT TYRE LH	Melted	250.00 FS	*250.00 FS
47	1		*FRONT WINDSCREEN SEALANT	Not Necessary	40.00 FS	*- FS
48	1		*A/C COOLANT	Necessary	50.00 FS	*50.00 FS
49	1		*FRONT SUPPORT PANEL (REPAIR) (NPA)	Necessary	-	*- F
50	1		*FRONT WINDSCREEN PILLAR (REPAIR) (NPA)	Necessary	-	*- F
51	1		*FRONT FENDER LH (REPAIR) FRONT FENDER RH INSTEAD OF FRONT FENDER LH (NPA)	Repair	-	*- F

F=Franchise part. S=SpcNett.

<b>Sub Total (S\$)</b>	<b>9,356.00</b>	<b>5,161.00</b>
<b>+ Margin on L,N Items 10.00/10.00% (S\$)</b>	<b>886.60</b>	<b>471.10</b>
<b>Total Parts (S\$)</b>	<b>10,242.60</b>	<b>5,632.10</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOWING	New	80.00	0.00
2	TO CHECK FRONT ELECTRICAL SYSTEM, REPLACE WIRE HARNESSSES AND FUSE BLOCK JUNCTION.	New	540.00	450.00
3	TO REMOVE AND REINSTALL A/C CONDENSER FOR NECESSARY REPAIR	New	100.00	80.00
4	TO REMOVE AND REPLACE RADIATOR ASSY	New	80.00	50.00
5	TO REMOVE AND REPLACE FRONT WINDSCREEN	New	120.00	0.00
6	TO REMOVE AND REPLACE LHF SHOCK ABSORBER	New	80.00	50.00
7	TO CHECK WHEEL ALIGNMENT	New	60.00	60.00
8	TO REPAIR FRONT AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,000.00	800.00
9	TO SPRAY PAINT ON FRONT AFFECTED AREA	New	1,000.00	800.00
<b>Gross Labour Cost (S\$)</b>			<b>3,060.00</b>	<b>2,290.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >