To Inspect Vehicle No: SH ( 5744)  at Workshop m/s Trans-cab  of 2 Amr Strue 63  Policy No: 29114756  Sum Insured:  Make of Veh: (Client's Record)  CA / REV / REP. / REV 24 HRS	Insured: SLT 3618B  Tel: 6663 1259  Claim No: 608404  Excess:
OD FP WS TP RES / OD RES / EVA / INV / MV / CS To Inspect Vehicle No: SH ( 57 444)  at Workshop m/s Tvans - Cab  of 2 Am v Swa4 63  Policy No: 29114756  Sum Insured:  Make of Veh: (Chient's Record)  CA / REV / REP. / REV 24 HRS	Insured: SLT 3618B  Tel: 6663 1259  Claim No: 668404  Excess:
To Inspect Vehicle No: SH ( 5744)  at Workshop m/s Trans-cab  of 2 Amr Strue 63  Policy No: 29114756  Sum Insured:  Make of Veh: (Client's Record)  CA / REV / REP. / REV 24 HRS	Claim No: 66 8 40 4  Excess:
at Workshop m/s Trans-cab of 2 Amr Strat 63 Policy No: 29114756 Sum Insured: Make of Veh: (Client's Record)  CA / REV / REP. / REV 24 HRS	Claim No: 66 8 40 4  Excess:
Policy No: 29  4756  Sum Insured:  Make of Veh: (Client's Record)  CA / REV / REP. / REV 24 HRS	Excess:
Sum Insured:  Make of Veh: (Client's Record)  CA / REV / REP. / REV 24 HRS	Excess:
(Client's Record)  CA / REV / REP. / REV 24 HRS	
CA / REV / REP. / REV 24 HRS	D.O.A. 12-10-1019
	H.O.D. Endorsement:  Vehicle IN JOUT
Date/Time Action/Instruction ( ) Estimate	
SLT 3618B X	
SHC 5144A:003/AIG15018432/1	Kua 3a 2 - DoA - 28 to / 2015
	The second second

ASS. REC. BY: REF: MSG/	
Kenneth	ASSIGNMENT
From: Date: Estimated Cost:	Veh No: SHC 5144 A Yr Regn: 01, 15
OD / TP / WS / TP RES / OD RES / EVA / INV / MV To Inspect Vehicle No:	Truck / Traller or
of Trans Cab	Make: Renowly lotatude c.c 199- Colour M. White / Res AC: Insured / Std / NI / NA Sp. Reading 4997 TRADE   TRADE   Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	CNO: VIETAB 215AUC 276215
Claims No.	Gen. Cond: good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: MTP I S/Rim & STD A/Rim or
(Policy Condition)  Plemark: The veh had commenced its repair at the time of inspection.	Tyre Size: F: Sailun 215/60R16
Bal. or Market Value:	TOYO/YOKO or
	Front Rear O
	R/Bal. 9 mm R/Bal. 9 mm
The state of the s	L/Bal. P mm L/Bal
Est. Repairs: 2 /2 days Res.: Yes or No Lum Sum: 20 % 3 Val.: Yes or No	D.O.A. 12/10/19  Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Date:Person Contacted: Vehicle: IN / OUT	- NISTA DON
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
/ File pass To	
61 Smg 8 3 0501 (Red \$50	381-95, 94%)
	12/ (10)
21 10 Sant Preli by Merimen	
D	ECEIVED 1 5 NOV 2019
N.	LOLIVED TO THE
Date/Time, File Pass to? : Prell. Report	
	Resurvey No. of Trip:   Survey Fee: 400
3 14/11/10	Transportation:
Add Fee:	
Report Format :	: Interview (\$ ) Fix735
	Tech Invs (\$ ). Others
Lump Sum / I.B.I: (S \$3050 = 1	Weekend (\$
	TOTAL INC.

# ...CLAIM SUBFOLDER...(New Assignment)

ase Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
15 Oct 2019		16 Oct 2019	riaj ripi	Aug Submitted	THIS MULTI EU	Status

Main	Reference	Claim Details	Documents	Show All	
CLAIM SUBFOLDER DETAIL	.s	The second second second second second	[Created by	insurer]	
Insured:	GRAB RENTALS PTE LTI	D, Co. Reg. No.: 201617200G			
Main Claimant:	TRANS-CAB SERVICES	PTE LTD, Co. Reg. No.: 20030	3878K		
Vehicle Reg. No.:	SHC5144A	Date of Loss:	[68 Months a	12/10/2019 12:00 - :59 [68 Months and 28 Days From LT Reg Date (Man Yr)]	
Claim Type:	<b>TP</b> / 608404	Policy/Cover Note No		29114756 (Comprehensive) Coverage: 01/02/2019 - 31/01/2020	
Vehicle Reg. No. (Insured):	SLT3618B	Policy No. (Claimant)	VFX/P168052	VFX/P1680520	
		Excess:			
Repairer:	Trans-Cab Services Pte	Ltd (HQ) 2 Ang Mo Kio Street 6	3, 569111 Ang Mo Kio - Tel: (	52876666	
Handling Insurer:	MSIG Insurance (Singa 6643 1391]	pore) Pte. Ltd. (HQ) - Tel: +6:	6827 7888 [Handled by N	IG CHEN HOW -	
Claimant's Insurer:	AXA Insurance Pte Ltd	(HQ) - Tel: 6338 7288			
Adjuster:	LKK Auto Consultants P	te Ltd (HQ) - Tel: 6256-3561	. [Imm.Advice due 17/1	10/2019]	
Driver/Custodian (Insured):	ANG ZHI HUA (31 / Male)	, NRIC: S8831863C, Tel: +6	591789551 Email:		
	on WP Car in Manual ace	igned to LKK via email on 15/10	19. (Manual Assign). OI: Grab		
Adj Asg. Remarks:		ants Pte Ltd. Contact: Zhewei @	6603 1259.	. Liab: unclear.	
Adj Asg. Remarks:  ASSOCIATED MAIL RECEIV	Assign: LKK Auto Consulta	ants Pte Ltd. Contact: Zhewei @		Compose Case Mail	
	Assign: LKK Auto Consulta	ants Pte Ltd. Contact: Zhewei @			
ASSOCIATED MAIL RECEIV	Assign: LKK Auto Consulta			Compose Case Mail	

# Yvonne Wong (LKK Auto)

From: Sent: Ng Wai Yin <waiyin.ng@transcab.com.sg>

Wednesday, November 13, 2019 4:02 PM

To:

Yvonne Wong (LKK Auto) jasminetan@transcab.com.sg

Cc: Subject:

FW: SHC 5144A DOA: 12/10/2019 -- AAD1910-101

Attachments:

SHC5144A ESTIMATE.pdf; DSCF7088.JPG; DSCF7087.JPG; DSCF7086.JPG

#### WITHOUT PREJUDICE

Dear Yvonne

Amount confirmed \$ 3,050 (before GST).

Thank You Best Regards, Ng Wai Yin

Finance Department TEL: 6603 1265 Ext.308

\*\*\* Please be reminded that all claims correspondence to be send to claims@transcab.com.sg

TRANS-CAB SERVICES PTE LTD No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel: 6287 6666 Fax: 6287 7764

From: Yvonne Wong (LKK Auto) [mailto:yvonnewong@lkkauto.com]

Sent: Wednesday, 13 November, 2019 9:40 AM

To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Cc: 'Jasmine Tan' <jasminetan@transcab.com.sg>

Subject: SHC 5144A DOA: 12/10/2019

Dear Wai Yin.

### WITHOUT PREJUDICE

Finalize amount \$3,050.00 @ 2.5 days

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <a href="mailto:yvonnewong@lkkauto.com">yvonnewong@lkkauto.com</a> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) Note: This document has not been finalised.

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn:

NG CHEN HOW

Date:

21 Oct 2019

# Preliminary Advice

Insured Vehicle No

: SLT3618B

TP Vehicle No

: SHC5144A

Accident Date

: 12/10/2019

Make

: RENAULT LATITUDE

Assignment Date

: 16/10/2019

Date of Inspection

: 16/10/2019

Est. Duration of Repair

: 2.50

Inspection At

: TRANS-CAB SERVICES PTE LTD (HQ)

2 ANG MO KIO STREET 63

SINGAPORE 569111

# Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	53,431.95
Revised Amount	:S\$	3,822.05
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00

:S\$ Lump Sum Repair

#### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

	The	bisla	:-	anaminal/nat	cocomical	for	ronair
1	ine	venicle	15	economical/not	economical	101	1 Chair

( X ) The above survey was conducted on a 'without prejudice' basis.

#### SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

<ol><li>By the lodgement of this report to the insurers, you hereby consaforesaid.</li></ol>	ent to the archiving of this report at the centre and to copies of the report being made available
	ACCIDENT STATEMENT
Date Of Report	14/10/2019 10:15
Date Of Accident	12/10/2019 12:30
Exact Location Of Accident	SCOTTS ROAD TOWARDS ORCHARD ROAD
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SHC5144A
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666
Vehicle Particulars	
Manufacturer	RENAULT
Model	LATITUDE-2.0 D DCI (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P1680520
Cover Note Number	
Driver	
Name of Driver	GOH SENG CHOON
NRIC No	S7045061E

Date Of Birth 08/07/1970 Occupation OUTDOOR Date Of Driving Pass 25/05/2005 **Driving Experience** 14 YEARS AND 4 MONTHS Gender MALE Mobile Number (LOCAL) +65-82008023 Fax Number

Contact Number

**EMail Address** NOEMAIL

BLK 450C BUKIT BATOK WEST AVE 6 Address

#08-621

Postcode 653450

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

OTHER - HIRER

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

Weather Conditions Road Surface

SIDE SWIPE CLEAR

DRY

Other Information

NO Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

2

: UNKNOWN

Passenger 1

GENDER:

NAME:

: MALE

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

ON 12/10/2019 AT ABOUT 1230HRS, I WAS TRAVELLING STRAIGHT ALONG THE THIRD LANE OF SCOTTS ROAD TOWARDS ORCHARD ROAD. SUDDENLY VEHICLE B(SLT3618B) SWERVED INTO MY LANE AT A FAST SPEED AND COLLIDED ONTO THE LEFT SIDE PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLT3618B

Vehicle Make/Model/Colour

**Details Of Properties** 

PRIVATE HIRE

Vehicle Category Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Page 2 of 11

Nature Of Damage No. Of Passenger (Including Driver)

### Sketch Plan Pg. 1

KETCH PLAN			
		<del></del>	<del></del>
		<del></del>	
	1	1 1 4 1 4	
		11 4 11 11 11	101
		1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2	Scotts Road towning Orchard Road
			AP SHESHAA
		1/2   A	K, ST 3618B
			<del></del>
++++		<del>-1-1-1-1-1-1-1</del>	<del>+                                      </del>
+++++		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
		( ),,,,,,	
		Pares all Cares	
	+++++++	600 y 10-802	
	1 1 1 1 1 1		
		Refer to GIA Report	
ECLARATION We declare the f	oregoing particula	rs are true in every respect.	
accidit tile i		Mum	Zhevei
olicyholder's Signa	ture	Driver's Signature	Reporting Centre Personnel's Signature
ate & Time:		(If driver is not the policyholder)	Name:
are a rivine.		Date & Time:	NRIC/FIN No.:
		Date & rime:	NRIC/FIN NO.:

GIARMC SkatchPlenForm\_V3

#### Sketch Plan #2 Pg. 1

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesald.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Driver's Signature

(If driver is not the policyholder)

Mum

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No .:

Page 5 of 11

## > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

wner ID Type:	Company
Owner ID:	878K
Vehicle Details	9.000
Vehicle No.:	SHC5144A
Vehicle to be Exported:	Yes
ntended Deregistration Date:	14 Oct 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000855
Chassis No.:	VF1ABL15AUC276215
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	14 Jan 2014
First Registration Date:	14 Jan 2014
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$12,498.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Jan 2022
PARF Rebate Amount: Intended COE Rebate Details	\$8,748.00
COE Expiry Date:	13 Jan 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$60,888.00
COE Rebate Amount:	\$17,104.00
Total Rebate Amount: Message	\$25,852.00
	not be further renewed. The vehicle must be de-registered upon COE expiry or when the whichever is earlier.

The information contained herein is correct as at 14 Oct 2019

OK

# Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5144A** 

Vehicle No.: **SHC 5144A** 

16 CCT 2019

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

RENAULT

VF1ABL15AUC276215

Not Norhaire 2419

LATITUDE

12.10.19 MSH

14/1/2014

	PART	LIST
1	BUMPER COVER FRT	\$ Bu/mbin 747.20 -
1	BUMPER SPOILER FRT	\$ Sm 344.70 X
1	BUMPER ABSORBER FRT	\$ 5 394.68 ⊀
1	BUMPER RETAINER FRT LH	\$ Dia 101.40
1	BUMPER SUPPORT FRT	\$ Sh 10.70 X
1	BUMPER UNDERTRAY FRT	\$ S∽ 292.50 X
1	BUMPER GRILLE LOWER FRT	\$ ∫ 147.00 X
1	BUMPER FOG LAMP GRILLE LH	\$ √ 207.21 X
1	BUMPER BEAM FRT	\$ N 663.70 X
1	HEADLAMP LH	\$ Cu Ingen 743.60
1	HEADLAMP PANEL FRT LH	\$ 127.70 X
1	FENDER PANEL FRT LH	\$ B 414.40 U
1	WHEELARCH FRT LH	\$ Jh 112.30
1	FENDER BRACKET LOWER LH	\$ Sex 11.80
1	FENDER INSULATOR LH	\$ Sc 65.50
1	FRONT BRACE PANEL	\$ N 177.22
1	BONNET	\$ N 1,312.70
1	BONNET INSULATOR	\$ Sh 294.30
1	BONNET STRUT LH	\$ S <sub>1</sub> 53.30 } X
1	BONNET STRUT RH	\$ 53.30
1	BONNET HINGE LH	\$ 236.50
1	BONNET HINGE RH	\$ N 237.40
1	BONNET LOCK	\$ 152.80
1	BONNET CABLE	\$ اگر <sub>55.20</sub>
1	BONNET CABLE COVER	\$ الم 80.60
1	BONNET SEAL OUTER	\$ Sh 83.20
1	BONNET SEAL INNER	\$ <i>I</i> 70.10 €

# **Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

# SHC 5144A

1	RADIATOR GRILLE		\$ Su 969.90
1	RADIATOR GRILLE BADGE 'RENAULT'		\$ In 225.36
1	RADIATOR GRILLE FRAME		\$ FL 686.00
1	FRAME FULL SUPPORT PANEL		\$ <i>\$</i> 592.70
1	FRAME FULL SUPPORT BRACKET		\$ N 41.60
1	AIR CLEANER BOX		\$ Su 464.20
1	AIR CLEANER HOSE		\$ ∫ <sub>175.85</sub>
1	AIR CLEANER LOWER		\$ Sm 271.26 > X
1	DOOR PANEL FRT LH		\$ n 2,844.66
1	DOOR WHEATHESTRIP FRONT LH		\$ Sa 316.00
1	DOOR GLASS RUNNER SEAL FRONT LH		\$ √m 332.00
1	DOOR SEAL LOWER FRONT LH		\$ <i>ي</i> ر 93.90
1	DOOR HINGE UPPER LH		\$ A 274.50
1	DOOR HINGE LOWER		\$ N 300.55
1	DOOR CHECK FRONT LH		\$ Su 90.90)
1	DOOR MIRROR ASSY LH		\$ Bn 727.90
1	DOOR MIRROR LAMP LH		\$ 134.10
1	DOOR HARNESS WIRE LH		\$ رم 2,670.00
1	ROCKER PANEL INNER GARNISH LH		\$ ر 466.51
1	ROCKER PANEL INNER LH		\$ 7 1,024.79
1	ROCKER PANEL OUTER LH		\$ H 1,184.99
1	ROCKER PANEL CENTER LH		\$ n 990.25
1	LOWER ARM LH L70Y		\$ ۶ <sub></sub> 192.70
1	KNUCKLE ARM LH L70Y		\$ Fix 481.50
1	ABSORBER FRT LH L70Y		\$ ر <sub>274.10</sub>
1	DRIVESHAFT LH		\$ N 1,355.70
1	STABILIZER BAR FRT		\$ 1 427.90 X
1	STEERING PUMP ELECTRIC		\$ 2,026.70
1	STEERING PINION RACK		\$ 3,765.30
1	AUTO COMPUTER		\$ ار 1,287.30
1	INJECTION COMPUTER		\$ گر 2,706.30
1	RHD HYDRAULIC POWER(ROCK&PINION)		\$ 3,765.30
1	SUBFRAME OUTER FRT		\$ 1,094.20
1	SUBFRAME BRACKET OUTER LH		\$ لا 49.00
1	SUBFRAME BRACKET OUTER RH		\$ St 49.00)
		TOTAL	\$ 39,543.93
		10%	 3,954.39
			\$ 35,589.53

## **Trans-cab Auto Services Pte Ltd**

AAD1910-101

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5144A

	Special Nott			
1	Special Nett BUMPER CLIP FRT	\$	M 66.00 L	
1	BUMPER BRACKET CLIP FRT LH	\$	12.00	
1	BUMPER SUPPORT CLIP FRT LH	\$	~~ 10.50	
1	BUMPER GRILLE LOWER CLIP	\$	~ 69.00	
1	WHEELARCH CLIP FRT LH	\$	~~ 30.50	
1	FRAME FULL SUPPORT PANEL CLIP	4	~~ 70.00	
1SET	FRAME FULL SUPPORT PANEL NUT	\$ \$	20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	30.00	
1SET	RADIATOR GRILLE SCREW	\$	16.00	
1SET	RADIATOR GRILLE FRAME CLIP	\$	22 52.00 X	
1	FRONT LEFT TYRE	\$	Sh 300.00	
1	FRONT LEFT TYRE RIM	\$	∫ <sub>1</sub> 380.00	
1SET	Front licence plate with holder	\$	In 80.00	
1	WINDSCREEN SEALANT	\$	~~ 253.80	
1	FRONT WINDSCREEN MOULDING	\$	120.00	
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	مم 100.00	
6	BONNET INSULATOR CLIP L70Y	\$	na 7.30	
2	BONNET CABLE CLIP L70Y	\$	٧٦ 6.31	
2	BONNET CABLE COVER SCREW L70Y	\$	10.85	
1	FRONT DOOR STICKER 'Trans-Cab'	\$	Me 80.00 60sa	
1	FRONT DOOR STICKER 'Classic'	\$	14 80.00 15sm	e.
1	DOOR CHECK BOLT	\$	~ 22.69 X	
1	DOOR HINGE BOLT	\$	10.85 <	
1	DOOR HINGE NUT LH	\$	14.60 X	
	TOTAL	\$	1,842.42	
	TOTAL PARTS	\$	37,431.95	
	LABOUR			
	Panel beating, knocking and straightening the			
	necessary portion, remove and renewal of parts, adjust			
	and realign the same	\$	6,000.00 7201	
	and realign the same	*	0,000.00 720	
	To transfer of front bumper fittings, attachment and			
	perform water seepage test.	\$	NN 380.00 X	

· ·				
ASS 25 21	cab Auto Services Pte Ltd		AAD1910-101	
	g Mo Kio Street 63 Singapore 569111			
	6287 6666 Fax No. : 6257 1330			
SHC 514	Reg. No. 201019626G			
SHC 514	To transfer of front fender fittings, attachment and			
	perform water seepage test.	\$	NA 380.00 X	
	perform water seepage test.	P	360.00 7	
	To transfer of front windscreen glass to facilitate			
	bodywork repair.	\$	NA 170.00 X	(
	bodywork repair.	*	170.00 /	`
	To check steering geometry and computer wheel			
	alignment	\$	1 220.00 X	
	angrinient	4	220.00 /	
	To remove and refit interior fittings, trimings, garnis	sh.		
	fittings and other, to enable repair.	\$	12 380.00 X	
	go and o mor, to onable repair.	7		
	To transfer of tire, rim and on wheel balancing.	\$	170.00 X	
	g.			
	Putty and spray painting of the affected portion.	\$	6,000.00	50
	To transfer of bonnet fittings, attachment and perfo	orm		
		2	380.00 X	,
	water seepage test.	\$	380.00 🗡	
	Labour charge to mount and dismount vehicle	on		
	Labour charge to mount and dismount vehicle		6 200.00 V	,
	jig bench, to facilitate repair.	\$	S 380.00 X	
	To transfer of front door fittings attackment and			
	To transfer of front door fittings, attachment and		5 200.00 #	,
	perform water seepage test.	\$	5 380.00 X	
	To dismonth and refit front and suspension			
	To dismantle and refit front end suspension,		. 200.00	,
	undercarriage parts, final checking and testing.	\$	5 380.00 X	
	T. Challet and I was a		170.00	,
	To Check Electrical Lighting Concerned.	\$	170.00 2	0
	To wast available of the official desired		17000	,
	To rust-proofing of the affected areas.	\$	170.00 3	9
ſ	To remove and renew newer steering and all and	olor		
	To remove and renew power steering pump, oil coo	oler	~~ 440.00 Z	r
	pipe and final checking and testing. the Repairer of the following:	5	710.00	1
	To resurvey before after approxy painting To display damagest past of the progressy.  To display damagest past of the progressy.	TAL \$	16,000.00	
	Parts prices are subjust to enterprise	otal #	F2 421 OF	
	Third party survey as mr a William Frejudice" basis     No lifetial most recommendationed	Julia 2	53,431.95	
	Supplements     Supplements     Supplements	***	20.0	
	to subject to draw approve horse transport LUMP, SUM (REPAIR D	AY)	2 hday	
	Acknowledged by Repairur		2 /rdas	
1	Similar		13	

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj F	tpt	Adj Submitted	Ins Auth'ed	Status	
Main	15 Oct 2019 16:31		16 Oct 2019 09:27 Edit Adj Rpt		050.00 t Estimates	S\$3,050.00 View Rpt		Pending for Surv Report Cancel Case	
0	Main	Refe	rence		Claim Detail:	s	Documents		Show All
CLAIM SU	BFOLDER DET	AILS				[Created	by insurer]		
Insured:	GRAB REN	TALS PTE LTD, C	o. Reg. No.: 2016	17200G					
Main Claimant:	TRANS-CA	B SERVICES PTE L	TD, Co. Reg. N	o.: 20030	3878K				
Vehicle Reg No.:	SHC5144	A			Date of Los		19 12:00 - :59 ns and <b>28</b> Days From	LTA Reg Date	(Man Yr)]
Claim Type:	TP / 6084	04			Policy/Cove Note No.:		(Comprehensive) 01/02/2019 - 31/01/	2020	
Vehicle Reg No. (Insured):	SLT3618B Policy No. VFX/P1680520								
					Excess:				
Repairer:	Trans-Cab	Services Pte Ltd (	HQ) 2 Ang Mo Ki	Street (	53, 569111 An	g Mo Kio - Te	1: 62876666		
Handling Insurer:	MSIG Insu	rance (Singapore	Pte. Ltd. (HQ)	-Tel: +6	5 6827 7888 .	[Handled by	NG CHEN HOW - 66	543 1391]	
Claimant's Insurer:	AXA Insura	ance Pte Ltd (HQ)	- Tel: 6338 7288						
Adjuster:	LKK Auto C	Consultants Pte Lt	d (HQ) - Tel: 625	6-3561 .	[Handled by	KENNETH K	ONG] [Final Rpt	due 15/11	1/2019]
Driver/Cust dian (Insured):		JA (31 / Male) , N	RIC: S8831863C,	Tel: +	6591789551 E	mail:			
Adj Asg. Remarks:		in, Manual assigned tact: Zhewei @ 660		on 15/10	)/19. (Manual /	Assign). OI:Gr	rab. Liab: unclear. Ass	ign: LKK Aut	o Consultan
ASSOCIAT	ED MAIL REC	EIVED					View A	All Compo	ose Case Mai
There are n	mail for this c	ase.							
ALL ASSO	CIATED TASK	(S⊟				View All	Search Tasks Crea	ite New Task	Complete
Due Date				Han	dler Assi	gned By	Jean of 103h3 Cred	ic item tosk	Complete

Page 1 of 2

### **Claim Documents**

\*SHC5144A (608404) [SLT3618B] TP TRANS-CAB SERVICES PTE LTD Oct 12 2019 12:00PM [GRAB RENTALS PTE LTD] Trans-Cab Services Pte Ltd

Up	load Documents Up	pload Photos Compose New Letter	View	View in Brows	ser v
Ass	essment Reports		1 per p	page 🗸	V
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	15/10/19 16:32	Accident Statement From:SC - Reg. No: SLT3618B, Claimant: GRAB RENTALS PTE LTD	0	Load HTM	
2	15/10/19 16:32	Addendum Sheet From:SC - Reg. No: SLT3618B, Claimant: GRAB RENTALS PTE LTD	0	Load JPG	$\mathbf{Z}$
3	15/10/19 16:32	Accident Statement Addm. #1 From:SC - Reg. No: SLT3618B, Claimant: GRAB RENTALS PTE LTD	6	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/10/19 09:58	Adjuster Immediate Advice	0	Load HTM	
Dhe	otos/Images		2 000	page 🔽	V
100000		Lucy A. A. T	3 per t		-
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	-	Thumbnail	
1	21/10/19 10:00	General View	6	Load JPG	Ø
2	21/10/19 10:00	General View	0	Load JPG	✓
3	21/10/19 10:00	General View	0	Load JPG	V
4	21/10/19 10:00	General View	0	Load JPG	☑
5	21/10/19 10:00	General View	0	Load JPG	⊻
6	21/10/19 10:00	General View	0	Load JPG	V
7	21/10/19 10:00	General View	0	Load JPG	V
8	21/10/19 10:00	General View	0	Load JPG	$\overline{\mathbf{V}}$
9	21/10/19 10:00	General View	0	Load JPG	V
10	21/10/19 10:00	General View	0	Load JPG	V
11	21/10/19 10:00	General View	0	Load JPG	V
12	21/10/19 10:00	General View	0	Load JPG	V
13	21/10/19 10:00	General View	0	Load JPG	V
14	21/10/19 10:00	General View	0	Load JPG	<b>V</b>
15	21/10/19 10:00	General View	0	Load JPG	<b>V</b>
16	21/10/19 10:00	General View	6	Load JPG	V
17	21/10/19 10:00	General View	0	Load JPG	<b>V</b>
18	21/10/19 10:00	General View	0	Load JPG	V
Doc	umentation		1 per p	page 🔽	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	-
1	15/10/19 16:36	PRI	0	Load PDF	
2	15/10/19 17:07	Manual Assign to LKK	0	Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)		Thumbnail	Print
1	16/10/19 09:25	Survey Request - Manual Assigned	0	Load PDF	

# **Linked Accident Report Documents**

			View	lew in Brows	ser 🗸
Ass	essment Reports		1 per pa	ge 🗸	V
No	Finalized On	Trans-Cab Services Pte Ltd (HQ)		Thumbnail	Print
1	14/10/19 10:42	Accident Statement	0	Load HTM	
Pho	otos/Images		3 per pa	ge 🔻	V
No	Finalized On	Trans-Cab Services Pte Ltd (HQ)	1	Thumbnail	Print
1	14/10/19 10:41	Accident Photo	0	Load JPG	V
2	14/10/19 10:41	Accident Photo	0	Load JPG	

Ass	essment Reports		1 per p	age 🔻	V
No	Finalized On	Trans-Cab Services Pte Ltd (HQ)		Thumbnail	
					V
3	14/10/19 10:41	Accident Photo	0	Load JPG	V
4	14/10/19 10:41	Accident Photo	0	Load JPG	V
5	14/10/19 10:41	Accident Photo	0	Load JPG	V
6	14/10/19 10:41	Accident Photo	0	Load JPG	V
Doc	umentation		1 per p	age 🔻	V
No	Finalized On	Trans-Cab Services Pte Ltd (HQ)		Thumbnail	Print
1	14/10/19 10:41	Sketch Plan	0	Load TIF	
2	14/10/19 10:41	Sketch Plan #2	0	Load TIF	

## **Documents Checklist**

	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			_
Show Remarks To: Handling Insurer  Note: Remarks are private unless you show it to other parties.			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19018237/KYF3E2

Date: 15/11/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29114756

Claimant

SHC5144A

Insured Vehicle No:

SLT3618B

Vehicle No: Date of Loss:

12/10/2019

Nature of Claim:

TP

Claim No: 608404

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

SHC5144A

Make & Model:

RENAULT LATITUDE, 2.0 D dCi (A) 14/01/2014 (Man. Year: 2013)

Engine No:

M9R8839C000855

Reg. Date: Colour:

Metallic White/Red

Chassis No: Odometer: VF1ABL15AUC276215 494700 km

Engine Capacity: Market Value/New Car

city: 1995 cc

Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

ES PES PES

215/60 R16

Front Tyre Size: Front Left Side: Front Right Side: 215/60 R16 Sailun 9 mm Rear Tyre Size: Rear Left Side: Rear Right Side:

Giti 8 mm Giti 8 mm

Front Right Side: Sailun 9 mm
The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	37,431.94	2,602.05	34,829.89	93.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,000.00	1,220.00	14,780.00	92.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	22.05 34,829.89 0.00 0.00 0.00 14,780.00 0.00 0.00 0.00 0.00 2.05 49,609.89 0.00 50,381.94 3.50 3,526.74	
Calculated Gross Total (S\$)	53,431.94	3,822.05	49,609.89	92.85
Approved Total (Overridden) (S\$)		3,050.00		
(S\$)	53,431.94	3,050.00	50,381.94	94.29
+ GST 7.00/7.00% (S\$)	3,740.24	213.50	3,526.74	94.29
Nett Amount (S\$)	57,172.18	3,263.50	53,908.68	94.29

INSPECTION

Date of Assignment:

16/10/2019

Date Inspected:

16/10/2019 Inspected At:

Trans-Cab Services Pte Ltd (HQ)

2 Ang Mo Kio Street 63 Singapore 569111

Estimated Period of Repair:

2.5 days

Adjuster: KENNETH KONG Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

Referen	ce	
Part Source:	: MRM-SG	Version: 1.0 (Last Synchronised: 15 Nov 2019)
Parts:	143	RENAULT LATITUDE 2.0 D dCi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted	no print-code for SHC5144A)
Validity:		tes are valid only if they contain the print code (above) on all estimate pages, running page the END OF ESTIMATES marker on the last estimate page
Further Info	: Items/values	not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BUMPER COVER FRT	Buckled / Mtg Cracked	747.20 FL	*747.20 FL
2	1	*BUMPER SPOILER FRT	Serviceable	344.70 FL	*- FL
3	1	*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*- FI
4	1	*BUMPER RETAINER FRT LH	Distorted	101.40 FL	*101.40 FI
5	1	*BUMPER SUPPORT FRT	Serviceable	10.70 FL	*- Fl
3	1	*BUMPER UNDERTRAY FRT	Serviceable	292.50 FL	*- Fl
7	1	*BUMPER GRILLE LOWER FRT	Serviceable	147.00 FL	*-Fl
В	1	*BUMPER FOG LAMP GRILLE LH	Serviceable	207.21 FL	*-Fl
9	1	*BUMPER BEAM FRT	Repair	663.70 FL	*- Fl
10	1	*HEADLAMP LH	Cut / Mtg Cracked	743.60 FL	*743.60 FL
11	1	*HEADLAMP PANEL FRT LH	Repair	127.70 FL	*-FL
12	1	*FENDER PANEL FRT LH	Bent	414.40 FL	*414.40 FL
13	1	*WHEELARCH FRT LH	Serviceable	112.30 FL	*-FL
14	1	*FENDER BRACKET LOWER LH	Serviceable	11.80 FL	*-FL
15	1	*FENDER INSULATOR LH	Serviceable	65.50 FL	*-FL
16	1	*FRONT BRACE PANEL	Repair	177.22 FL	*-FL
17	1	*BONNET	Repair	1,312.70 FL	*-FL
18	1	*BONNET INSULATOR	Serviceable	294.30 FL	*-FL
19	1	*BONNET STRUT LH	Serviceable	53.30 FL	*-FL
20	1	*BONNET STRUT RH	Serviceable	53.30 FL	*-FL
21	1	*BONNET HINGE LH	Repair	236.50 FL	*-FL
22	1	*BONNET HINGE RH	Repair	237.40 FL	*-FL
23	1	*BONNET LOCK	Repair	152.80 FL	*- FL
24	1	*BONNET CABLE	Serviceable	55.20 FL	*-FL
25	1	*BONNET CABLE COVER	Serviceable	80.60 FL	*-FL
26	1	*BONNET SEAL COVER	Serviceable	83.20 FL	*-FL
27	1	*BONNET SEAL INNER	Serviceable	70.10 FL	*-FL
28	1	*RADIATOR GRILLE	Serviceable	969.90 FL	*- FL
29	1	*RADIATOR GRILLE BADGE RENAULT	Serviceable	225.36 FL	*-FL
30	1	*RADIATOR GRILLE FRAME	Serviceable	686.00 FL	*-FL
31	1	*FRAME FULL SUPPORT PANEL	Serviceable	592.70 FL	*-FL
32	1	*FRAME FULL SUPPORT BRACKET	Repair	41.60 FL	*-FL
33	1	*AIR CLEANER BOX	Serviceable	464.20 FL	*-FL
34	1	*AIR CLEANER HOSE	Serviceable	175.85 FL	*-FL
35	1	*AIR CLEANER LOWER	Serviceable	271.26 FL	*-FL
36	1	*DOOR PANEL FRT LH	Repair	2,844.66 FL	*-FL
37	1	*DOOR WEATHERSTRIP FRONT LH	Serviceable	316.00 FL	*-FL
38	1	*DOOR GLASS RUNNER SEAL FRONT LH	Serviceable	332.00 FL	*-FL
39	1	*DOOR SEAL LOWER FRONT LH	Serviceable	93.90 FL	*-FL
10	1	*DOOR HINGE UPPER LH	Repair	274.50 FL	*- FL
11	1	*DOOR HINGE LOWER	Repair	300.55 FL	*-FL
12	1	*DOOR CHECK FRONT LH	Serviceable	90.90 FL	*-FL
13	1	*DOOR MIRROR ASSY LH	Broken	727.90 FL	

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
44	1	*DOOR MIRROR LAMP LH	Serviceable	134.10 FL	*-Fl
45	1	*DOOR HARNESS WIRE LH	Serviceable	2,670.00 FL	
16	1	*ROCKER PANEL INNER GARNISH LH	Serviceable	466.51 FL	
47	1	*ROCKER PANEL INNER LH	Repair	1,024.79 FL	
18	1	*ROCKER PANEL OUTER LH	Repair	1,184.99 FL	
49	1	*ROCKER PANEL CENTER LH	Repair	990.25 FL	
50	1	*LOWER ARM LH L70Y	Serviceable	192.70 FL	
51	1	*KNUCKLE ARM LH L70Y	Serviceable	481.50 FL	
52	1	*ABSORBER FRT LH L70Y	Serviceable	274.10 FL	
53	1	*DRIVESHAFT LH	Repair	1,355.70 FL	
54	1	*STABILIZER BAR FRT	Serviceable	427.90 FL	
55	1	*STEERING PUMP ELECTRIC	Serviceable	2,026.70 FL	
56	1	*STEERING PINION RACK	Serviceable	3,765.30 FL	*-F
57	1	*AUTO COMPUTER	Serviceable	1,287.30 FL	*-F
58	1	*INJECTION COMPUTER	Serviceable	2,706.30 FL	*-F
59	1	*RHD HYDRAULIC POWER (ROCK & PINION)	Serviceable	3,765.30 FL	
30	1	*SUBFRAME OUTER FRT	Serviceable	1,094.20 FL	*-F
61	1	*SUBFRAME BRACKET OUTER LH	Serviceable	49.00 FL	
52	1	*SUBFRAME BRACKET OUTER RH	Serviceable	49.00 FL	*-F
33	1	*BUMPER CLIP FRT	Necessary	66.00 FS	
64	1	*BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	
35	1	*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	
66	1	*BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	
67	1	*WHEELARCH CLIP FRT LH	Not Necessary	30.50 FS	
86	1	*FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	
39 70	1	*SET FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	
71	1	*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	
72	1	*SET RADIATOR GRILLE SCREW  *SET RADIATOR GRILLE FRAME CLIP	Not Necessary	16.00 FS	
73	1	*FRONT LEFT TYRE	Not Necessary Serviceable	52.00 FS	
74	1	*FRONT LEFT TYRE RIM	Serviceable	300.00 FS 380.00 FS	
75	1	*SET FRONT LICENCE PLATE WITH HOLDER	Serviceable	80.00 FS	
76	1	*WINDSCREEN SEALANT	Not Necessary	253.80 FS	
77	1	*FRONT WINDSCREEN MOULDING	Not Necessary	120.00 FS	
78	1	*FRONT WINDSCREEN INNER SPONGE SEAL		100.00 FS	
79	6	*BONNET INSULATOR CLIP L70Y	Not Necessary	7.30 FS	
30	2	*BONNET CABLE CLIP L70Y	Not Necessary	6.31 FS	
31	2	*BONNET CABLE COVER SCREW L70Y	Not Necessary	10.85 FS	
32	1	*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	
33	1	*FRONT DOOR STICKER CLASSIC	Necessary	80.00 FS	
34	1	*DOOR CHECK BOLT	Not Necessary	22.69 FS	
35	1	*DOOR HINGE BOLT	Not Necessary	10.85 FS	
36	1	*DOOR HINGE NUT LH	Not Necessary	14.60 FS	
	-15	part. S=SpcNett. L=ListItemDisc.	110. Heddoddai y	14.0010	
			Sub Total (S\$)	41,386.33	2,875.50
		- List Item Discount on L It			273.45

Total Parts (S\$) 37,431.94 2,602.05

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	6,000.00	720.00
2	TO TRANSFER OF FRONT BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
3	TO TRANSFER OF FRONT FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
4	TO TRANSFER OF FRONT WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
6	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	0.00
7	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	450.00
9	TO TRANSFER OF BONNET FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
10	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR	New	380.00	0.00
11	TO TRANSFER OF FRONT DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
12	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING	New	380.00	0.00
13	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
14	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
15	TO REMOVE AND RENEW POWER STEERING PUMP, OIL COOLER PIPE AND FINAL CHECKING AND TESTING	New	440.00	0.00
	Gross Labour	Cost (SS)	16,000.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >