~	urveyor : <u>K</u>			IENT (Office)		ate/Time; 16-10.19 9.499.9
F	الم:(Person): الم	rune ton Got-	Ing of	nslq	D	ate/Time: 16-10.14
E	Estimated Cost: _			Bill to:		
	OD TP (WS): To Inspect Vehic	rerestod res le No: JR C	1EVA/INV/MV/ 9297	CS	Insured:	GBD 9972R 65693971
- 1	at Workshop m/s	Young seng	Heng		Tel:	65 69 3972
		Lu strut	#01-12			
	Policy No: A 2	9090898 MKC		Claim No: _	59867	3
	Sum Insured:			Excess:		
		REP. / REV 24 HE 0,19 10.369.n	RS Person Contacted	de Helen		H.O.D. Endorsement:
	Date/Time	Action/Instruction (X) Estinu	ite.		
	Date/Time					
		GBD 9942R :X	1			The second secon
		GBD 9972R :X				

Milmu

ASS. PEO. BY: RASINC ASSIGNMENT JRC 9297 Yr Regn: From: Date: Veh No: Type: M.Car / M.Cycle/ Bus / Van / Lorry / Taxi / Prime Mover / Estimated Cost: OD /(TP) WS / TP RES / OD RES / EVA / INV / MV Truck / Trailer or c.c 250 JRC 9297 To Inspect Vehicle No: KLWASAKI Make: YOUG SONS HONG at Workshop m/s MAKETT GVERN A/C: Insured / Std / NI / NA Colour 5, SURN LEE ST \$01-12 T/Radio: Insured / Std / NI / NA Sp.Reading Insured: Eng/No: Policy No. C/No: Gen. Cond: Good /(Fair / Poor / Burnt Claims No. Steering: Inorder / Jammed / Leaked / Burnt or Sum Insured: Excess: Inorder / Jammed / Leaked / Burnt or (Client's Record) Make of Veh: Modi: Nil / StRim / STD A/Rim or Tyre Size: 130/70-17 (Policy Condition) Remark: The veh had commenced its N/S O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU /PIR/ SUMI / repair at the time of inspection. TOYO / YOKO or Bal. or Market Value: Front Rear Consistent?: Yes or No R/Bal R/Bal. IDAC Accident Rport: mm Consistent?: Yes or No L/Bal. L/Bal. GIA / PR Seen: mm mm D.O.I. Est. Repairs: days Res.: Yes or No D.O.A. Lum Sum: 3 Val.: Yes or No Survey held at YONG SENG HENC Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or CA / REV / REP. / 24 HRS FRT & NIS Vehicle: IN / OUT Person Contacted: Date: The U/C / Chassis frame / Body Structure affected due to collision. Date / Time Action / Instruction NO 61A

Date/Time, File Pass to? : Prell. Report Days Of Repair: : Final Report Resurvey No. of Trip: Survey Fee: Date/Time, File Return to? Transportation: Add Fee: : Site Insp (\$ S+RS. SI Interview (\$ Photos Papari Formes: PRS. Tech. Invs (\$ Others Long Fom / LEJ: 12 Weet end 18 TOTAL:

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adi Rpt	Adj Subr	nitted	Ins Auth'ed	Sta	itus	
Main	04 Jul 2019		16 Oct 2019 09:49 Assign					Ne	w Assignmo Cancel Case	ent _
	Main	Re	ference	Clai	m Details		Docu	ments	\Box	Show All
CLAIM S	UBFOLDER DE	TAILS					1	Created	d by insure	r]
Insured: Main Clair	mant:		R ENGINEERING		. Reg. No.: 2	0041219	2N			
Vehicle Re	12.5	JRC9	Sec		te of Loss:		01/07/2019 12:00 [6 Months From LT (Man Yr)]		s From LTA	7.7
Claim Typ	e:	TP / 5	598673	Po	Policy/Cover Note No.:		C	A29090898MKC (Comprehe Coverage: 11/08/2018 - 10/08/2019		
Vehicle Re	g. No. (Insured)	GBD99	72R	Po	icy No. (Clain	nant):		.,,		
					ess:		CONTRACTOR SECTION AND ADDRESS OF THE PARTY	S\$600.00		
Repairer:		Yong S Pionee	Seng Heng Motor - Tel:	Services (PI	ONEER) 5 SC	OON LEE	STREET, #01-	12 PION	IEER POINT,	627607
Handling	Insurer:	MSIG 6594 2	Insurance (Sing: 541]	apore) Pte. Lt	d. (HQ) - Tel	: +65 68	327 7888 [H	landled	by Irene Ta	n Gek Ing
Adjuster:			uto Consultants	Pte Ltd (HQ)	Tel: 6256-3	561 [1	mm.Advic	e due	17/10/201	91
Driver/Cu	stodian (Insured)): 001 KG	OOI CHAI () , NR	IC: S26109570	, Tel: +65	8308182	9 Email:			
Adj Asg. F	Remarks:	on WP. Contac	Liab: unclear. Ag t: Ms Helen @ 656	ree on SJE. Ass 59 3976.	ign: LKK Auto	Consult	ants Pte Ltd /	FormTe	am Consulta	ncy Pte Ltd.
ASSOCI	ATED MAIL REC	EIVED					Viev	All	Compose	Case Mail
There are	no mail for this	case.						managed a		
В										
ALL ASS	OCIATED TASE	cs			View All	Search	n Tasks	Create #	New Task	Complete
Due Da		Type Task (Group Subjec	t Handler	Assigned	Ву	Completed	On	Created O	n Done





1 013

Police Station Of Origin:

Nanyang N.P.C 2 Jurong West Avenue 5 SINGAPORE

649482

Tel No: 1800-7929999

REPORT OF A TRAFFIC ACCIDENT

		OI O
Report No.	T/20190701	/2085

	ne Report M 019 14:19	lade:	Vide Report No.: J/20190701/0076	Station Diary No.: 469
Informa	nt's Partic	ulars		
	f Informant: OI CHAI		Address: APT BLK 437 JURONG WI SINGAPORE 640437	EST AVENUE 1 #06-424
	/ ID No.: O / S26109	57D	Contact No.: Home/Office:	Mobile: 83081829
National MALAY:			Email:	14
Sex: Male	Age: 64	Date of Birth: 17/04/1955	Type of Informant: Driver	
Race: Chinese			Language: Chinese	Institution / School Name:
Occupa DRIVER			Driving Licence Information Class: 2B,2A,3,4	n: Date of Expiry:

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 01/07/2019 12:1:	Type of Location: Straight Road	
Location: Along Road 1 JOO KOON 0 Weather:		Road Surface:		Road Speed Limit:	
Clear		Dry			
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Light	
	sion:			Anyone conveyed by	

Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
GBD9972R	The same of the sa	TOYOTA	TOYOTA DYNA 150 MANUAL	Blue	Slightly Damaged	0
JRC9297	Motorcycle		00 0 produced 0.050/50/50/50/		- 5750 Apr. 22	0

Details of Person Involved	
Any Pedestrian Involved: No	The state of the s
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



T/20190701/2085

2 of 3 Report No. T/20190701/2085

Police Station Of Origin: Nanyang N.P.C 2 Jurong West Avenue 5 SINGAPORE

649482

Tel No: 1800-7929999

CONTINUATION OF REPORT

Driver Name	OOI KOOI CHAI	others described by		ID No		S2610957D
Related Vehicle	GBD9972R (Lorry)			Conta	ct No.	83081829
Hospital/Clinic	NIL			Class Drivin Licent Expire	g	Class: 2B,2A,3,4 Date of Expiry: NIL
Date Treatment	NIL		Date Disc		NIL	
No. of Days gran	ted Medical Leave	NIL	Degree o	f Injury	NIL	

Brief Details.

On 01/07/2019 at about 1215hrs, I was travelling along Joo Koon Circle in my vehicle GBD9972R. As I was approaching my destination, I made a right signal and waited for a while before making the turn. I then proceeded to make the right turn with the intention of entering into the compound of 'Mazak' located at 21 Joo Koon Circle. While I was making the turn, I suddenly felt an impact on my right side. I realized a motorbike has collided onto the right side of my vehicle. I alighted to make a check and saw the motorcyclist on the floor. His motorbike bearing registration plate JRC9297 was also on the floor. Someone then called for police and the motorcyclist was also conveyed to hospital. I did not managed to exchange particulars with the motorcyclist except taking down his bike registration plate number.

My vehicle sustained slight damage which includes dents on the right side as well as on the oil box.

I have handed my in-vehicle camera SD card to Traffic Police officer who was at scene. I was then issued with a case card ref J/20190701/0076 and was advised by the Traffic Police to lodge a police report.

I wish to state that there is also a camera outside Mazak which is directed at the accident location. My company will be able to retrieve the footage to assist in the investigation.





3 of 3

Report No. T/20190701/2085

Police Station Of Origin: Nanyang N.P.C 2 Jurong West Avenue 5 SINGAPORE 649482 Tel No: 1800-7929999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report J / Staff Sgt NALINEE CHUA	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 01/07/2019 14:19
Officer In Charge Of Case: TP / GIT / Insp TAN CHIN YONG Contact No.: 65476178	Classification Of Case:
Anthentication Stamp	
Singapore Police Force	

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case 1	lotified	Est Submitted	Adj Assigned	Adj Rpt		Adj Subr	mitted	Ins Auth'ed	Status		
Main	14 Jul 2019		16 Oct 2019 09:49 Edit Adj Rpt	S\$0.00 Edit Estimat	es	S\$0.00 View Rp			Report	Pending for Survey Report Cancel Case	
М	ain	Re	ference		laim	Details		Documer	nts] [Show All
CLAIM SUB	FOLDER DE	ETAILS	Out to				[Created	by insurer]			
Insured:	LEADER E	ENGINEERING PT	ELTD, Co. Re	g. No.: 20041	2192	N	777				
Main Claimant:	BEI SHUI	KUAN, ID: F79	09287N								
Vehicle Reg. No.:	JRC929	JRC9297			Date	e of Loss:	and contract	19 12:00 - :59			
Claim Type:	TP / 598673					cy/Cover e No.:		8MKC (Compret 11/08/2018 - 1			
Vehicle Reg. No. (Insured):	GBD9972	tR.				cy No. imant):					
Academies Ave.					Exce	and the second second second second second	S\$600.00	Contract the second section is the second section in the second section section in the second section is the second section in the second section in the second section is the second section in the second section in the second section is the second section in the second section in the second section is the second section in the second section in the second section is the second section in the second section in the second section is the second section in the second section in the second section is the second section in the second section in the second section is the second section in the second section in the second section is the second section in the second section in the second section is the second section in the second section in the second section is the second section in the second section in the second section is the second section in the second section in the second section is the second section in the second section in the second section is the second section in the second section in the second section is the second section in the second section in the second section is the second section in the second section in the second section is the second section in the second section in the second section is the second section in the second section in the section is the section in the			
Repairer:	Yong Sen	ng Heng Motor Se	rvices (PIONE	ER) 5 SOON I	LEE S	TREET, #0	1-12 PION	EER POINT, 6276	07 Pioneer	- Tel:	
Handling Insurer:		surance (Singapo									
Adjuster:		Consultants Pte	Ltd (HQ) - Tel:	6256-3561 .	[Ha	ndled by N	MOHD RAS	UL] [Imm.	Advice d	ue 17/10	0/2019]
Driver/Custo dian (Insured):	00I K00I	CHAI () , NRIC:									
Adj Asg. Remarks:	on WP. Lia 6569 3970	ab: unclear. Agree 6.	on SJE. Assign: I	LKK Auto Con	sultan	its Pte Ltd	/ FormTea	m Consultancy P	te Ltd. Con	tact: Ms I	telen @
ASSOCIAT	ED MAIL RE	CEIVED							View All	Compose	e Case Mai
There are no	mail for this	case.									
ALL ASSO	CIATED TAS	sks ⁼					View All	Search Tasks	Create M	lew Task	Complet
Due Date	Priority	Type Task	Group Sub	ject Hand	ller	Assign	ned By	Completed O	n Cre	eated On	Done
No results.											

Claim Documents

*JRC9297 (598673) [GBD9972R] TP **BEI SHUI KUAN** Jul 1 2019 12:00PM [LEADER ENGINEERING PTE LTD] Yong Seng Heng Motor Services

Upk	oad Documents Up	load Photos Compose New Letter	View	View in Brow	vser ▼
Asse	essment Reports		1 per	page ▼	•
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	01/10/19 16:22	Accident Statement From: OD - Reg. No: GBD9972R, Claimant: LEADER ENGINEERING PTE LTD	0	Load HTM	
Pho	tos/Images		3 per	page ▼	•
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/10/19 16:04	General View	0	Load JPG	•
2	21/10/19 16:04	General View	0	Load JPG	•
3	21/10/19 16:04	General View	0	Load JPG	•
4	21/10/19 16:04	General View	0	Load JPG	•
5	21/10/19 16:04	General View	0	Load JPG	•
6	21/10/19 16:04	General View	0	Load JPG	•
7	21/10/19 16:04	General View	0	Load JPG	•
8	21/10/19 16:04	General View	0	Load JPG	•
9	21/10/19 16:04	General View	0	Load JPG	•
10	21/10/19 16:04	General View	0	Load JPG	•
11	21/10/19 16:04	General View	0	Load JPG	•
12	21/10/19 16:04	General View	0	Load JPG	•
13	21/10/19 16:04	General View	0	Load JPG	•
14	21/10/19 16:04	General View	0	Load JPG	•
15	21/10/19 16:04	General View	0	Load JPG	•
16	21/10/19 16:04	General View	0	Load JPG	•
17	21/10/19 16:04	General View	0	Load JPG	•
18	21/10/19 16:04	General View	0	Load JPG	•
19	21/10/19 16:04	General View	0	Load JPG	•
20	21/10/19 16:04	General View	0	Load JPG	•
21	21/10/19 16:04	General View	0	Load JPG	•
22	21/10/19 16:04	General View	0	Load JPG	•
23	21/10/19 16:04	General View	0	Load JPG	•
24	21/10/19 16:04	General View	0	Load JPG	•
25	21/10/19 16:04	General View	0	Load JPG	•
26	21/10/19 16:04	General View	0	Load JPG	•
27	21/10/19 16:04	General View	0	Load JPG	•
28	21/10/19 16:04	General View	0	Load JPG	•
29	21/10/19 16:04	General View	0	Load JPG	•
30	21/10/19 16:04	General View	0	Load JPG	•
31	21/10/19 16:04	General View	0	Load JPG	•
32	21/10/19 16:04	General View	0	Load JPG	•
33	21/10/19 16:04	General View	0	Load JPG	•
34	21/10/19 16:04	General View	0	Load JPG	•
35	21/10/19 16:04	General View	0	Load JPG	•
36	21/10/19 16:04	General View	0	Load JPG	•

Ass	essment Reports		1 per	page 🔻	(4)
No.	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
37	21/10/19 16:04	General View	0	Load JPG	•
38	21/10/19 16:04	General View	0	Load JPG	•
39	21/10/19 16:04	General View	0	Load JPG	•
40	21/10/19 16:04	General View	0	Load JPG	•
41	21/10/19 16:04	General View	0	Load JPG	•
42	21/10/19 16:04	General View	0	Load JPG	•
43	21/10/19 16:04	General View	0	Load JPG	•
44	21/10/19 16:04	General View	0	Load JPG	•
45	21/10/19 16:04	General View	0	Load JPG	•
46	21/10/19 16:04	General View	0	Load JPG	€
47	21/10/19 16:04	General View	0	Load JPG	€
48	21/10/19 16:04	General View	0	Load JPG	€
49	21/10/19 16:04	General View	0	Load JPG	•
50	21/10/19 16:04	General View	0	Load JPG	•
51	21/10/19 16:04	General View	0	Load JPG	•
52	21/10/19 16:04	General View	0	Load JPG	•
53	21/10/19 16:04	General View	0	Load JPG	•
54	21/10/19 16:04	General View	0	Load JPG	•
55	21/10/19 16:04	General View	0	Load JPG	€
56	21/10/19 16:04	General View	0	Load JPG	•
57	21/10/19 16:04	General View	0	Load JPG	M
58	21/10/19 16:04	General View	0	Load JPG	•
59	21/10/19 16:04	General View	0	Load JPG	•
60	21/10/19 16:04	General View	0	Load JPG	•
61	21/10/19 16:04	General View	0	Load JPG	•
Do	cumentation		1 per	page 🔻	•
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	01/10/19 16:22	POLICE REPORT From:OD - Reg. No: GBD9972R, Claimant: LEADER ENGINEERING PTE LTD	0	Load TIF	
2	15/10/19 17:28	Workshop Details	0	Load PDF	
3	15/10/19 17:28	Agree on SJE	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/MSG19018241/R1CF3S2

Date:

06/11/2019

REFERENCE

MSIG Insurance (Singapore) Pte. Ltd. Handling Insurer:

Policy No:

A29090898MKC

Claimant Vehicle

JRC9297

Insured Vehicle No:

GBD9972R

No: Date of Loss:

01/07/2019

Nature of Claim:

TP

Claim No: 598673

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

JRC9297

Make & Model:

KAWASAKI NINJA, 250cc (Man. Year: 1900)

Engine No: Chassis No: Odometer:

NA NA 0 km

Reg. Date: Colour:

Green

Engine Capacity:

250 cc

Market Value/New Car Price: N/A Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Fair

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

110/70-17

Rear Tyre Size:

130/70-17

Front Left Side:

Pirelli 3 mm

Rear Left Side: Rear Right Side: OHTSU 3 mm

0 mm

Front Right Side: 0 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

16/10/2019

Date Inspected:

16/10/2019 Inspected At:

Yong Seng Heng Motor Services (PIONEER)

5 SOON LEE STREET, #01-12 PIONEER POINT

Singapore 627607

Estimated Period of Repair:

6.0 days

MOHD RASUL Adjuster:

Manager:

CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REGISTRATION DATE UNABLE TO TRADE: DUE TO FOREIGNER VEHICLE.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 - \$7,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 06 Nov 2019)

Parts:

Labour: Repairer's KAWASAKI NINJA 250cc (Model not available in database)

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for JRC9297)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >