

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19018253/UDA3Q2

**Date:** 10/09/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**  
**Vehicle No :** SKG2658Y **Insured Vehicle No :** SCP9083G

**Date of Loss:** 14/10/2019 **Nature of Claim:** TP **Claim No:** 7442174857SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKG2658Y</b>		
Make & Model:	LEXUS IS250, 2.5 (A)	Engine No:	4GR0627254
Reg. Date:	03/02/2010 (Man. Year: 2010)	Chassis No:	JTHBK262905116810
Colour:	Black	Odometer:	306812 km
Engine Capacity:	2500 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	235/45Z R17	Rear Tyre Size:	235/45Z R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,111.00</b>		
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>3,111.00</b>	<b>-3,111.00</b>	
<b>+ Loss of Use (7.0 x S\$110.00/day) (\$\$)</b>		770.00		
<b>+ Doc/Search Fee (\$\$)</b>		7.45		
<b>Nett Liability (\$\$)</b>		<b>3,888.45</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>3,880.00</b>		

### INSPECTION

Date of Assignment: 15/10/2019

Date Inspected: 16/10/2019 Inspected At:

Zoom Autowerks Pte Ltd  
15 Kaki Bukit Road 4, #01-53  
Singapore 417808

Estimated Period of Repair: 0.0 days

**Adjuster:** MARCUS CHUA

**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

PLEASE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIR.

MARKET VALUE : \$23,000.00

LTA REIMBURSEMENT VALUE (RV) : \$19,889.00

NETT VALUE : \$3,111.00

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

## REPAIR DETAILS

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**