

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/III19018256/K1GS3Q2

**Date:** 24/09/2020

#### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant Vehicle No :</b> SHB8073G	<b>Insured Vehicle No :</b>	SHC8565Z
Date of Loss: 14/10/2019	Nature of Claim:	TP Claim No: MCT19100293

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB8073G	Engine No:	D4DFDH314488
Make & Model:	KIA OPTIMA, 1.7 D (A)	Chassis No:	KNAGM414MF5658334
Reg. Date:	03/02/2016 (Man. Year: 2015)	Odometer:	391271 km
Colour:	Silver		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

#### CONDITION OF TYRES

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	Hankook 7 mm	Rear Left Side:	Hankook 7 mm
Front Right Side:	Hankook 7 mm	Rear Right Side:	Hankook 7 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,300.80	545.90	754.90	58.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,170.00	660.00	510.00	43.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,470.80</b>	<b>1,205.90</b>	<b>1,264.90</b>	<b>51.19</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>950.00</b>		
<b>(S\$)</b>	2,470.80	950.00	1,520.80	61.55
<b>+ GST 7.00/7.00% (S\$)</b>	172.96	66.50	106.46	61.55
<b>Nett Amount (S\$)</b>	<b>2,643.76</b>	<b>1,016.50</b>	<b>1,627.26</b>	<b>61.55</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

#### INSPECTION

Date of Assignment:	15/10/2019	
Date Inspected:	15/10/2019 Inspected At:	Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02 Singapore 486443
Estimated Period of Repair:	3.0 days	

**Adjuster:** KALVIN ANG WEI KUN

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 21 Sep 2020)
<b>Parts:</b> 143	KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SHB8073G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT O/S WHEEL COVER	Repair	116.00 FL	*- FL	
2	1		*FRONT BUMPER	Cut	531.00 FL	*531.00 FL	
3	1		*FRONT BUMPER EMBLEM	Not Necessary	44.00 FL	*- FL	
4	1		*FRONT BUMPER O/S SIDE RETAINER	Serviceable	16.00 FL	*- FL	
5	1		*FRONT BUMPER O/S PROTECTOR	Serviceable	51.00 FL	*- FL	
6	1		*FRONT BUMPER O/S FOG LAMP COVER	Serviceable	66.00 FL	*- FL	
7	2		*FRONT BUMPER O/S & N/S UPPER BRACKET	Serviceable	32.00 FL	*- FL	
8	2		*FRONT BUMPER O/S & N/S SUPPORT BRACKET	Serviceable	32.00 FL	*- FL	
9	1		*FRONT O/S FENDER	Repair	384.00 FL	*- FL	
10	1		*FRONT BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS	
11	1		*FRONT O/S FENDER STICKER	Not Necessary	30.00 FS	*- FS	
12	1		*SET FRONT O/S FENDER INNER SHIELD CLIPS	Not Necessary	28.00 FS	*- FS	
13	1		*SUNDRY	Necessary	50.00 FS	*20.00 FS	
					<b>Sub Total (\$\$)</b>	<b>1,428.00</b>	<b>599.00</b>
					<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	127.20	53.10
					<b>Total Parts (\$\$)</b>	<b>1,300.80</b>	<b>545.90</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .INCLUDING KNOCK -OUT ,STRAIGHTEN REPAIR RESHAPE AND ADJUST OF THE SAME	New	650.00	300.00
2	TO PUTTY AND SPRAY PAINTING OF FRONT BUMPER ,FRONT O/S FENDER	New	400.00	360.00
3	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	120.00	0.00
			<b>Gross Labour Cost (\$)</b>	<b>660.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >